

NARRATIVE REPORT

1.0 BUILDING INFORMATION

Minard Hall was originally constructed in 1901; a 1917 addition extended the building to the north, a 1930 addition extended the building further north, and 2003 addition extended the building to the west. The building has had several renovations, notably, a 1968-1973 multi-phase renovation throughout the building.

Minard Hall is a four-story, 104,287 ft² building which primarily serves as classroom and office areas for university personnel. Music Education (A016) is attached to the west side of Minard Hall and is reported separately.

The interior floor finishes included carpet, floor tile, concrete, linoleum, vinyl flooring, wood, and epoxy flooring; the interior wall finishes included gypsum wallboard, plaster, wood, concrete, clay brick, brick, epoxy, ceramic tile, and concrete block ; and the interior ceiling finishes included ceiling tile, wood, concrete, plaster, gypsum wallboard, epoxy, and metal. The roofing system is a peaked asphalt shingled roof on the 1901, 1917, and 1930 buildings; and a combination flat rubber-membrane roof and peaked asphalt shingled roof on the 2003 building; the exterior of the building is brick.

The piping systems were insulated; fiberglass insulation (with and without hard fittings), aircell insulation (with hard fittings), and millboard insulation (with hard fittings) are located throughout the building. Steam enters the building in room 114A and domestic water enters the buildings through the basement mechanical area accessible through room 113. HVAC systems located in the building consisted of steam radiators and forced air furnaces equipped with heating/cooling coils.

2.0 ASBESTOS SURVEY INFORMATION

Minard Hall was surveyed as part of a larger project on NDSU's Fargo, ND Campus. This report is part of "Volume 3" of a nine volume series. This report includes building specific information only; please refer to the opening section of "Volume 3" for methodologies, definitions, and other pertinent supporting information.

A total of 337 samples were collected from suspect asbestos-containing materials (ACM) from Minard Hall on July 17, 2007 and an additional 9 samples were collected on June 16, 2008. Laboratory analysis results indicate **77 of these samples tested positive for asbestos.**

2.1 Suspect Materials Identified and Sampled

Gypsum Wallboard (20 types)	Joint Compound (21 types)
Ceiling Tile (13 types)	Carpet Mastic (9 types)
Baseboard Adhesive	Building Seam Caulk (2 types)
Sink Undercoating (3 types)	Red Firestop
Encapsulant on Fiberglass Insulation (3 types)	Black AHU Putty
Roof Flashing (4 types)	Asphalt Shingle (4 types)
Roof Tarpaper (4 types)	Wall Texture (7 types)
Acoustic Ceiling Plaster	Hard Plaster- Monocoat (3 types)
Hard Plaster- Basecoat (3 types)	Hard Plaster- Skimcoat (3 types)
Ceiling Texture (2 types)	Floor Tile (11 types)

Floor Tile Mastic (11 types)	Sheet Vinyl Flooring (2 types)
Sheet Vinyl Flooring Adhesive (2 types)	Carpet Mastic (with residual flooring)
Linoleum (2 types)	Stair Tread
Stair Tread Adhesive (3 types)	Floor Filler Material (3 types)
Baseboard Adhesive (6 types)	Window Caulk
Wood Panel Adhesive (2 types)	HVAC Duct Caulk
Coating Material (on bricks)	Wire Insulation
Felt Material (above tin ceiling)	Exterior Window Glazing
Exterior Transite Panels	Aircell Pipe Insulation
Hard Fittings on Aircell Insulation	Millboard Pipe Insulation
Hard Fittings on Millboard Insulation	Hard Fitting on Fiberglass Insulation
Encapsulant on Millboard Insulation	Exterior Door Caulk (2 types)
Exterior Window Caulk (2 types)	Exterior Building Seam Caulk
Window Glazing	Window Glazing on Door
Window/Door System Glazing	

The Asbestos Bulk Sample Results Table includes asbestos sampling data.

2.2 **Asbestos Containing Materials**

Acoustic Ceiling Plaster
 Joint Compound (3 types)
 Carpet Mastic (with residual flooring)
 Mastic for 12" Tan/White/Brown Mottled Floor Tile
 12" Light Green Floor Tile with Brown Marks and Mastic
 12" Brown Floor Tile with Splatter Marks and Mastic
 White Pebble Pattern Linoleum
 12" Brown Floor Tile with Brown Marks and Mastic
 Wood Panel Adhesive
 Exterior Window Glazing
 Exterior Transite Panels
 Purple Sink Undercoating
 Brown Sink Undercoating
 Aircell Pipe Insulation
 Hard Fittings on Aircell Insulation
 Millboard Pipe Insulation
 Hard Fittings on Millboard Insulation
 Hard Fittings on Fiberglass Insulation
 Roof Flashing (3 types)
 Mastic for 12" Off-White Floor Tile with Tan
 Window Glazing
 Window Glazing on Door
 Window/Door System Glazing
 9" Floor Tile and Mastic (assumed)

The ACM Locations/ Friable Materials Assessments Table includes ACM locations data.

2.3 **Cost Estimates**

Legend Technical Services Inc. estimates abatement costs (removal & disposal) of ACM for Minard Hall as follows:

ACM	QUANTITY	UNIT COST	TOTAL COST
Asbestos Wood Panel Adhesive	54,229 ft ²	\$5.00/ft ²	\$271,145.00
Asbestos Transite Panel	125 ea	\$50.00/ea	\$6,250.00
Asbestos Sink Undercoatings (all types)	4 ea	\$150.00/ea	\$600.00
Asbestos Aircell Pipe Insulation	391 ft	\$25.00/ft	\$9,775.00
Asbestos Hard Fitting on Aircell Insulation	13 ea	\$60.00/ea	\$880.00
Asbestos Millboard Pipe Insulation	138 ft	\$25.00/ft	\$3,450.00
Asbestos Hard Fitting on Millboard Insulation	4 ea	\$60.00/ea	\$240.00
Asbestos Hard Fitting on Fiberglass Insulation	9 ea	\$60.00/ea	\$5,400.00
Asbestos Window Glazing (all types)	11 ea	\$225.00/ea	\$2,475.00
Asbestos Acoustic Ceiling Plaster	3,242 ft ²	\$7.50/ft ²	\$24,315.00
Asbestos Carpet Mastic (with residual mastic)	71 ft ²	\$4.00/ft ²	\$284.00
Asbestos Joint Compound	44,085ft ²	\$5.00/ft ²	\$220,425.00
Asbestos Linoleum	168 ft ²	\$4.00/ft ²	\$672.00
Asbestos Floor Tile and/or Mastic	33,912 ft ²	\$4.00/ft ²	\$135,648.00
Asbestos Flashing (on penetrations)	16 ea	\$60.00/ea	\$960.00
Asbestos Flashing (on seams)	150 ft	\$5.00/ft	\$750.00
Total Estimated Abatement Costs:			\$683,169.00

2.4 Survey Notes

LEGEND identified and sampled multiple types (homogeneous areas) of Wood Panel Adhesive in Minard Hall from: the 1968-1973 multi-phase renovation and an unknown renovation on the 4th floor of the 1930 building. The wood panel adhesive from the 1968-1973 multi-phase renovation tested positive for asbestos; it is a black material seen in the 1972 and 1973 renovation years. LEGEND quantified this material using available architectural drawings in combination with a walk-through inspection of the building, identifying all areas where the ACM wood panel adhesive (black) is visible above the ceiling tile at the top of the wood paneling. LEGEND was unable to identify the extent of the ACM wood panel adhesive in 3 areas:

1. In the room 102 area (last major renovations in 1968), new wood panel walls have been added to form rooms 102G and 102H and walls in room 102D and 102E have had wood paneling added over them in an unknown year. LEGEND was unable to identify any wood panel adhesive in this area and did not identify these walls on the ACM tables or diagrams.
2. In the room 310 area, an unknown renovation has added wood panel walls. The wood panel walls appears homogeneous to the wood panel walls with the ACM adhesive throughout the building, however their construction is different, the walls do not extend above the older vintage ceiling tile in this area. LEGEND was unable to identify any wood panel adhesive in this area and did not identify these walls on the ACM tables or diagrams.
3. In the fourth floor of the 1930 building, an unknown renovation has changed the room layout, mixing a new vintage of wood panel walls in with the older vintage of wood panel walls (with ACM adhesive). LEGEND was unable to fully

distinguish the wood paneling with ACM adhesive from the wood paneling with non-ACM adhesive and identified all walls with wood paneling in this area on the ACM tables and diagrams.

In these areas, LEGEND recommends assuming all wood panel walls to have ACM wood panel adhesive being them until a destructive survey can be conducted for a final visual verification behind the wood paneling.

LEGEND identified 1 hard fitting and 1 foot of unknown pipe insulation in a mechanical closet accessible through room 412J. The material is to the north of the door from room 412J and is inaccessible; LEGEND was unable to identify which type of pipe insulation the material is. All hard fittings sampled in Minard Hall tested positive for asbestos and both the Aircell Pipe Insulation and Millboard Pipe Insulation sampled in Minard hall tested positive for asbestos. LEGEND considers the hard fitting and the pipe insulation to be ACM; the material is identified on the ACM tables and diagrams.

LEGEND inspected the crawlspace below Minard Hall as accessible; several areas were observed without access, either due to water accumulation or no sufficient passageways to cross through. In one inaccessible area below the 1901 building LEGEND observed a possible abandoned main steam pipe that appeared to be insulated with aircell pipe insulation. Quantities of the material are unknown.

LEGEND identified and sampled 4 types (homogeneous areas) of roof flashing on Minard Hall from: the 1901 building; the 1917 building; the 1930 building; and the 2003 building. The roof flashing from the 1901 building, the 1917 building, and the 1930 building tested positive for asbestos. The ACM roof flashing was identified around roof penetrations and on the seams in the roof between the different buildings.

LEGEND identified and sampled 21 types (homogeneous areas) of joint compound in Minard Hall from numerous renovations. Joint compound from the 1968, 1972, and 1973 years of the 1968-1973 multi-phase renovations tested positive for asbestos. These materials are found throughout Minard Hall; refer to the ACM tables and diagrams for further information.

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 100 Abated Fall 2011

9" Floor Tile and Mastic	Assumed	140 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	93 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north and west walls.

Room 101 Abated Fall 2011

9" Floor Tile and Mastic	Assumed	212 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	612 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east, and west walls.

Room 101A Abated Fall 2011

9" Floor Tile and Mastic	Assumed	120 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	396 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east, and west walls.

Room 101B Abated Fall 2011

9" Floor Tile and Mastic	Assumed	122 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	396 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east, and west walls.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
Room 101C Abated Fall 2011								
9" Floor Tile and Mastic	Assumed	175 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	486 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east, and west walls.
Room 101D Abated Fall 2011								
Joint Compound	2-3% Chrysotile	279 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north and west walls.
Room 102 Abated Fall 2011								
9" Floor Tile and Mastic	Assumed	155 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	378 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the south wall, south half of the east wall, and the west wall.
Room 102A Abated Fall 2011								
Joint Compound	2-3% Chrysotile	234 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, east, and south walls.
Room 102B Abated Fall 2011								
Joint Compound	2-3% Chrysotile	585 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east, and west walls.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
Aircell Pipe Insulation	60-80% Chrysotile	18 ft	Friable TSI	Significantly Damaged	Physical Air Erosion Vibration	■□□ ■□□ ■□□	1	The asbestos aircell pipe insulation is above the ceiling tile along the center of the room.
Hard Fittings on Aircell Insulation	40% Chrysotile	2 fittings	Friable TSI	Significantly Damaged	Physical Air Erosion Vibration	■□□ ■□□ ■□□	1	None

Room 102C Abated Fall 2011

9" Floor Tile and Mastic	Assumed	136 ft ²	Non-friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	414 ft ²	Non-friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The asbestos joint compound is on the north, south, east, and west walls.

Room 102D Abated Fall 2011

9" Floor Tile and Mastic	Assumed	133 ft ²	Non-friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	414 ft ²	Non-friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The asbestos joint compound is on the north, south, east, and west walls (joint compound is under new wood paneling in areas).
Aircell Pipe Insulation	60-80% Chrysotile	14 ft	Friable TSI	Damaged	Physical Air Erosion Vibration	■□□ ■□□ ■□□	1	The asbestos aircell pipe insulation is above the ceiling tile along the south wall.
Hard Fitting on Aircell Insulation	40% Chrysotile	3 fittings	Friable TSI	Significantly Damaged	Physical Air Erosion Vibration	■□□ ■□□ ■□□	1	None

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 102E Abated Fall 2011

9" Floor Tile and Mastic	Assumed	171 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	576 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east, and west walls (joint compound is under new wood paneling in areas).
Aircell Pipe Insulation	60-80% Chrysotile	30 ft	Friable TSI	Damaged	Physical Air Erosion Vibration	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	1	The asbestos aircell pipe insulation is above the ceiling tile along the south and west walls.
Hard Fitting on Aircell Insulation	40% Chrysotile	1 fitting	Friable TSI	Damaged	Physical Air Erosion Vibration	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	1	None
Millboard Pipe Insulation	50% Chrysotile	30 ft	Friable TSI	Damaged	Physical Air Erosion Vibration	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	1	The asbestos millboard pipe insulation is above the ceiling tile along the south and west walls.
Hard Fitting on Millboard Insulation	40% Chrysotile	1 fitting	Friable TSI	Damaged	Physical Air Erosion Vibration	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	1	None

Room 102F Abated Fall 2011

9" Floor Tile and Mastic	Assumed	45 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs.
Joint Compound	2-3% Chrysotile	234 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east, and west walls.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	-----------------------------	-------

Room 102G Abated Fall 2011

Joint Compound	2-3% Chrysotile	108 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north and west walls (joint compound is under new wood paneling in areas).
Millboard Pipe Insulation	50% Chrysotile	9 ft	Friable TSI	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	7	The asbestos millboard pipe insulation is above the ceiling tile along the north wall.

Room 102H Abated Fall 2011

Joint Compound	2-3% Chrysotile	72 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north wall.
Millboard Pipe Insulation	50% Chrysotile	9 ft	Friable TSI	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	7	The asbestos millboard pipe insulation is above the ceiling tile along the north wall.

Room 104 (includes small hallway to room 102A) Abated Fall 2011

9" Floor Tile and Mastic	Assumed	446 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	639 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	Please refer to ACM Locations Map for further information (joint compound is under new wood paneling in areas).

Room 104A Abated Fall 2011

9" Floor Tile and Mastic	Assumed	81 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	216 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east, and west walls.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
Aircell Pipe Insulation	60-80% Chrysotile	10 ft	Friable TSI	Damaged	Physical Air Erosion Vibration	■□□ ■□□ ■□□	1	The asbestos aircell pipe insulation is above the ceiling tile along the west wall.
Millboard Pipe Insulation	50% Chrysotile	10 ft	Friable TSI	Damaged	Physical Air Erosion Vibration	■□□ ■□□ ■□□	1	The asbestos millboard pipe insulation is above the ceiling tile along the west wall.

Room 104B Abated Fall 2011

9" Floor Tile and Mastic	Assumed	81 ft ²	Non-friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	216 ft ²	Non-friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The asbestos joint compound is on the north, south, east, and west walls.
Aircell Pipe Insulation	60-80% Chrysotile	10 ft	Friable TSI	Damaged	Physical Air Erosion Vibration	■□□ ■□□ ■□□	1	The asbestos aircell pipe insulation is above the ceiling tile along the west wall.
Hard Fitting on Aircell Insulation	40% Chrysotile	2 fittings	Friable TSI	Damaged	Physical Air Erosion Vibration	■□□ ■□□ ■□□	1	None
Millboard Pipe Insulation	50% Chrysotile	10 ft	Friable TSI	Damaged	Physical Air Erosion Vibration	■□□ ■□□ ■□□	1	The asbestos millboard pipe insulation is above the ceiling tile along the west wall.

Room 104C Abated Fall 2011

9" Floor Tile and Mastic	Assumed	125 ft ²	Non-friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	414 ft ²	Non-friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The asbestos joint compound is on the north, south, east, and west walls.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
Aircell Pipe Insulation	60-80% Chrysotile	24 ft	Friable TSI	Damaged	Physical Air Erosion Vibration	■ □ □ ■ □ □ ■ □ □	1	The asbestos aircell pipe insulation is above the ceiling tile along the north and west walls.
Millboard Pipe Insulation	50% Chrysotile	24 ft	Friable TSI	Damaged	Physical Air Erosion Vibration	■ □ □ ■ □ □ ■ □ □	1	The asbestos millboard pipe insulation is above the ceiling tile along the north and west walls.
Hard Fitting on Millboard Insulation	40% Chrysotile	2 fittings	Friable TSI	Damaged	Physical Air Erosion Vibration	■ □ □ ■ □ □ ■ □ □	1	None

Room 104D Abated Fall 2011

Joint Compound	2-3% Chrysotile	72 ft ²	Non-friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The asbestos joint compound is on the west wall (room 104B is a sound proof booth, the materials is outside the booth).
Aircell Pipe Insulation	60-80% Chrysotile	5 ft	Friable TSI	Damaged	Physical Air Erosion Vibration	■ □ □ ■ □ □ ■ □ □	1	The asbestos pipe insulation is on the west end of the room (room 104B is a sound proof booth, the materials is outside the booth).
Hard Fitting on Aircell Insulation	40% Chrysotile	1 fittings	Friable TSI	Damaged	Physical Air Erosion Vibration	■ □ □ ■ □ □ ■ □ □	1	None

Room 104E Abated Fall 2011

Joint Compound	2-3% Chrysotile	18 ft ²	Non-friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The asbestos joint compound is on the south half of the east wall.
---------------------------	-----------------	--------------------	------------------------------	------	------	------	------	--

Hallway 105 (hallway from room 101C to 105D) Abated Fall 2011

9" Floor Tile and Mastic	Assumed	185 ft ²	Non-friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
-------------------------------------	---------	---------------------	------------------------------	------	------	------	------	---

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
Joint Compound	2-3% Chrysotile	36 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	Refer to ACM Locations Map for further information.
Wood Panel Adhesive	5% Chrysotile	657 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	Refer to ACM Locations Map for further information.
Aircell Pipe Insulation	60-80% Chrysotile	12 ft	Friable TSI	Damaged	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	1	The asbestos aircell pipe insulation is above the ceiling tile adjacent to room 105H.

Room 105A Abated Fall 2011

9" Floor Tile and Mastic	Assumed	151 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	225 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	Refer to ACM Locations Map for further information.

Room 105B Abated Fall 2011

9" Floor Tile and Mastic	Assumed	84 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	48 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the west half of the south wall and the south half of the east wall.

Room 105C Abated Fall 2011

9" Floor Tile and Mastic	Assumed	81 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
---	---------	--------------------	------------------------------	------	------	--	------	---

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
Joint Compound	2-3% Chrysotile	85 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the east and west walls.
Room 105D Abated Fall 2011								
9" Floor Tile and Mastic	Assumed	33 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	198 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east, and west walls.
Room 105E Abated Fall 2011								
9" Floor Tile and Mastic	Assumed	80 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	90 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north halves of the east and west walls.
Room 105F Abated Fall 2011								
9" Floor Tile and Mastic	Assumed	77 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	72 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the south wall.
Room 105G Abated Fall 2011								
9" Floor Tile and Mastic	Assumed	77 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
Wood Panel Adhesive	5% Chrysotile	324 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.
Room 105H Abated Fall 2011								
Carpet Mastic (with residual flooring)	5% Chrysotile	71 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	None
Room 105J Abated Fall 2011								
9" Floor Tile and Mastic	Assumed	100 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	385 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.
Aircell Pipe Insulation	60-80% Chrysotile	12 ft	Friable TSI	Damaged	Physical Air Erosion Vibration	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	1	The asbestos aircell pipe insulation is above the ceiling tile along the east wall.
Room 105K Abated Fall 2011								
Wood Panel Adhesive	5% Chrysotile	468 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.
Aircell Pipe Insulation	60-80% Chrysotile	28 ft	Friable TSI	Damaged	Physical Air Erosion Vibration	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	1	The asbestos aircell pipe insulation is above the ceiling tile along the center of the room.
Hard Fitting on Aircell Insulation	40% Chrysotile	1 fitting	Friable TSI	Damaged	Physical Air Erosion Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	1	None

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
Millboard Pipe Insulation	50% Chrysotile	14 ft	Friable TSI	Damaged	Physical Air Erosion Vibration	■□□ ■□□ ■□□	1	The asbestos millboard pipe insulation is above the ceiling tile along the center of the room.
Room 105L Abated Fall 2011								
Joint Compound	2-3% Chrysotile	45 ft ²	Non-friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The asbestos joint compound is on the north wall.
Room 105L1 Abated Fall 2011								
Joint Compound	2-3% Chrysotile	180 ft ²	Non-friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The asbestos joint compound is on the north and east walls.
Room 105L2 Abated Fall 2011								
Joint Compound	2-3% Chrysotile	234 ft ²	Non-friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The asbestos joint compound is on the east and south walls.
Room 105L3 Abated Fall 2011								
Joint Compound	2-3% Chrysotile	243 ft ²	Non-friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The asbestos joint compound is on the south and west walls.
Room 107 Abated Spring 2011								
9" Floor Tile and Mastic	Assumed	80 ft ²	Non-friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet and on the east half of the room, only.
Joint Compound	2-3% Chrysotile	81 ft ²	Non-friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The asbestos joint compound is on the west half of the north wall.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
Aircell Pipe Insulation	60-80% Chrysotile	12 ft	Friable TSI	Damaged	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	1	The asbestos aircell pipe insulation is along the west wall.
Room 108 Abated Spring 2011								
Joint Compound	2-3% Chrysotile	584 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east, and west walls.
Room 112 Abated Summer/Fall 2009								
Joint Compound	2-3% Chrysotile	90 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the east half of the south wall.
Room 113 Abated Fall 2011								
9" Floor Tile and Mastic	Assumed	73 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs.
Joint Compound	2-3% Chrysotile	171 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the south and west walls.
Room 114A Abated Summer/Fall 2009								
Window Glazing on Door	2% Chrysotile	1 window	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos glazing is on the door it in the southeast corner of the room.
Room 115 (includes small hallway to room 115F) Abated Fall 2011								
Wood Panel Adhesive	5% Chrysotile	243 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is in the small hallway between rooms 115A and 115F.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
Hallway 116 Abated Winter/Spring 2010								
9" Floor Tile and Mastic	Assumed	38 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs and are under carpet; they are adjacent to room 118G and 118N.
Joint Compound	2-3% Chrysotile	171 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, east, and west walls adjacent to room 118G and 118N.
Room 118G Abated Winter/Spring 2010								
Joint Compound	2-3% Chrysotile	297 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, and east walls and part of the west wall.
Aircell Pipe Insulation	60-80% Chrysotile	8 ft	Friable TSI	Damaged	Physical Air Erosion Vibration	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	1	The asbestos aircell pipe insulation is along the southwest corner of the room.
Room 118H Abated Winter/Spring 2010								
Joint Compound	2-3% Chrysotile	396 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the west end of the south wall, north wall, east wall, and west wall.
Room 118J Abated Winter/Spring 2010								
Joint Compound	2-3% Chrysotile	112 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north and east walls.
Room 118K Abated Winter/Spring 2010								
Joint Compound	2-3% Chrysotile	243 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, and east walls.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	-----------------------------	-------

Room 118L Abated Winter/Spring 2010

Joint Compound	2-3% Chrysotile	477 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east, and west walls.
---------------------------	-----------------	---------------------	------------------------------	------	------	--	------	---

Room 118M Abated Winter/Spring 2010

Joint Compound	2-3% Chrysotile	333 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east, and west walls.
---------------------------	-----------------	---------------------	------------------------------	------	------	--	------	---

Room 118N Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	123 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs.
Joint Compound	2-3% Chrysotile	153 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the east and west walls.
Acoustic Ceiling Plaster	8% Chrysotile	33 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	7	The asbestos acoustic ceiling plaster is above ceiling tile on the east end of the room, only.

Room 118P Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	119 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	594 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east, and west walls.
Acoustic Ceiling Plaster	8% Chrysotile	62 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	7	The asbestos acoustic ceiling plaster is above ceiling tile on the south end of the room, only.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 118Q Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	37 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	216 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, east, and west walls.

Room 118R Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	37 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	216 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east, and west walls.

Room 118S Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	37 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	216 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east, and west walls.

Room 118T Abated Winter/Spring 2010

12" Light Green Floor Tile with Brown Marks and Mastic	3-5% Chrysotile	45 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
Joint Compound	2-3% Chrysotile	286 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east, and west walls.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 118U Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	51 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	360 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east, and west walls.

Room 118V Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	33 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	210 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east, and west walls.

Room 118W Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	61 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	162 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the south, east, and west walls.
Acoustic Ceiling Plaster	8% Chrysotile	61 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	7	The asbestos acoustic ceiling plaster is above the ceiling tile.

Room 118X Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	141 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
-------------------------------------	---------	---------------------	------------------------------	------	------	--	------	---

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
Joint Compound	2-3% Chrysotile	162 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the west half of the south wall, east wall, and west wall.
Acoustic Ceiling Plaster	8% Chrysotile	141 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	7	The asbestos acoustic ceiling plaster is above the ceiling tile.

Room 120 Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	367 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	702 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east, and west walls.

Room 120A Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	34 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	211 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east, and west walls.

Room 120B Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	34 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	211 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east, and west walls.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 120C Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	34 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	211 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east, and west walls.

Room 120D Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	34 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	211 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east, and west walls.

Room 120E Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	34 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	211 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east, and west walls.

Room 120F Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	34 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	211 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east, and west walls.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Hallway 188 (includes small hallway to room 114A) Abated Fall 2011

9" Floor Tile and Mastic	Assumed	1,901 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs.
Mastic for 12" Off-white Floor Tile with Tan Marks	5% Chrysotile	188 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The mastic for 12" floor tile contains asbestos; the floor tile is negative and is in the small hallway by room 114A.
Joint Compound	2-3% Chrysotile	474 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	Refer to ACM Locations Map for further information.
Acoustic Ceiling Plaster	8% Chrysotile	677 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	■□□ ■□□ ■□□	7	Refer to ACM Locations Map for further information.
Window/Door System Glazing	3% Chrysotile	1 door 1 window	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos window glazing is on south window and door in the small hallway by room 114A.

Room 188S Abated Fall 2011

9" Floor Tile and Mastic	Assumed	302 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs.
Joint Compound	2-3% Chrysotile	400 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	Refer to ACM Locations Map for further information.
Aircell Pipe Insulation	60-80% Chrysotile	32 ft	Friable TSI	Damaged	Physical Air Erosion Vibration	■□□ ■□□ ■□□	1	The asbestos aircell pipe insulation is above the ceiling tile.
Hard Fitting on Aircell Insulation	40% Chrysotile	1 fitting	Friable TSI	Damaged	Physical Air Erosion Vibration	■□□ ■□□ ■□□	1	None

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
Millboard Pipe Insulation	50% Chrysotile	32 ft	Friable TSI	Damaged	Physical Air Erosion Vibration	■ □ □ ■ □ □ ■ □ □	1	The asbestos millboard pipe insulation is above the ceiling tile.
Hard Fitting on Millboard Insulation	40% Chrysotile	1 fitting	Friable TSI	Damaged	Physical Air Erosion Vibration	■ □ □ ■ □ □ ■ □ □	1	None

Room 200

Abated September 2011

9" Floor Tile and Mastic		ft ²	Non-friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet
Joint Compound	2-3% Chrysotile	729 ft ²	Non-friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The asbestos joint compound is on the north, south, east and west walls.

Room 200A

Abated September 2011

Joint Compound	2-3% Chrysotile	36 ft ²	Non-friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The asbestos joint compound is on the north, south, east and west walls.
---------------------------	-----------------	--------------------	------------------------------	------	------	------	------	--

Room 201

Abated September 2011

Joint Compound	2-3% Chrysotile	999 ft ²	Non-friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The asbestos joint compound is on the north, south, east and west walls.
---------------------------	-----------------	---------------------	------------------------------	------	------	------	------	--

Room 203

Abated September 2011

9" Floor Tile and Mastic	Assumed	330 ft ²	Non-friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet
Joint Compound	2-3% Chrysotile	876 ft ²	Non-friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The asbestos joint compound is on the north, south, east and west walls.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 203A Abated September 2011

9" Floor Tile and Mastic	Assumed	78 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet
Joint Compound	2-3% Chrysotile	162 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the south and west walls.

Room 204 Abated September 2011

9" Floor Tile and Mastic	Assumed	368 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet
Joint Compound	2-3% Chrysotile	702 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east and west walls.

Room 205 (including room 205A) Abated September 2011

9" Floor Tile and Mastic	Assumed	837 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet
Joint Compound	2-3% Chrysotile	1,062 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east and west walls.

Room 206 Abated September 2011

Mastic for 12" Tan/White/Brown Mottled Floor Tile	3% Chrysotile	442 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The mastic for 12" floor tile contains asbestos; the floor tile is negative.
Joint Compound	2-3% Chrysotile	720 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east, and west walls.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 208 Abated September 2011

9" Floor Tile and Mastic	Assumed	176 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet
Joint Compound	2-3% Chrysotile	477 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east and west walls.

Room 208A Abated September 2011

Joint Compound	2-3% Chrysotile	450 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east, and west walls.
---------------------------	-----------------	---------------------	------------------------------	------	------	--	------	---

Room 208B Abated Spring 2011

9" Floor Tile and Mastic	Assumed	86 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet
Joint Compound	2-3% Chrysotile	243 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the south, east, and west walls.

Room 208C Abated Spring 2011

9" Floor Tile and Mastic	Assumed	93 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet
Joint Compound	2-3% Chrysotile	279 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, east, and west walls.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 209 Abated September 2011

Joint Compound	2-3% Chrysotile	965 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east, and west walls.
----------------	-----------------	---------------------	------------------------------	------	------	--	------	---

Room 210 Abated Spring 2011

9" Floor Tile and Mastic	Assumed	464 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs.
Joint Compound	2-3% Chrysotile	774 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east, and west walls.

Room 211 Abated Summer/Fall 2009

9" Floor Tile and Mastic	Assumed	199 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	160 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north wall (on the side of the stairway) and the west wall.

Room 211A Abated Summer/Fall 2009

9" Floor Tile and Mastic	Assumed	125 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs.
-----------------------------	---------	---------------------	------------------------------	------	------	--	------	--

Room 211B Abated Summer/Fall 2009

9" Floor Tile and Mastic	Assumed	125 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
-----------------------------	---------	---------------------	------------------------------	------	------	--	------	---

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	-----------------------------	-------

Room 212 Abated Summer/Fall 2009

9" Floor Tile and Mastic	Assumed	263 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs.
Joint Compound	2-3% Chrysotile	456 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the east half of the north wall, south wall, east wall, and west wall.

Room 213 Abated September 2011

9" Floor Tile and Mastic	Assumed	272 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	216 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the west wall.
Aircell Pipe Insulation	60-80% Chrysotile	12 ft	Friable TSI	Damaged	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	1	The asbestos aircell pipe insulation is along the southeast corner of the room.

Room 214 Abated Winter/Spring 2010

Joint Compound	2-3% Chrysotile	36 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the west end of the south wall.
---------------------------	-----------------	--------------------	------------------------------	------	------	--	------	---

Room 215 Abated Spring 2011

9" Floor Tile and Mastic	Assumed	638 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	216 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the west wall.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
Room 216 Abated Winter/Spring 2010								
12" Floor Tile with Brown Splatter Marks and Mastic	3-5% Chrysotile	100 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
Room 218 Abated Winter/Spring 2010								
Joint Compound	2-3% Chrysotile	270 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the south, east, and west walls.
Room 219 Abated Winter/Spring 2010								
9" Floor Tile and Mastic	Assumed	2,122 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	517 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north wall, north half of the west wall and above all the windows and doors throughout the room.
Room 220 Abated Winter/Spring 2010								
Joint Compound	2-3% Chrysotile	667 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east, and west walls.
Room 221 Abated Winter/Spring 2010								
9" Floor Tile and Mastic	Assumed	411 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	405 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the south, east, and west walls.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
Wood Panel Adhesive	5% Chrysotile	297 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north wall.

Room 221A Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	103 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	360 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east, and west walls.
Purple Sink Undercoating	5% Chrysotile	1 sink	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos undercoating is on a sink along the west wall.

Room 221B Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	168 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	468 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.

Room 221C Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	191 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	126 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the east wall.

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	-----------------------------	-------

Wood Panel Adhesive	5% Chrysotile	378 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, and west walls.
Hard Fitting on Fiberglass Insulation	2% Chrysotile	1 fitting	Friable TSI	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	6	The asbestos hard fitting on fiberglass insulation is along the north wall.

Room 221D Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	123 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	396 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.

Room 221E Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	396 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	120 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.

Room 223 Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	188 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	495 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 223A Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	128 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	405 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.

Room 223B Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	70 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	333 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.

Room 224 (north room) Abated Winter/Spring 2010

Joint Compound	2-3% Chrysotile	630 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north wall, west wall, east wall, and east half of the south wall.
---------------------------	-----------------	---------------------	------------------------------	------	------	--	------	--

Room 224 (south room) Abated Winter/Spring 2010

Joint Compound	2-3% Chrysotile	630 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the south and west wall.
---------------------------	-----------------	---------------------	------------------------------	------	------	--	------	--

Hallway 288 (includes all hallways on 2nd floor) Abated September 2011

9" Floor Tile and Mastic	Assumed	2, 826 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs.
-------------------------------------	---------	------------------------	------------------------------	------	------	--	------	--

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
Joint Compound	2-3% Chrysotile	2,016 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	Refer to ACM Locations Map for further information.
Acoustic Ceiling Plaster	8% Chrysotile	1,088 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	7	The asbestos acoustic ceiling plaster is above ceiling tile; refer to ACM Locations Map for further information.
Aircell Pipe Insulation	60-80% Chrysotile	10 ft	Friable TSI	Significantly Damaged	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	1	The asbestos aircell pipe insulation is along the southwest corner adjacent to room 224.

Room 299A Abated September 2011

White Pebbled Pattern Linoleum	20% Chrysotile	168 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	None
Joint Compound	2-3% Chrysotile	468 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east, and west walls.

Room 299B Abated September 2011

Joint Compound	2-3% Chrysotile	468 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east, and west walls.
---------------------------	-----------------	---------------------	------------------------------	------	------	--	------	---

Room 300 (includes small hallway to room 388E) Abated Fall 2011

9" Floor Tile and Mastic	Assumed	637 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	1,053 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	Refer to ACM Locations Map for further information.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
Wood Panel Adhesive	5% Chrysotile	459 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	Refer to ACM Locations Map for further information.

Room 300A Abated Fall 2011

9" Floor Tile and Mastic	Assumed	64 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	153 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north and west walls.

Room 300B (east room) Abated Fall 2011

9" Floor Tile and Mastic	Assumed	216 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	261 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north and south walls.
Wood Panel Adhesive	5% Chrysotile	460 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the west and east walls.

Room 300B (west room) Abated Fall 2011

9" Floor Tile and Mastic	Assumed	108 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	378 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, east, and west walls.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 300C Abated Fall 2011

9" Floor Tile and Mastic	Assumed	203 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	504 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, east, and west walls.

Hallway 301 (includes hallway from room 301A to 301C) Abated Fall 2011

9" Floor Tile and Mastic	Assumed	316 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	507 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, east, and west walls.

Room 301A Abated Fall 2011

9" Floor Tile and Mastic	Assumed	93 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	338 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, east, and west walls.

Room 301B Abated Fall 2011

9" Floor Tile and Mastic	Assumed	93 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	338 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, east, and west walls.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 301C (north room) Abated Fall 2011

9" Floor Tile and Mastic	Assumed	201 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	513 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, east, and west walls.

Room 301C (south room) Abated Fall 2011

9" Floor Tile and Mastic	Assumed	128 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	405 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, east, and west walls.

Room 301D Abated Fall 2011

9" Floor Tile and Mastic	Assumed	128 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	405 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, east, and west walls.

Room 301E Abated Fall 2011

9" Floor Tile and Mastic	Assumed	102 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	360 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, east, and west walls.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 301F Abated Fall 2011

9" Floor Tile and Mastic	Assumed	102 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	360 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, east, and west walls.

Hallway 302 (includes hallway from room 302A to 302D) Abated Fall 2011

9" Floor Tile and Mastic	Assumed	142 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	403 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, east, and west walls.

Room 302A Abated Fall 2011

9" Floor Tile and Mastic	Assumed	120 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	382 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, east, and west walls.

Room 302B Abated Fall 2011

9" Floor Tile and Mastic	Assumed	94 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	342 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, east, and west walls.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 302C Abated Fall 2011

9" Floor Tile and Mastic	Assumed	128 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	405 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, east, and west walls.

Room 302D Abated Fall 2011

9" Floor Tile and Mastic	Assumed	115 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	387 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, east, and west walls.

Room 302F Abated Fall 2011

9" Floor Tile and Mastic	Assumed	108 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	378 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, east, and west walls.

Room 303 Abated Fall 2011

9" Floor Tile and Mastic	Assumed	533 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	918 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, east, and west walls.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Hallway 304 (includes hallway from room 304A to 304B) Abated Fall 2011

9" Floor Tile and Mastic	Assumed	212 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	504 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, east, and west walls.

Room 304A Abated Fall 2011

9" Floor Tile and Mastic	Assumed	186 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	504 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, east, and west walls.

Room 304B Abated Fall 2011

9" Floor Tile and Mastic	Assumed	115 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	387 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, east, and west walls.

Room 304C Abated Fall 2011

9" Floor Tile and Mastic	Assumed	115 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	387 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, east, and west walls.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 304D Abated Fall 2011

9" Floor Tile and Mastic	Assumed	161 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	612 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, east, and west walls.

Room 304E Abated Fall 2011

9" Floor Tile and Mastic	Assumed	81 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	333 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east, and west walls.
Purple Sink Undercoating	5% Chrysotile	1 sink	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos undercoating is on a sink along the north wall.

Hallway 305 (includes hallway 305A to 305D) Abated Fall 2011

9" Floor Tile and Mastic	Assumed	132 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	612 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, east, and west walls.

Room 305A Abated Fall 2011

9" Floor Tile and Mastic	Assumed	105 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
-------------------------------------	---------	---------------------	------------------------------	------	------	--	------	---

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
Wood Panel Adhesive	5% Chrysotile	378 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, east, and west walls.

Room 305B Abated Fall 2011

9" Floor Tile and Mastic	Assumed	105 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	378 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, east, and west walls.

Room 305C Abated Fall 2011

9" Floor Tile and Mastic	Assumed	125 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	405 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, east, and west walls.

Room 305D Abated Fall 2011

9" Floor Tile and Mastic	Assumed	125 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	405 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, east, and west walls.

Room 306 Abated Fall 2011

9" Floor Tile and Mastic	Assumed	106 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
-------------------------------------	---------	---------------------	------------------------------	------	------	--	------	---

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
Wood Panel Adhesive	5% Chrysotile	378 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, east, and west walls.

Room 306A Abated Fall 2011

9" Floor Tile and Mastic	Assumed	38 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs.
Joint Compound	2-3% Chrysotile	252 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north wall, south wall, east wall, west wall, and ceiling.

Room 309 (includes small hallway to room 309E) Abated Fall 2011

9" Floor Tile and Mastic	Assumed	180 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	126 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north wall.
Wood Panel Adhesive	5% Chrysotile	378 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the south, east, and west walls.

Room 309A Abated Fall 2011

9" Floor Tile and Mastic	Assumed	43 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	99 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north wall.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
Wood Panel Adhesive	5% Chrysotile	135 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the south, east, and west walls.

Room 309B Abated Fall 2011

9" Floor Tile and Mastic	Assumed	127 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	455 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, east, and west walls.

Room 309C Abated Fall 2011

9" Floor Tile and Mastic	Assumed	87 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	127 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, east, and west walls.

Room 309D Abated Fall 2011

9" Floor Tile and Mastic	Assumed	96 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	300 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, and east walls.

Room 309E Abated Fall 2011

9" Floor Tile and Mastic	Assumed	74 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
-------------------------------------	---------	--------------------	------------------------------	------	------	--	------	---

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
Wood Panel Adhesive	5% Chrysotile	306 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, and west walls.

Room 309F Abated Fall 2011

9" Floor Tile and Mastic	Assumed	70 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	378 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the south, east, and west walls.

Room 309G Abated Fall 2011

9" Floor Tile and Mastic	Assumed	68 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	225 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, east, and west walls.

Room 310 Abated Fall 2011

9" Floor Tile and Mastic	Assumed	79 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	171 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north and east walls.

Room 310A Abated Fall 2011

9" Floor Tile and Mastic	Assumed	138 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
-------------------------------------	---------	---------------------	------------------------------	------	------	--	------	---

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
Joint Compound	2-3% Chrysotile	216 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the south and east walls.

Room 310B Abated Fall 2011

9" Floor Tile and Mastic	Assumed	137 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	207 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the south and west walls.

Room 310C Abated Fall 2011

9" Floor Tile and Mastic	Assumed	89 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	171 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north and west walls.

Room 310D Abated Fall 2011

9" Floor Tile and Mastic	Assumed	123 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	306 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, and west walls.

Room 310E Abated Fall 2011

9" Floor Tile and Mastic	Assumed	92 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
---	---------	--------------------	------------------------------	------	------	--	------	---

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
Joint Compound	2-3% Chrysotile	252 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, and east walls.
Room 311 Abated Summer/Fall 2009								
9" Floor Tile and Mastic	Assumed	131 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Room 314 Abated Summer/Fall 2009								
9" Floor Tile and Mastic	Assumed	599 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	27 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north west corner of the room, only.
Brown Sink Undercoating	10% Chrysotile	1 sink	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos undercoating is on a sink along the north wall.
Room 314A Abated Summer/Fall 2009								
9" Floor Tile and Mastic	Assumed	85 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Hallway 315 Abated Spring 2011								
9" Floor Tile and Mastic	Assumed	122 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	36 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the west wall.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
Wood Panel Adhesive	5% Chrysotile	441 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, and east walls.

Room 315A Abated Spring 2011

9" Floor Tile and Mastic	Assumed	107 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	378 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, east, and west walls.

Room 315B Abated Spring 2011

9" Floor Tile and Mastic	Assumed	127 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	423 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, east, and west walls.

Room 315C Abated Spring 2011

9" Floor Tile and Mastic	Assumed	405 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	120 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, east, and west walls.

Room 315D Abated Spring 2011

9" Floor Tile and Mastic	Assumed	100 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
-------------------------------------	---------	---------------------	------------------------------	------	------	--	------	---

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
Wood Panel Adhesive	5% Chrysotile	360 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, east, and west walls.
Room 315E Abated Spring 2011								
9" Floor Tile and Mastic	Assumed	109 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	342 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, east, and west walls.
Room 315E1 Abated Fall 2011								
Wood Panel Adhesive	5% Chrysotile	468 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, east, and west walls.
Room 315E1A Abated Fall 2011								
Wood Panel Adhesive	5% Chrysotile	306 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, east, and west walls.
Room 315F Abated Spring 2011								
9" Floor Tile and Mastic	Assumed	96 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	360 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wall panel adhesive is on the north, south, east, and west walls.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
Room 316 Abated Winter/Spring 2010								
Joint Compound	2-3% Chrysotile	45 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the west half of the south wall.
Room 318 Abated Winter/Spring 2010								
12" Light Green Floor Tile with Brown Marks and Mastic	3-5% Chrysotile	112 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
Joint Compound	2-3% Chrysotile	72 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the south wall.
Room 319 Abated Winter/Spring 2010								
Joint Compound	2-3% Chrysotile	180 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north and south walls.
Room 320 (includes small hallway to room 320G) Abated Winter/Spring 2010								
9" Floor Tile and Mastic	Assumed	180 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	72 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	Refer to ACM Locations Map for further information.
Wood Panel Adhesive	5% Chrysotile	135 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	Refer to ACM Locations Map for further information.
Acoustic Ceiling Plaster	8% Chrysotile	180 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	7	The asbestos acoustic ceiling plaster is above ceiling tile; refer to ACM Locations Map for further information.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 320A Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	84 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	360 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east, and west walls.
Purple Sink Undercoating	5% Chrysotile	1 sink	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos undercoating is on a sink along the south wall.

Room 320B Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	234 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	617 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.

Room 320C Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	112 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	387 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.

Room 320D Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	105 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
-------------------------------------	---------	---------------------	------------------------------	------	------	--	------	---

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
Wood Panel Adhesive	5% Chrysotile	369 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.

Room 320E Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	105 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	369 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.
Hard Fitting on Fiberglass Insulation	2% Chrysotile	2 fittings	Friable TSI	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	6	The asbestos hard fittings on fiberglass insulation are above the ceiling tile in the center of the room.

Room 320F Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	124 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	414 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.

Room 320G Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	107 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	360 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 320H Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	121 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	396 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.

Room 320J Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	121 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	394 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.

Room 321 (includes small hallway to room 321K) Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	90 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet and in the small hallway between rooms 321M to 321K.
Joint Compound	2-3% Chrysotile	1,314 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east, and west walls.

Room 321A Abated Winter/Spring 2010

Wood Panel Adhesive	5% Chrysotile	369 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.
--------------------------------	---------------	---------------------	------------------------------	------	------	--	------	--

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
Room 321B Abated Winter/Spring 2010								
Wood Panel Adhesive	5% Chrysotile	324 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.
Room 321C Abated Winter/Spring 2010								
Wood Panel Adhesive	5% Chrysotile	324 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.
Room 321D Abated Winter/Spring 2010								
Wood Panel Adhesive	5% Chrysotile	324 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.
Room 321E Abated Winter/Spring 2010								
Wood Panel Adhesive	5% Chrysotile	342 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.
Room 321F Abated Winter/Spring 2010								
Wood Panel Adhesive	5% Chrysotile	378 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.
Room 321G Abated Winter/Spring 2010								
Wood Panel Adhesive	5% Chrysotile	504 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 321H Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	103 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	378 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.

Room 321J Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	99 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	360 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.

Room 321K Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	35 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	205 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north wall, south wall, east wall, west wall, and ceiling.

Room 321L Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	127 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	288 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east, and west walls.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 321M **Abated Winter/Spring 2010**

9" Floor Tile and Mastic	Assumed	242 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	468 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, and east walls.

Room 321N **Abated Winter/Spring 2010**

12" Light Green Floor Tile with Brown Marks and Mastic	3-5% Chrysotile	60 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
Joint Compound	2-3% Chrysotile	219 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east, and west walls.

Room 321P **Abated Winter/Spring 2010**

Joint Compound	2-3% Chrysotile	207 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, and east walls.
---------------------------	-----------------	---------------------	------------------------------	------	------	--	------	---

Room 322 (includes hallway from room 320A to 322F) **Abated Winter/Spring 2010**

9" Floor Tile and Mastic	Assumed	747 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	2,323 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	Refer to ACM Locations Map for further information.
Joint Compound	2-3% Chrysotile	279 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	Refer to ACM Locations Map for further information.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 322A Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	261 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Joint Compound	2-3% Chrysotile	189 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the south wall.
Wood Panel Adhesive	5% Chrysotile	405 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, east, and west walls.

Room 322B Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	184 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	522 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.
Acoustic Ceiling Plaster	8% Chrysotile	138 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	7	The asbestos acoustic ceiling plaster is above the ceiling tile on the east end of the room.

Room 322C Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	81 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	324 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 322D Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	107 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	360 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.

Room 322E Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	130 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	432 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.

Room 322F Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	82 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	234 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, and east walls.

Room 322F1 Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	81 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	234 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, and west walls.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 322G Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	189 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	504 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.

Room 322H Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	110 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	378 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.

Room 322J Abated Winter/Spring 2010

9" Floor Tile and Mastic	Assumed	110 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs; they are under carpet.
Wood Panel Adhesive	5% Chrysotile	378 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.

Hallway 388 Abated Fall 2011

9" Floor Tile and Mastic	Assumed	1,546 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs.
Joint Compound	2-3% Chrysotile	2,412 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	Refer to ACM Locations Map for further information.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
Acoustic Ceiling Plaster Abated Winter/Spring 2010	8% Chrysotile	750 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	■□□ ■□□ ■□□	7	The asbestos acoustic ceiling plaster is above the ceiling tile in the north end of the hallway.
Room 401 (includes small hallway from room 401E to 401F) Abated Summer/Fall 2009								
Wood Panel Adhesive	5% Chrysotile	459 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north wall and the south wall of the small hallway.
Room 401B Abated Summer/Fall 2009								
Wood Panel Adhesive	5% Chrysotile	261 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, east, and west walls.
Room 401E Abated Summer/Fall 2009								
Wood Panel Adhesive	5% Chrysotile	153 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north wall.
Room 401F Abated Summer/Fall 2009								
Wood Panel Adhesive	5% Chrysotile	90 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the east wall and east half of the south wall.
Room 402 Abated Winter/Spring 2010								
Wood Panel Adhesive	5% Chrysotile	927 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
Room 402A Abated Winter/Spring 2010								
9" Floor Tile and Mastic	Assumed	196 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs.
Joint Compound	2-3% Chrysotile	270 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the south and east walls.
Room 402B Abated Winter/Spring 2010								
9" Floor Tile and Mastic	Assumed	44 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs.
Joint Compound	2-3% Chrysotile	117 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the south and west walls.
Room 402C Abated Winter/Spring 2010								
Wood Panel Adhesive	5% Chrysotile	450 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.
Room 403C Abated Summer/Fall 2009								
Hard Fitting on Fiberglass Insulation	2% Chrysotile	2 fittings	Friable TSI	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	7	None
Room 403E Abated Summer/Fall 2009								
Wood Panel Adhesive	5% Chrysotile	270 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the east and west walls.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
Room 403F Abated Summer/Fall 2009								
Wood Panel Adhesive	5% Chrysotile	216 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north and west walls.
Room 403H Abated Summer/Fall 2009								
Wood Panel Adhesive	5% Chrysotile	252 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the south, east, and west walls.
Room 404 Abated Winter/Spring 2010								
Joint Compound	2-3% Chrysotile	36 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north end of the west wall.
Wood Panel Adhesive	5% Chrysotile	667 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.
Room 404A Abated Winter/Spring 2010								
Wood Panel Adhesive	5% Chrysotile	360 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.
Room 404B Abated Winter/Spring 2010								
Wood Panel Adhesive	5% Chrysotile	360 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.
Room 404C Abated Winter/Spring 2010								
Wood Panel Adhesive	5% Chrysotile	360 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
Room 404D Abated Winter/Spring 2010								
Wood Panel Adhesive	5% Chrysotile	378 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.
Room 404E Abated Winter/Spring 2010								
Wood Panel Adhesive	5% Chrysotile	360 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.
Room 404F Abated Winter/Spring 2010								
Wood Panel Adhesive	5% Chrysotile	360 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.
Room 404G Abated Winter/Spring 2010								
Wood Panel Adhesive	5% Chrysotile	360 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.
Room 404H Abated Winter/Spring 2010								
Wood Panel Adhesive	5% Chrysotile	396 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.
Room 407 Abated Summer/Fall 2009								
Wood Panel Adhesive	5% Chrysotile	747 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.
Joint Compound	2-3% Chrysotile	36 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north wall.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	-----------------------------	-------

Room 407A

Joint Compound Abated Winter/Spring 2010	2-3% Chrysotile	36 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north half of the ceiling, north wall, and the north halves of the east and west walls.
Hard Fitting on Fiberglass Insulation Abated Summer/Fall 2009	2% Chrysotile	3 fittings	Friable TSI	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	6	The asbestos hard fittings on fiberglass insulation are along the west wall.

Room 408 **Abated Winter/Spring 2010**

Wood Panel Adhesive	5% Chrysotile	387 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.
--------------------------------	---------------	---------------------	------------------------------	------	------	--	------	--

Room 408A **Abated Winter/Spring 2010**

Wood Panel Adhesive	5% Chrysotile	242 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.
--------------------------------	---------------	---------------------	------------------------------	------	------	--	------	--

Room 408B **Abated Winter/Spring 2010**

Wood Panel Adhesive	5% Chrysotile	242 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.
--------------------------------	---------------	---------------------	------------------------------	------	------	--	------	--

Room 408C **Abated Winter/Spring 2010**

Wood Panel Adhesive	5% Chrysotile	486 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.
--------------------------------	---------------	---------------------	------------------------------	------	------	--	------	--

Room 408D **Abated Winter/Spring 2010**

Wood Panel Adhesive	5% Chrysotile	405 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.
--------------------------------	---------------	---------------------	------------------------------	------	------	--	------	--

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	-----------------------------	-------

Room 408E Abated Winter/Spring 2010

Wood Panel Adhesive	5% Chrysotile	306 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.
--------------------------------	---------------	---------------------	------------------------------	------	------	--	------	--

Room 408F Abated Winter/Spring 2010

Wood Panel Adhesive	5% Chrysotile	306 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.
--------------------------------	---------------	---------------------	------------------------------	------	------	--	------	--

Room 410 Abated Winter/Spring 2010

Joint Compound	2-3% Chrysotile	423 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the west wall and west half of the north wall.
Wood Panel Adhesive	5% Chrysotile	621 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the south wall, east wall, and east half of the north wall.

Hallway 412 Abated Summer/Fall 2009

Joint Compound	2-3% Chrysotile	63 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the west wall.
Wood Panel Adhesive	5% Chrysotile	990 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the south wall, east wall, and east half of the north wall.

Room 412A Abated Summer/Fall 2009

Wood Panel Adhesive	5% Chrysotile	333 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.
--------------------------------	---------------	---------------------	------------------------------	------	------	--	------	--

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
Room 412B Abated Summer/Fall 2009								
Wood Panel Adhesive	5% Chrysotile	333 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.
Room 412C (includes small closet) Abated Summer/Fall 2009								
Joint Compound	2-3% Chrysotile	477 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east, and west walls in the room and the ceiling, north, east, and west walls in the closet.
Room 412D Abated Summer/Fall 2009								
Joint Compound	2-3% Chrysotile	63 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, south, east, and west walls.
Room 412E Abated Summer/Fall 2009								
Wood Panel Adhesive	5% Chrysotile	342 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.
Room 412F Abated Summer/Fall 2009								
Wood Panel Adhesive	5% Chrysotile	342 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.
Room 412G Abated Summer/Fall 2009								
Joint Compound	2-3% Chrysotile	63 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north, east, and west walls.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	-----------------------------	-------

Room 412H Abated Summer/Fall 2009

Wood Panel Adhesive	5% Chrysotile	432 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.
--------------------------------	---------------	---------------------	------------------------------	------	------	--	------	--

Room 412J Abated Summer/Fall 2009

Wood Panel Adhesive	5% Chrysotile	450 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.
--------------------------------	---------------	---------------------	------------------------------	------	------	--	------	--

Room 412K Abated Summer/Fall 2009

Wood Panel Adhesive	5% Chrysotile	378 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.
--------------------------------	---------------	---------------------	------------------------------	------	------	--	------	--

Room 412L Abated Summer/Fall 2009

Wood Panel Adhesive	5% Chrysotile	324 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos wood panel adhesive is on the north, south, east, and west walls.
--------------------------------	---------------	---------------------	------------------------------	------	------	--	------	--

Hallway 488 (includes hallway from room 401A to 403D) Abated Winter/Spring 2010

Wood Panel Adhesive	5% Chrysotile	1,980 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	Refer to ACM Locations Map for further information.
Joint Compound	2-3% Chrysotile	63 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	Refer to ACM Locations Map for further information.

4th Floor Mechanical Closets Abated Winter/Spring 2010

Hard Fitting on Fiberglass Insulation	2% Chrysotile	1 fitting	Friable TSI	Significantly Damaged	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	1	Refer to ACM Locations Map for further Information.
--	---------------	-----------	----------------	--------------------------	--------------------------------------	---	---	---

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
Aircell Pipe Insulation	60-80% Chrysotile	154 ft	Friable TSI	Significantly Damaged	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	1	Refer to ACM Locations Map for further information.
Hard Fittings on Aircell Insulation	40% Chrysotile	2 fittings	Friable TSI	Significantly Damaged	Physical Air Erosion Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	1	Refer to ACM Locations Map for further information.

Northeast Stairway (includes 1st to 4th floor) Abated Spring 2011

9" Floor Tile and Mastic	Assumed	584 ft ²	Non-friable Miscellaneous	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed ACMs.	
Joint Compound	2-3% Chrysotile	378 ft ²	Non-friable Miscellaneous	N/A*	N/A*	N/A*	Refer to ACM Locations Map for further information.	
Window/Door System Glazing	3% Chrysotile	1 door 2 windows	Non-friable Miscellaneous	N/A*	N/A*	N/A*	The asbestos glazing is on the windows and the east door of main entrance.	
Acoustic Ceiling Plaster	8% Chrysotile	206 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	7	The asbestos acoustic ceiling plaster is above the ceiling tile; refer to ACM Locations Map for further information.

East Stairway (includes 1st to 4th floor and entry vestibule between 1st and 2nd floor) Abated Fall 2011

9" Floor Tile and Mastic	Assumed	417 ft ²	Non-friable Miscellaneous	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed ACMs; refer to ACM Locations Map for further information.
12" Brown Floor Tile with Brown Marks and Mastic	3-5% Chrysotile	249 ft ²	Non-friable Miscellaneous	N/A*	N/A*	N/A*	The 12" floor tile and mastic contain asbestos; refer to ACM Locations Map for further information.
Joint Compound	2-3% Chrysotile	1,944 ft ²	Non-friable Miscellaneous	N/A*	N/A*	N/A*	Refer to ACM Locations Map for further information.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
MINARD HALL A021

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
Window Glazing	3% Chrysotile	1 window	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos glazing is on the east window between the 2 nd and 3 rd floors.

East Elevator Abated 2013

12" Brown Floor Tile with Brown Marks and Mastic	3-5% Chrysotile	49 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 12" floor tile and mastic contain asbestos.
---	-----------------	--------------------	------------------------------	------	------	--	------	---

Exterior Abated 2009-2011

Window Glazing	3% Chrysotile	5 windows	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos window glazing is on the west and south windows by room 114A.
Transite Panels	3% Chrysotile	125 ea	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos transite panels are located above the exterior windows.

Roof Abated 2011-2013

Flashing (on penetrations)	10% Chrysotile	16 ea	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos flashing is around the penetrations (vents and chimneys) on the roofs of the 1901, 1917, and 1930 buildings.
Flashing (on seams)	2-10% Chrysotile	150 ft	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos flashing is on the seams between the 1901 and 1917 buildings and the 1917 and 1930 buildings.

- 1) Damaged or Significantly Damaged TSI ACM
- 2) Damaged Friable Surfacing ACM
- 3) Significantly Damaged Friable Surfacing ACM
- 4) Damaged or Significantly Damaged Friable Miscellaneous ACM

- 5) ACM with Potential for Damage
- 6) ACM with Potential for Significant Damage
- 7) Any Remaining Friable ACM or Friable Suspected ACM

End

* = Non-Friable materials were not assessed