

# NARRATIVE REPORT

## 1.0 BUILDING INFORMATION

Sudro Hall was originally constructed in 1959; a 1968 addition extended the building to the east, a 1998 addition extended the northeast entryway, and a 2002 addition extended the building to the northeast. The building has had several renovations; notably, a 2002 renovation to the throughout the 1959 and 1968 buildings.

Sudro Hall is a three-story, 62,725 ft<sup>2</sup> building which primarily serves as office areas and classroom areas for science personnel.

The interior floor finishes included terrazzo, ceramic tile, floor tile, concrete, and carpet; the interior ceiling finishes included plaster, metal, ceiling tile, and gypsum wallboard; and the interior wall finishes included plaster, concrete, gypsum wallboard, concrete block, brick, ceramic block, and ceramic tile. The roofing system is a flat rubber-membrane roof and the exterior of the structure is brick.

The piping systems were insulated; fiberglass insulation (with and without hard fittings), millboard insulation (with hard fittings), and mag block insulation (with hard fittings) are located in the building. Steam and domestic water enter the building via a tunnel into room 31. HVAC systems located in the building consisted of steam radiators and forced air furnaces equipped with heating/cooling coils.

## 2.0 ASBESTOS SURVEY INFORMATION

Sudro Hall was surveyed as part of a larger project on NDSU's Fargo, ND Campus. This report is part of "Volume 5" of a nine volume series. This report includes building specific information only; please refer to the opening section of "Volume 5" for methodologies, definitions, and other pertinent supporting information.

A total of 146 samples were collected from suspect asbestos-containing materials (ACM) from Sudro Hall on June 27, 2007 and an additional 13 samples were collected on April 17, 2008. Laboratory analysis results indicate **23 of these samples tested positive for asbestos.**

### 2.1 Suspect Materials Identified and Sampled

Joint Compound (4 types)	Gypsum Wallboard (4 types)
Floor Tile (7 types)	Floor Tile Mastic (7 types)
Stair Tread Mastic	Carpet Mastic
Baseboard Adhesive (2 types)	Hard Plaster-Skimcoat (3 types)
Hard Plaster-Basecoat (3 types)	Rough Ceiling Texture
Ceiling Tile (4 types)	Pyrobar
Sink Undercoating (3 types)	Floor Filler Material
Wall Texture (2 types)	Green HVAC Canvas Connector
Black Lab Countertop (2 types)	Hard Plaster-Monocoat
Acoustic Ceiling Plaster	Rainleader Bowl Insulation
Mag Block Pipe Insulation	Hard Fitting on Mag Block Insulation
Hard Fitting on Fiberglass Insulation (2 types)	Hard Fitting on Millboard Insulation
Millboard Pipe Insulation	Encapsulant on Fiberglass Insulation
Air Vent Caulk	Penetration Putty (2 types)

Building Seam Caulk (2 types)  
Window Caulk  
Fume Hood

Foundation Coating  
Window Sill Material

The Asbestos Bulk Sample Results Table includes asbestos sampling data.

## 2.2 Asbestos Containing Materials

Rough Ceiling Texture  
Mastic for 12" Tan Floor Tile with Brown Marks  
Black Sink Undercoating  
Unknown Floor Tile and Mastic  
Acoustic Ceiling Plaster  
Hard Fitting on Fiberglass Insulation (1 type)  
Mag Block Pipe Insulation  
Millboard Pipe Insulation  
Hard Fittings on Millboard Insulation  
Air Vent Caulk  
Fume Hood

The ACM Locations/ Friable Materials Assessments Table include ACM locations data.

## 2.3 Cost Estimates

Legend Technical Services Inc. estimates abatement costs (removal & disposal) of ACM for Sudro Hall as follows:

ACM	QUANTITY	UNIT COST	TOTAL COST
Asbestos Hard Fittings on Fiberglass Insulation	84 ea	\$60.00/ea	\$5,040.00
Asbestos Sink Undercoating (all types)	1 ea	\$150.00/ea	\$150.00
Asbestos Floor Tile and/or Mastic (all types)	7,226 ft <sup>2</sup>	\$4.00/ft <sup>2</sup>	\$28,904.00
Asbestos Ceiling Texture	836 ft <sup>2</sup>	\$7.50/ft <sup>2</sup>	\$6,270.00
Asbestos Acoustic Ceiling Plaster	2,615 ft	\$7.50/ft <sup>2</sup>	\$19,612.50
Asbestos Fume Hood	9 ea	\$350.00/ea	\$3,150.00
Asbestos Mag Block Pipe Insulation	98 ft	\$25.00/ft	\$2,450.00
Asbestos Millboard Pipe Insulation	121 ft	\$25.00/ft	\$3,025.00
Asbestos Hard Fitting on Millboard Insulation	1 ea	\$60.00/ea	\$60.00
Asbestos Air Vent Caulk	2 ea	\$125.00/ea	\$250.00
<b>Total Estimated Abatement Costs:</b>			<b>\$68,911.50</b>

## 2.4 Survey Notes

LEGEND identified and sampled hard fittings on fiberglass insulation throughout the 1959 and 1968 buildings. The hard fittings on fiberglass insulation in the 1959 building are ACM and the hard fittings on fiberglass insulation in the 1968 building are non-ACM.

LEGEND sampled an unknown floor tile and mastic below the carpet in rooms 123, 123D, 123E, 123F, 123G, and 123H (samples #102-105); the unknown floor tile and mastic tested positive for asbestos.

LEGEND sampled hard plaster- skimcoat from the west wall in hallway 88 by room 5 (sample #40) and the north wall in room 102 (sample #54); the samples were collected above the ceiling tile at the damaged areas where the ceiling plaster had been removed. Both samples tested positive for asbestos. Available architectural drawings (1959) indicate an acoustic ceiling plaster was used in both locations and available NDSU records indicate an asbestos abatement project had been conducted to remove the acoustic ceiling plaster from both locations; the acoustic ceiling plaster was identified and sampled by LEGEND elsewhere in the building (samples #112 and 113), testing positive for asbestos. LEGEND resampled the hard plaster- skimcoats from the west wall in hallway 88 by room 5 (sample #148), farther down the wall under a circular access panel, and from the north wall in room 102 (sample #152), farther down the wall under an electric outlet cover. Both additional samples tested negative for asbestos. LEGEND considers samples #40 and #54 to be false positives caused by contamination from a residual ACM acoustic ceiling plaster originally used as the ceiling systems in hallway 88 and room 102 in 1959.

**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
SUDRO HALL (BUILDING A052)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. <sup>1</sup>	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	-----------------------------	-------

**Room 1**

9" Floor Tile and Mastic	Assumed	36 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs.
--------------------------	---------	--------------------	------------------------------	------	------	--	------	--

**Room 5** Abated December 2009

9" Floor Tile and Mastic	Assumed	988 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs.
Fume Hood	15% Chrysotile	3 ea	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos fume hoods are along the east wall.

**Room 10**

Millboard Pipe Insulation	20% Chrysotile	10 ft	Friable TSI	Significantly Damaged	Physical Air Erosion Vibration	■□□ ■□□ ■□□	1	The asbestos millboard pipe insulation is in a pipe chase along the west wall.
---------------------------	----------------	-------	----------------	--------------------------	--------------------------------------	-------------------	---	--

**Room 10A**

Air Vent Caulk	3% Chrysotile	1 ea.	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos caulk is around an air vent along the north wall.
----------------	---------------	-------	------------------------------	------	------	--	------	--

**Room 11B**

Hard Fitting on Fiberglass Insulation	0-8% Chrysotile 0-2% Amosite	2 fittings	Friable TSI	Good	Physical Air Erosion Vibration	■□□ ■□□ ■□□	7	The asbestos hard fittings on fiberglass are above ceiling tile on the east end of the room.
---------------------------------------	---------------------------------	------------	----------------	------	--------------------------------------	-------------------	---	--

**Room 17**

Fume Hood	15% Chrysotile	1 ea	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos fume hood is along the south wall.
-----------	----------------	------	------------------------------	------	------	--	------	---

\* = Non-Friable materials were not assessed

**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
SUDRO HALL (BUILDING A052)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. <sup>1</sup>	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

**Room 26A**

Mastic for 12" Tan Floor Tile with Brown Streaks	10% Chrysotile	87 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The mastic contains asbestos; the floor tile is negative.
--	----------------	--------------------	------------------------------	------	------	--	------	---

**Room 31**

Mag Block Pipe Insulation	25% Amosite	49 ft	Friable TSI	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	The asbestos mag block pipe insulation is along the west wall.
---------------------------	-------------	-------	----------------	------	--------------------------------------	---	---	--

**Room 36** Abated February 2020

<del>Hard Fitting on Fiberglass Insulation</del>	0-8% Chrysotile 0-2% Amosite	6 fittings	Friable TSI	Good	Physical Air Erosion Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	7	The asbestos hard fittings on fiberglass are above ceiling tile.
--	---------------------------------	------------	----------------	------	--------------------------------------	---	---	--

**Hallway 88 (includes all hallways in basement and the janitor's closet across from room 35A)**

Hard Fitting on Fiberglass Insulation	0-8% Chrysotile 0-2% Amosite	15 fittings	Friable TSI	Good	Physical Air Erosion Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	7	The asbestos hard fittings on fiberglass are above ceiling tile throughout the hallway that runs from room 35D to room 10.
Millboard Pipe Insulation	20% Chrysotile	12 ft	Friable TSI	Significantly Damaged	Physical Air Erosion Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	1	The asbestos millboard pipe insulation is in a pipe chase across from room 16.

**Room 102**

9" Floor Tile and Mastic	Assumed	138 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs.
--------------------------	---------	---------------------	------------------------------	------	------	--	------	--

**Room 102A**

9" Floor Tile and Mastic	Assumed	152 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs.
--------------------------	---------	---------------------	------------------------------	------	------	--	------	--

\* = Non-Friable materials were not assessed

**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
SUDRO HALL (BUILDING A052)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. <sup>1</sup>	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	-----------------------------	-------

**Room 102A1**

9" Floor Tile and Mastic	Assumed	156 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs.
--------------------------	---------	---------------------	------------------------------	------	------	--	------	--

**Room 103**

9" Floor Tile and Mastic	Assumed	145 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs.
--------------------------	---------	---------------------	------------------------------	------	------	--	------	--

**Room 107**

9" Floor Tile and Mastic	Assumed	1,021 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs.
Fume Hood	15% Chrysotile	2 ea	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos fume hoods are along the east wall.

**Room 108**

Millboard Pipe Insulation	20% Chrysotile	12 ft	Friable TSI	Significantly Damaged	Physical Air Erosion Vibration	■□□ ■□□ ■□□	1	The asbestos millboard pipe insulation is in a pipe chase to the north of the main entry to the room from hallway 188.
---------------------------	----------------	-------	----------------	--------------------------	--------------------------------------	-------------------	---	--

**Room 113**

Hard Fitting on Fiberglass Insulation	0-8% Chrysotile 0-2% Amosite	5 fittings	Friable TSI	Good	Physical Air Erosion Vibration	■□□ ■□□ ■□□	7	The asbestos hard fittings on fiberglass are above the hard plaster ceiling.
---------------------------------------	---------------------------------	------------	----------------	------	--------------------------------------	-------------------	---	--

**Room 114 (pipe chase)**

Hard Fitting on Fiberglass Insulation	0-8% Chrysotile 0-2% Amosite	2 fittings	Friable TSI	Good	Physical Air Erosion Vibration	□■□ ■□□ ■□□	7	The asbestos hard fittings on fiberglass are along the east wall.
---------------------------------------	---------------------------------	------------	----------------	------	--------------------------------------	-------------------	---	---

\* = Non-Friable materials were not assessed

**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
SUDRO HALL (BUILDING A052)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. <sup>1</sup>	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

**Room 116**

9" Floor Tile and Mastic	Assumed	836 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs.
Acoustic Ceiling plaster (with Rough Ceiling Texture)	3-10% Chrysotile	836 ft <sup>2</sup>	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	The rough ceiling texture has been applied to an acoustic ceiling plaster above it; they are both ACM.
Hard Fitting on Fiberglass Insulation	0-8% Chrysotile 0-2% Amosite	6 fittings	Friable TSI	Good	Physical Air Erosion Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	7	The asbestos hard fittings on fiberglass are above the acoustic ceiling plaster ceiling.
Fume Hood	15% Chrysotile	2 ea	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos fume hoods are in the center of the room.

**Room 120** Abated Oct 2015

<del>Mastic for 12" Tan Floor Tile with Brown Streaks</del>	10% Chrysotile	110 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The mastic contains asbestos; the floor tile is negative.
---	----------------	---------------------	------------------------------	------	------	--	------	---

**Room 121**

Mag Block Pipe Insulation	25% Amosite	49 ft	Friable TSI	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	6	The asbestos mag block pipe insulation is throughout the room.
~10 ft abated on west air handler steam line (coil replaced) January 2009								

**Room 123** Abated February 2011: Tile remains throughout suite underneath existing walls.

<del>Unknown Floor Tile and Mastic</del>	2-5% Chrysotile	647 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The unknown floor tile and mastic contain asbestos; they are under the carpet.
--	-----------------	---------------------	------------------------------	------	------	--	------	--

\* = Non-Friable materials were not assessed

**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
SUDRO HALL (BUILDING A052)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. <sup>1</sup>	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

**Room 123A** Room # Chg to 122 May 2009 Abated February 2011

<del>Mastic for 12" Tan Floor Tile with Brown Streaks</del>	10% Chrysotile	105 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The mastic contains asbestos; the floor tile is negative (under carpet).
---	----------------	---------------------	------------------------------	------	------	--	------	--

**Room 123B**

Mastic for 12" Tan Floor Tile with Brown Streaks	10% Chrysotile	93 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The mastic contains asbestos; the floor tile is negative.
Black Sink Undercoating	10% Chrysotile	1 sink	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos undercoating is on a sink along the northwest corner of room 123B.

**Room 123C**

Mastic for 12" Tan Floor Tile with Brown Streaks	10% Chrysotile	143 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The mastic contains asbestos; the floor tile is negative.
--	----------------	---------------------	------------------------------	------	------	--	------	---

**Room 123D** Abated February 2011

<del>Unknown Floor Tile and Mastic</del>	2-5% Chrysotile	260 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The unknown floor tile and mastic contain asbestos; they are under the carpet.
--	-----------------	---------------------	------------------------------	------	------	--	------	--

**Room 123E** Abated February 2011

<del>Unknown Floor Tile and Mastic</del>	2-5% Chrysotile	254 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The unknown floor tile and mastic contain asbestos; they are under the carpet.
--	-----------------	---------------------	------------------------------	------	------	--	------	--

**Room 123F** Abated February 2011

<del>Unknown Floor Tile and Mastic</del>	2-5% Chrysotile	345 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The unknown floor tile and mastic contain asbestos; they are under the carpet.
--	-----------------	---------------------	------------------------------	------	------	--	------	--

\* = Non-Friable materials were not assessed



**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
SUDRO HALL (BUILDING A052)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. <sup>1</sup>	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

**Room 123G** Abated February 2011

<del>Unknown Floor Tile and Mastic</del>	2-5% Chrysotile	324 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The unknown floor tile and mastic contain asbestos; they are under the carpet.
--	-----------------	---------------------	------------------------------	------	------	--	------	--

**Room 123H** Abated February 2011

<del>Unknown Floor Tile and Mastic</del>	2-5% Chrysotile	194 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The unknown floor tile and mastic contain asbestos; they are under the carpet.
--	-----------------	---------------------	------------------------------	------	------	--	------	--

**Room 128**

Mastic for 12" Tan Floor Tile with Brown Streaks	10% Chrysotile	110 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The mastic contains asbestos; the floor tile is negative.
--	----------------	---------------------	------------------------------	------	------	--	------	---

**Room 129**

Mastic for 12" Tan Floor Tile with Brown Streaks	10% Chrysotile	109 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The mastic contains asbestos; the floor tile is negative.
--	----------------	---------------------	------------------------------	------	------	--	------	---

**Room 130**

Mastic for 12" Tan Floor Tile with Brown Streaks	10% Chrysotile	109 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The mastic contains asbestos; the floor tile is negative.
--	----------------	---------------------	------------------------------	------	------	--	------	---

**Room 135** And now incl. room 133 Abated February 2020

<del>Hard Fitting on Fiberglass insulation</del>	0-8% Chrysotile 0-2% Amosite	21 fittings	Friable TSI	Good	Physical Air Erosion Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	7	The asbestos hard fittings on fiberglass are above ceiling tile in the east end of the room.
--	---------------------------------	-------------	----------------	------	--------------------------------------	---	---	--

\* = Non-Friable materials were not assessed

**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
SUDRO HALL (BUILDING A052)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. <sup>1</sup>	NOTES
<del>Millboard Pipe Insulation</del>	20% Chrysotile	52 ft	Friable TSI	Good	Physical Air Erosion Vibration	■□□ ■□□ ■□□	7	The asbestos millboard pipe insulation is above ceiling tile in the east end of the room.
<del>Hard Fittings on Millboard Insulation</del>	10% Amosite	6 fittings	Friable TSI	Good	Physical Air Erosion Vibration	■□□ ■□□ ■□□	7	None

**Room 136**

Hard Fitting on Fiberglass Insulation	0-8% Chrysotile 0-2% Amosite	10 fittings	Friable TSI	Good	Physical Air Erosion Vibration	■□□ ■□□ ■□□	7	The asbestos hard fittings on fiberglass are above ceiling tile in the middle of the room.
--	---------------------------------	-------------	----------------	------	--------------------------------------	-------------------	---	--

**Room 136A** Now with Room 136

Hard Fitting on Fiberglass Insulation	0-8% Chrysotile 0-2% Amosite	9 fittings	Friable TSI	Good	Physical Air Erosion Vibration	■□□ ■□□ ■□□	7	The asbestos hard fittings on fiberglass are above ceiling tile in the east end of the room.
--	---------------------------------	------------	----------------	------	--------------------------------------	-------------------	---	--

**Room 136B**

Hard Fitting on Fiberglass Insulation	0-8% Chrysotile 0-2% Amosite	2 fittings	Friable TSI	Good	Physical Air Erosion Vibration	■□□ ■□□ ■□□	7	The asbestos hard fittings on fiberglass are above ceiling tile in southwest corner of the room.
--	---------------------------------	------------	----------------	------	--------------------------------------	-------------------	---	--

**Room 136D** Abated June 2014

<del>9" Floor Tile and Mastic</del>	Assumed	12 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed ACMs.
---	---------	--------------------	------------------------------	------	------	------	------	--

**Hallway 188 (includes all hallways on 1<sup>st</sup> floor)**

Millboard Pipe Insulation	20% Chrysotile	12 ft	Friable TSI	Significantly Damaged	Physical Air Erosion Vibration	■□□ ■□□ ■□□	1	The asbestos millboard pipe insulation is in a pipe chase across from room 116.
------------------------------	----------------	-------	----------------	--------------------------	--------------------------------------	-------------------	---	---

\* = Non-Friable materials were not assessed

**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
SUDRO HALL (BUILDING A052)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. <sup>1</sup>	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

**Hallway 207A**

Millboard Pipe Insulation	20% Chrysotile	23 ft	Friable TSI	Significantly Damaged	Physical Air Erosion Vibration	■□□ ■□□ ■□□	1	Refer to the ACM Locations Map for further information.
Hard Fitting on Millboard Insulation	10% Amosite	1 fitting	Friable TSI	Good	Physical Air Erosion Vibration	■□□ ■□□ ■□□	7	None

**Room 218**

Fume Hood	15% Chrysotile	1 ea	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The asbestos fume hood is along the south wall.
-----------	----------------	------	---------------------------	------	------	------	------	---

**Room 222**

Acoustic Ceiling Plaster	3-10% Chrysotile	229 ft <sup>2</sup>	Friable Surfacing	Good	Physical Air Erosion Vibration	■□□ ■□□ ■□□	7	The asbestos acoustic ceiling plaster is above ceiling tile and only on the west end of the room.
--------------------------	------------------	---------------------	-------------------	------	--------------------------------------	-------------------	---	---

**Room 222H**

Acoustic Ceiling Plaster	3-10% Chrysotile	135 ft <sup>2</sup>	Friable Surfacing	Good	Physical Air Erosion Vibration	■□□ ■□□ ■□□	7	The asbestos acoustic ceiling plaster is above the ceiling tile.
--------------------------	------------------	---------------------	-------------------	------	--------------------------------------	-------------------	---	--

**Room 222J**

Acoustic Ceiling Plaster	3-10% Chrysotile	173 ft <sup>2</sup>	Friable Surfacing	Good	Physical Air Erosion Vibration	■□□ ■□□ ■□□	7	The asbestos acoustic ceiling plaster is above the ceiling tile.
--------------------------	------------------	---------------------	-------------------	------	--------------------------------------	-------------------	---	--

**Room 222K**

Acoustic Ceiling Plaster	3-10% Chrysotile	122 ft <sup>2</sup>	Friable Surfacing	Good	Physical Air Erosion Vibration	■□□ ■□□ ■□□	7	The asbestos acoustic ceiling plaster is above the ceiling tile.
--------------------------	------------------	---------------------	-------------------	------	--------------------------------------	-------------------	---	--

\* = Non-Friable materials were not assessed

**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
SUDRO HALL (BUILDING A052)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. <sup>1</sup>	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	-----------------------------	-------

**Room 222L**

Acoustic Ceiling Plaster	3-10% Chrysotile	173 ft <sup>2</sup>	Friable Surfacing	Good	Physical Air Erosion Vibration	■□□ ■□□ ■□□	6	The asbestos acoustic ceiling plaster is above the ceiling tile.
--------------------------	------------------	---------------------	-------------------	------	--------------------------------------	-------------------	---	--

**Room 222M**

Acoustic Ceiling Plaster	3-10% Chrysotile	148 ft <sup>2</sup>	Friable Surfacing	Good	Physical Air Erosion Vibration	■□□ ■□□ ■□□	6	The asbestos acoustic ceiling plaster is above the ceiling tile.
--------------------------	------------------	---------------------	-------------------	------	--------------------------------------	-------------------	---	--

**West Stairway (basement-2<sup>nd</sup> floor)**

9" Floor Tile and Mastic	Assumed	777 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs.
Acoustic Ceiling Plaster	3-10% Chrysotile	537 ft <sup>2</sup>	Friable Surfacing	Good	Physical Air Erosion Vibration	■□□ ■□□ ■□□	6	The asbestos acoustic ceiling plaster is on the 2 <sup>nd</sup> floor level and between the basement and 1 <sup>st</sup> floor levels.

**Northeast Stairway (basement-2<sup>nd</sup> floor)**

9" Floor Tile and Mastic	Assumed	165 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed ACMs.
Acoustic Ceiling Plaster	3-10% Chrysotile	262 ft <sup>2</sup>	Friable Surfacing	Good	Physical Air Erosion Vibration	■□□ ■□□ ■□□	6	The asbestos acoustic ceiling plaster is on the 2nd floor level.

**Exterior**

Air Vent Caulk	3% Chrysotile	1 ea.	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos air vent caulk is along the north exterior wall by room 10A.
----------------	---------------	-------	---------------------------	------	------	--	------	---

\* = Non-Friable materials were not assessed

**LEGEND TECHNICAL SERVICES, INC.**  
 ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
 SUDRO HALL (BUILDING A052)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. <sup>1</sup>	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

<sup>1</sup>Assessment Categories:

- |  |   |
|--|---|
| 1) Damaged or Significantly Damaged TSI ACM<br>2) Damaged Friable Surfacing ACM<br>3) Significantly Damaged Friable Surfacing ACM<br>4) Damaged or Significantly Damaged Friable Miscellaneous ACM | 5) ACM with Potential for Damage<br>6) ACM with Potential for Significant Damage<br>7) Any Remaining Friable ACM or Friable Suspected ACM |
|--|---|

**End**