

NARRATIVE REPORT

1.0 BUILDING INFORMATION

Walster Hall was originally constructed in 1959; the building has had no major renovations.

Walster Hall is a three-story, 48,356 ft² building which primarily serves as office areas and classroom areas for science personnel. Loftsgard Hall (A078) is attached via a skyway to the south side of Walster Hall and is reported separately; the skyway is reported with Loftsgard Hall (A078).

The interior floor finishes included floor tile, concrete, carpet, and terrazzo; the interior ceiling finishes included ceiling tile, concrete, plaster, and gypsum wallboard; and the interior wall finishes included concrete block, plaster, ceramic block, gypsum wallboard, brick, wood, and ceramic tile. The roofing system is a flat rubber-membrane roof and the exterior of the structure is brick.

The piping systems were insulated; fiberglass insulation (with and without hard fittings) and neoprene insulation are located in the building. Steam and domestic water enter the building via a tunnel into room 28. HVAC systems located in the building consisted of steam radiators and forced air furnaces equipped with heating/cooling coils.

2.0 ASBESTOS SURVEY INFORMATION

Walster Hall was surveyed as part of a larger project on NDSU's Fargo, ND Campus. This report is part of "Volume 5" of a nine volume series. This report includes building specific information only; please refer to the opening section of "Volume 5" for methodologies, definitions, and other pertinent supporting information.

A total of 75 samples were collected from suspect asbestos-containing materials (ACM) from Walster Hall on August 1, 2007 and an additional 26 samples were collected on April 3, 2008. Laboratory analysis results indicate **45 of these samples tested positive for asbestos.**

2.1 Suspect Materials Identified and Sampled

Rough Ceiling Texture	Ceiling Tile (4 types)
Hard Plaster-Skimcoat	Hard Plaster-Basecoat
Sink Undercoating (11 types)	Floor Tile (2 types)
Floor Tile Mastic (2 types)	Carpet Mastic (2 types)
Baseboard Adhesive	Foam Insulation Panel Adhesive
Red HVAC Duct Caulk	Penetration Putty
Transite Fume Exhaust Pipe	Transite Fume Hood Exhaust Caulk
Black Lab Countertop (8 types)	Rough Ceiling Texture Over-Spray
Encapsulant on Fiberglass Insulation	Hard Fitting on Fiberglass Insulation
Hard Pack on Fiberglass Insulation	Joint Compound
Gypsum Wallboard	Exterior Building Seam Caulk
Fume Hood (3 types)	Window Glazing
Exterior Panel Glazing	Exterior Window Glazing
Exterior Window Caulk (2 types)	Concrete Deck Filler

The Asbestos Bulk Sample Results Table includes asbestos sampling data.

2.2 **Asbestos Containing Materials**

- Rough Ceiling Texture
- Black Sink Undercoating (4 types)
- Mastic for 12" Off-White Floor Tile with Blue/Gray Marks
- Carpet Mastic (with residual black mastic)
- Foam Insulation Panel Adhesive
- Red HVAC Duct Caulk
- Transite Fume Hood Exhaust Pipe
- Transite Fume Hood Exhaust Caulk
- Rough Ceiling Texture Over-Spray
- Hard Fitting on Fiberglass Insulation
- Hard Pack on Fiberglass Insulation
- Fume Hood (3 types)
- Gray Sink Undercoating
- Black Lab Countertop (5 types)
- Interior Window Glazing
- Exterior Window Glazing
- Exterior Panel Glazing

The ACM Locations/ Friable Materials Assessments Table include ACM locations data.

2.3 **Cost Estimates**

Legend Technical Services Inc. estimates abatement costs (removal & disposal) of ACM for Walster Hall as follows:

ACM	QUANTITY	UNIT COST	TOTAL COST
Asbestos Hard Fittings on Fiberglass Insulation	363 ea	\$60.00/ea	\$21,780.00
Asbestos Hard Pack on Fiberglass Insulation	10 ea	\$60.00/ea	\$600.00
Asbestos Sink Undercoating (all types)	12 ea	\$150.00/ea	\$1,800.00
Asbestos Window/Panel Glazing (all types)	126 ea	\$225.00/ea	\$28,350.00
Asbestos Floor Tile and/or Mastic (all types)	36,482 ft ²	\$4.00/ft ²	\$145,928.00
Asbestos Black Lab Countertop (all types)	11 ea	\$350.00/ea	\$3,850.00
Asbestos Red HVAC Caulk	264 ea	\$60.00/ea	\$15,840.00
Asbestos Carpet Mastic	779 ft ²	\$4.00/ft ²	\$3,116.00
Asbestos Rough Ceiling Texture	29,014 ft ²	\$7.50/ft ²	\$217,605.00
Asbestos Rough Ceiling Texture Over-Spray	1,944 ft	\$25.00/ft	\$48,600.00
Asbestos Foam Wall Panel Adhesive	2,240 ft ²	\$7.50/ft ²	\$16,800.00
Asbestos Fume Hood (all types)	14 ea	\$350.00/ea	\$4,900.00
Asbestos Transite Fume Exhaust Pipe and Caulk	420 ft	\$25.00/ft	\$10,500.00
Total Estimated Abatement Costs:			\$519,669.00

2.4 **Survey Notes**

LEGEND was able to visually quantify hard fittings on fiberglass insulation throughout the majority of the building on steam and domestic water pipes. However, on floors 1-3 a few inaccessible ceilings and pipe chases prevented LEGEND from verifying the presence of possible additional hard fittings. LEGEND assumes additional hard fittings will be discovered during renovation or demolition activities on the water pipes supplying the custodial rooms and bathrooms. LEGEND recommends assuming an additional 25-50 hard fittings on fiberglass insulation on each of the 1st, 2nd, and 3rd floors.

LEGEND identified and collected samples from Red HVAC Duct Caulk in Walster Hall; it tested positive for asbestos. LEGEND visually quantified the Red HVAC Duct Caulk above the ceiling tile in the hallways on 1st, 2nd, and 3rd floors and in rooms 128 and 128A. LEGEND noted 2 large chases immediately to the south of the northwest and northeast stairways; according to available architectural drawing these chases conceal additional ducts. In addition, the ducts enter several rooms in an inaccessible soffit. LEGEND assumes additional Red HVAC Duct Caulk will be discovered during renovation or demolition activities in these areas. LEGEND recommends assuming an additional 10-25 duct seams with Red HVAC Duct Caulk on each of the 1st, 2nd, and 3rd floors.

LEGEND identified and collected samples from 8 separate types (homogeneous areas) of black lab countertops, 11 separate types (homogeneous areas) of sink undercoatings, and 3 separate types (homogeneous areas) of fume hoods in Walster Hall. 5 types of black lab countertop, 5 types of sink undercoatings, and 3 types of fume hoods tested positive for asbestos; black lab countertops, sink undercoatings, and fume hoods in these homogeneous areas are identified as ACM on the ACM locations tables and diagrams. 3 types of black lab countertop, 6 types of sink undercoatings, and 0 types of fume hoods tested negative for asbestos; black lab countertops, sink undercoatings, and fume hoods in these homogeneous areas are non-ACM and are not identified on the ACM location tables and diagrams.

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	-----------------------------	-------

Room 101 and 101A Abated August 2011

Rough Ceiling Texture	15% Chrysotile	245 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	245 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs; they are under the carpet.

Room 102

Rough Ceiling Texture	15% Chrysotile	280 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		

Room 103 Abated October 2022

Rough Ceiling Texture	15% Chrysotile	248 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		

Room 104

Rough Ceiling Texture	15% Chrysotile	135 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Window Glazing	Assumed	1 window	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos glazing is on a window by the south room entrance.

Room 104B

Rough Ceiling Texture	15% Chrysotile	147 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 105

Rough Ceiling Texture	15% Chrysotile	109 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	109 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs; they are under the carpet.

Room 106

Rough Ceiling Texture	15% Chrysotile	406 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		

Room 107

Rough Ceiling Texture	15% Chrysotile	116 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	116 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 108

Rough Ceiling Texture	15% Chrysotile	213 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	213 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 109

Rough Ceiling Texture Over-Spray (on pipes)	3% Chrysotile	80 ft	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	The asbestos over-spray is on pipes along the ceiling.
Hard Fittings on Fiberglass Insulation	0-30% Chrysotile 0-15% Amosite	2 fittings	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	The asbestos hard fittings on fiberglass pipe insulation are along the ceiling in the middle of the room.
Rough Ceiling Texture	15% Chrysotile	398 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	None
9" Floor Tile and Mastic	Assumed	398 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.
Transite Fume Hood Exhaust Pipe and Caulk	15-30% Chrysotile 30% Crocidolite	5 ft	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos transite fume hood exhaust pipe is protruding from a chase in the northeast corner of the room; the black caulk on the pipe is ACM.
Fume Hood	10-15% Chrysotile	1 ea	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos transite fume hood is along the north wall.

Room 111A

Rough Ceiling Texture Over-Spray (on pipes)	3% Chrysotile	90 ft	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	The asbestos over-spray is on pipes along the ceiling.
Hard Fittings on Fiberglass Insulation	0-30% Chrysotile 0-15% Amosite	2 fittings	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	The asbestos hard fittings on fiberglass pipe insulation are along the ceiling in the middle of the room.
Rough Ceiling Texture	15% Chrysotile	742 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	None

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
9" Floor Tile and Mastic	Assumed	742 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.
Transite Fume Hood Exhaust Pipe and Caulk	15-30% Chrysotile 30% Crocidolite	5 ft	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos transite fume hood exhaust pipe is protruding from a chase in the southeast corner of the room; the black caulk on the pipe is ACM.
Fume Hood	10-15% Chrysotile	1 ea	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos transite fume hood is along the south wall.

Room 111B

Rough Ceiling Texture Over-Spray (on pipes)	3% Chrysotile	124 ft	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	The asbestos over-spray is on pipes along the ceiling.
Hard Fittings on Fiberglass Insulation	0-30% Chrysotile 0-15% Amosite	2 fittings	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	The asbestos hard fittings on fiberglass pipe insulation are along the ceiling in the middle of the room.
Rough Ceiling Texture	15% Chrysotile	588 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	None
Mastic for 12" Off-White Floor Tile with Gray Marks	15% Chrysotile	588 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The mastic contains asbestos; the floor tile is negative.
Transite Fume Hood Exhaust Pipe and Caulk	15-30% Chrysotile 30% Crocidolite	10 ft	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos transite fume hood exhaust pipe is protruding from a chase in the southeast corner of the room; the black caulk on the pipe is ACM.
Gray Sink Undercoating	3% Chrysotile	4 sinks	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	Refer to the ACM Locations Map for further information.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 111C

Rough Ceiling Texture	15% Chrysotile	130 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	130 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.
Fume Hood	10-15% Chrysotile	1 ea	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos transite fume hood is along the north wall.

Room 112

Rough Ceiling Texture	15% Chrysotile	41 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	41 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 113

Rough Ceiling Texture	15% Chrysotile	198 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	198 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.
Transite Fume Hood Exhaust Pipe and Caulk	15-30% Chrysotile 30% Crocidolite	5 ft	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos transite fume hood exhaust pipe is protruding from a chase in the northeast corner of the room; the black caulk on the pipe is ACM.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	-----------------------------	-------

Room 114 and 114A Abated October 2022

Rough Ceiling Texture	15% Chrysotile	248 ft ²	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>		6	None
					Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>			
					Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>			
9" Floor Tile and Mastic	Assumed	248 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 115

Rough Ceiling Texture	15% Chrysotile	406 ft ²	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>		6	None
					Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>			
					Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>			
9" Floor Tile and Mastic	Assumed	406 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.
Black Sink Undercoating	3-10% Chrysotile	1 sink	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos undercoating is on a sink in the center of the room.
Transite Fume Hood Exhaust Pipe and Caulk	15-30% Chrysotile 30% Crocidolite	10 ft	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos transite fume hood exhaust pipe is protruding from a chase in the southeast corner of the room; the black caulk on the pipe is ACM.
Fume Hood	10-15% Chrysotile	1 ea	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos transite fume hood is along the east wall.
Black Lab Countertop	5-10% Chrysotile	1 ea	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos black lab countertop is under the fume hood along the east wall.

Room 116

Rough Ceiling Texture	15% Chrysotile	166 ft ²	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>		6	None
					Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>			
					Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>			

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

9" Floor Tile and Mastic	Assumed	166 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.
--------------------------	---------	---------------------	------------------------------	------	------	--	------	--

Room 117

9" Floor Tile and Mastic	Assumed	310 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.
--------------------------	---------	---------------------	------------------------------	------	------	--	------	--

Black Lab Countertop	5-10% Chrysotile	2 ea	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos black lab countertops are along the north and south walls.
----------------------	------------------	------	------------------------------	------	------	--	------	---

Room 118

Rough Ceiling Texture	15% Chrysotile	78 ft ²	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>		6	None
-----------------------	----------------	--------------------	----------------------	------	--	--	---	------

9" Floor Tile and Mastic	Assumed	78 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs; they are under the carpet.
--------------------------	---------	--------------------	------------------------------	------	------	--	------	---

Room 119

9" Floor Tile and Mastic	Assumed	83 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.
--------------------------	---------	--------------------	------------------------------	------	------	--	------	--

Room 121

9" Floor Tile and Mastic	Assumed	83 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.
--------------------------	---------	--------------------	------------------------------	------	------	--	------	--

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	-----------------------------	-------

Room 123

Rough Ceiling Texture	15% Chrysotile	125 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	125 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 125

Rough Ceiling Texture	15% Chrysotile	125 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	125 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 127

Rough Ceiling Texture	15% Chrysotile	125 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	125 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 128

Red HVAC Duct Caulk	10% Chrysotile	5 ea	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The asbestos red HVAC duct caulk is on air ducts on the west and east sides of room 128.
Hard Fittings on Fiberglass Insulation	0-30% Chrysotile 0-15% Amosite	5 fittings	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	The asbestos hard fittings on fiberglass pipe insulation are on the west end of room 128.
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
Hard Pack on Fiberglass Insulation	0-30% Chrysotile 0-5% Amosite	3 ea	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	The asbestos hard pack on fiberglass insulation is on the west end of room 128.

Room 128A

Red HVAC Duct Caulk	10% Chrysotile	4 ea	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	The asbestos red HVAC duct caulk is on air ducts on the west and east sides of room 128A.
---------------------	----------------	------	------------------------------	------	------	------	---

Room 129

Rough Ceiling Texture	15% Chrysotile	125 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	None
9" Floor Tile and Mastic	Assumed	125 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs.	

Room 131

Rough Ceiling Texture	15% Chrysotile	125 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	None
9" Floor Tile and Mastic	Assumed	125 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs.	

Room 132

Rough Ceiling Texture	15% Chrysotile	81 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	None
9" Floor Tile and Mastic	Assumed	81 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs.	

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	-----------------------------	-------

Room 133

Rough Ceiling Texture	15% Chrysotile	125 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	125 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 134

Rough Ceiling Texture	15% Chrysotile	78 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	78 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 135

Rough Ceiling Texture	15% Chrysotile	403 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	403 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs.
Black Sink Undercoating	3-10% Chrysotile	1 sink	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The asbestos undercoating is on a sink in the middle of the room.
Transite Fume Hood Exhaust Pipe and Caulk	15-30% Chrysotile 30% Crocidolite	5 ft	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The asbestos transite fume hood exhaust pipe is protruding from a chase in the southwest corner of the room; the black caulk on the pipe is ACM.
Rough Ceiling Texture Over-Spray (on pipes)	3% Chrysotile	39 ft	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	The asbestos over-spray is on pipes along the ceiling.
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
Hard Fittings on Fiberglass Insulation	0-30% Chrysotile 0-15% Amosite	4 fittings	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	The asbestos hard fittings on fiberglass pipe insulation are along the ceiling in the middle of the room.
Fume Hood	10-15% Chrysotile	1 ea	Non-Friable Miscellaneous	N/A*	N/A*	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	N/A*	The asbestos transite fume hood is along the south wall.
Black Lab Countertop	5-10% Chrysotile	1 ea	Non-Friable Miscellaneous	N/A*	N/A*	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	N/A*	The asbestos black lab countertop is under the fume hood along the south wall.

Room 136

Rough Ceiling Texture	15% Chrysotile	79 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
9" Floor Tile and Mastic	Assumed	79 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 137

Rough Ceiling Texture Abated April 2009	15% Chrysotile	397 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
9" Floor Tile and Mastic Abated April 2009	Assumed	397 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	N/A*	The 9" floor tile and mastic are assumed to be ACMs.
Black Sink Undercoating Abated April 2009	3-10% Chrysotile	1 sink	Non-Friable Miscellaneous	N/A*	N/A*	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	N/A*	The asbestos undercoating is on a sink along the north wall.
Transite Fume Hood Exhaust Pipe and Caulk Abated April 2009	15-30% Chrysotile 30% Crocidolite	15 ft	Non-Friable Miscellaneous	N/A*	N/A*	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	N/A*	The asbestos transite fume hood exhaust pipe is protruding from a chase in the northwest corner of the room; the black caulk on the pipe is ACM.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
Rough Ceiling Texture Over-Spray (on pipes)	3% Chrysotile	4 ft	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	The asbestos over-spray is on pipes along the south ceiling.
Fume Hood Abated April 2009	10-15% Chrysotile	1 ea	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos transite fume hood is along the north wall and has an unattached transite panel that sits below the fume hood.

Room 138

Rough Ceiling Texture	15% Chrysotile	126 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	None
9" Floor Tile and Mastic	Assumed	126 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 139

Rough Ceiling Texture	15% Chrysotile	397 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	None
9" Floor Tile and Mastic	Assumed	397 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.
Black Sink Undercoating	3-10% Chrysotile	1 sink	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos undercoating is on a sink in the center of the room.
Transite Fume Hood Exhaust Pipe and Caulk	15-30% Chrysotile 30% Crocidolite	15 ft	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos transite fume hood exhaust pipe is protruding from a chase in the southwest corner of the room; the black caulk on the pipe is ACM.
Rough Ceiling Texture Over-Spray (on pipes)	3% Chrysotile	119 ft	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	The asbestos over-spray is on pipes along the ceiling.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
Hard Fittings on Fiberglass Insulation	0-30% Chrysotile 0-15% Amosite	10 fittings	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	The asbestos hard fittings on fiberglass pipe insulation are along the ceiling in the middle and east end of the room.
Fume Hood	10-15% Chrysotile	2 ea	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos transite fume hoods are along on the west end of room 139 and have unattached transite panels that sit below each fume hood.

Room 140

Rough Ceiling Texture	15% Chrysotile	126 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	None
9" Floor Tile and Mastic	Assumed	126 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 143

Rough Ceiling Texture Abated April 2009	15% Chrysotile	651 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	None
9" Floor Tile and Mastic Abated April 2009	Assumed	651 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.
Transite Fume Hood Exhaust Pipe and Caulk Abated April 2009	15-30% Chrysotile 30% Crocidolite	5 ft	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos transite fume hood exhaust pipe is protruding from a chase in the southwest corner of the room; the black caulk on the pipe is ACM.
Rough Ceiling Texture Over-Spray (on pipes)	3% Chrysotile	160 ft	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	The asbestos over-spray is on pipes along the ceiling.
Fume Hood Abated April 2009	10-15% Chrysotile	1 ea	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos transite fume hood is along the south wall and has an unattached transite panel that sits below the fume hood.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	-----------------------------	-------

Room 145

Rough Ceiling Texture	15% Chrysotile	402 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
9" Floor Tile and Mastic	Assumed	402 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	N/A*	The 9" floor tile and mastic are assumed to be ACMs.
Transite Fume Hood Exhaust Pipe and Caulk	15-30% Chrysotile 30% Crocidolite	5 ft	Non-Friable Miscellaneous	N/A*	N/A*	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	N/A*	The asbestos transite fume hood exhaust pipe is protruding from a chase in the northwest corner of the room; the black caulk on the pipe is ACM.
Rough Ceiling Texture Over-Spray (on pipes)	3% Chrysotile	90 ft	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	The asbestos over-spray is on pipes along the ceiling.
Hard Fittings on Fiberglass Insulation	0-30% Chrysotile 0-15% Amosite	2 fittings	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	The asbestos hard fittings on fiberglass pipe insulation are along the ceiling in the middle of the room.
Black Sink Undercoating	3-10% Chrysotile	1 sink	Non-Friable Miscellaneous	N/A*	N/A*	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	N/A*	The asbestos undercoating is on a sink along the north wall.

Room 147

Rough Ceiling Texture	15% Chrysotile	125 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
9" Floor Tile and Mastic	Assumed	125 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 149

Rough Ceiling Texture	15% Chrysotile	125 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
-----------------------	----------------	---------------------	----------------------	------	----------	---	---	------

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
9" Floor Tile and Mastic	Assumed	125 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Hallway 188

9" Floor Tile and Mastic	Assumed	2,716 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.
Hard Fittings on Fiberglass Insulation	0-30% Chrysotile 0-15% Amosite	15 fittings	Friable Surfacing	Good	Physical Air Erosion Vibration	■□□ ■□□ ■□□	7	Please refer to ACM locations for further information.
Hard Pack on Fiberglass Insulation	0-30% Chrysotile 0-5% Amosite	7 ea	Friable Surfacing	Good	Physical Air Erosion Vibration	■□□ ■□□ ■□□	7	Please refer to ACM locations for further information.
Red HVAC Duct Caulk	10% Chrysotile	85 ea	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos red HVAC duct caulk is above ceiling tile throughout the hallways.

Room 188A

Hard Fittings on Fiberglass Insulation	0-30% Chrysotile 0-15% Amosite	10 fittings	Friable Surfacing	Good	Physical Air Erosion Vibration	□■□ ■□□ ■□□	5	The asbestos hard fittings on fiberglass pipe insulation throughout the pipe chase.
---	-----------------------------------	-------------	----------------------	------	--------------------------------------	-------------------	---	---

Room 199M

Mastic for 12" Off- White Floor Tile with Gray Marks	15% Chrysotile	105 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The mastic contains asbestos; the floor tile is negative.
--	----------------	---------------------	------------------------------	------	------	--	------	---

Room 199W

9" Floor Tile and Mastic	Assumed	81 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.
--------------------------	---------	--------------------	------------------------------	------	------	--	------	--

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 200 Now Room 202 Abated July 2014

9" Floor Tile and Mastic	Assumed	403 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs; they are under the carpet.
-------------------------------------	---------	---------------------	------------------------------	------	------	--	------	---

Room 201

Rough Ceiling Texture	15% Chrysotile	120 ft ²	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>		6	None
					Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>			
					Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>			
9" Floor Tile and Mastic	Assumed	120 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 202 Now Room 202B

Rough Ceiling Texture	15% Chrysotile	218 ft ²	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>		6	None
					Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>			
					Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>			
9" Floor Tile and Mastic	Assumed	218 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs; they are under the carpet.
Window Glazing	5% Chrysotile	2 windows	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos glazing is on the two south windows in room 202.

Room 203

Rough Ceiling Texture	15% Chrysotile	120 ft ²	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>		6	None
					Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>			
					Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>			
9" Floor Tile and Mastic	Assumed	120 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 204

Rough Ceiling Texture	15% Chrysotile	617 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	617 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs; they are under the carpet.

Room 205

Rough Ceiling Texture	15% Chrysotile	122 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	122 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.
Window Glazing	5% Chrysotile	1 window	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos glazing is on the north interior window by the room entrance.

Room 207

Rough Ceiling Texture	15% Chrysotile	120 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	120 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 208

Rough Ceiling Texture	15% Chrysotile	125 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
9" Floor Tile and Mastic	Assumed	125 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 209

Rough Ceiling Texture	15% Chrysotile	120 ft ²	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>		6	None
9" Floor Tile and Mastic	Assumed	120 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 210

Rough Ceiling Texture	15% Chrysotile	125 ft ²	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>		6	None
9" Floor Tile and Mastic	Assumed	125 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 212

Rough Ceiling Texture	15% Chrysotile	119 ft ²	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>		6	None
9" Floor Tile and Mastic	Assumed	119 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 213 Abated July 2022

Rough Ceiling Texture	15% Chrysotile	398 ft ²	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>		6	None
-----------------------	----------------	---------------------	----------------------	------	--	--	---	------

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
9" Floor Tile and Mastic	Assumed	398 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.
Transite Fume Hood Exhaust Pipe and Caulk	15-30% Chrysotile 30% Crocidolite	15 ft	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos transite fume hood exhaust pipe is protruding from a chase in the northeast corner of the room; the black caulk on the pipe is ACM.
Rough Ceiling Texture Over-Spray (on pipes)	3% Chrysotile	111 ft	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	The asbestos over-spray is on pipes along the ceiling.
Hard Fittings on Fiberglass Insulation	0-30% Chrysotile 0-15% Amosite	2 fittings	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	The asbestos hard fittings on fiberglass pipe insulation are along the ceiling in the middle of the room.
Fume Hood	10-15% Chrysotile	1 ea	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos transite fume hood is along the north wall.
Black Sink Undercoating	3-10% Chrysotile	1 sink	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos undercoating is on a sink in the center of the room.

Room 213A Abated July 2022 Now part of 215

Rough Ceiling Texture	15% Chrysotile	191 ft ²	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	None
9" Floor Tile and Mastic	Assumed	191 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.
Transite Fume Hood Exhaust Pipe and Caulk	15-30% Chrysotile 30% Crocidolite	15 ft	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos transite fume hood exhaust pipe is protruding from a chase in the southeast corner of the room; the black caulk on the pipe is ACM.
Rough Ceiling Texture Over-Spray (on pipes)	3% Chrysotile	70 ft	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	The asbestos over-spray is on pipes along the ceiling.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	-----------------------------	-------

Room 214

Rough Ceiling Texture	15% Chrysotile	127 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	127 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 215 Abated July 2022

Rough Ceiling Texture	15% Chrysotile	220 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	220 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs.
Rough Ceiling Texture Over-Spray (on pipes)	3% Chrysotile	60 ft	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	The asbestos over-spray is on pipes along the ceiling.
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		

Room 217

Rough Ceiling Texture	15% Chrysotile	661 ft ²	Friable Surfacing	Significantly Damaged	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	2	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	661 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs.
Transite Fume Hood Exhaust Pipe and Caulk	15-30% Chrysotile 30% Crocidolite	30 ft	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The asbestos transite fume hood exhaust pipe is protruding from a chase in the east end of the room; the black caulk on the pipe is ACM.
Rough Ceiling Texture Over-Spray (on pipes)	3% Chrysotile	237 ft	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	The asbestos over-spray is on pipes along the ceiling.
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
Hard Fittings on Fiberglass Insulation	0-30% Chrysotile 0-15% Amosite	4 fittings	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	The asbestos hard fittings on fiberglass pipe insulation are along the ceiling in the middle of the room.

Room 218

Rough Ceiling Texture	15% Chrysotile	227 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	None
9" Floor Tile and Mastic	Assumed	227 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs; they are under the carpet.

Room 218A

Rough Ceiling Texture	15% Chrysotile	103 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	None
9" Floor Tile and Mastic	Assumed	103 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs; they are under the carpet.

Room 219

Rough Ceiling Texture	15% Chrysotile	278 ft ²	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	None
9" Floor Tile and Mastic	Assumed	278 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs.
Rough Ceiling Texture Over-Spray (on pipes)	3% Chrysotile	62 ft	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	The asbestos over-spray is on pipes along the ceiling.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 220

Rough Ceiling Texture	15% Chrysotile	779 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
Carpet Mastic (with residual black mastic) Abated June 2013	10% Chrysotile	779 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	N/A*	None
Window Glazing	5% Chrysotile	4 windows	Non-Friable Miscellaneous	N/A*	N/A*	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	N/A*	The asbestos glazing is on the four north interior windows in room 220.

Room 221

Rough Ceiling Texture	15% Chrysotile	786 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
9" Floor Tile and Mastic	Assumed	786 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	N/A*	The 9" floor tile and mastic are assumed to be ACMs.
Transite Fume Hood Exhaust Pipe and Caulk	15-30% Chrysotile 30% Crocidolite	30 ft	Non-Friable Miscellaneous	N/A*	N/A*	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	N/A*	The asbestos transite fume hood exhaust pipe is protruding from a chase in the east end of the room; the black caulk on the pipe is ACM.
Rough Ceiling Texture Over-Spray (on pipes)	3% Chrysotile	154 ft	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	The asbestos over-spray is on pipes along the ceiling.

Room 222

Rough Ceiling Texture	15% Chrysotile	260 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
9" Floor Tile and Mastic	Assumed	260 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	N/A*	The 9" floor tile and mastic are assumed to be ACMs.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	-----------------------------	-------

Room 225

Rough Ceiling Texture	15% Chrysotile	118 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	118 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 226

Rough Ceiling Texture	15% Chrysotile	120 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	120 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 227

Rough Ceiling Texture	15% Chrysotile	118 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	118 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs; they are under the carpet.

Room 228

Rough Ceiling Texture	15% Chrysotile	120 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	120 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	-----------------------------	-------

Room 229

Rough Ceiling Texture	15% Chrysotile	118 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	118 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs; they are under the carpet.

Room 231

Rough Ceiling Texture	15% Chrysotile	118 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	118 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs; they are under the carpet.

Abated June 2008

Room 233

Rough Ceiling Texture	15% Chrysotile	118 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	118 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 235

Rough Ceiling Texture	15% Chrysotile	118 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	118 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	-----------------------------	-------

Room 237

Rough Ceiling Texture	15% Chrysotile	112 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	112 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 239

Rough Ceiling Texture	15% Chrysotile	112 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	112 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 241

Rough Ceiling Texture	15% Chrysotile	422 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	422 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs.
Transite Fume Hood Exhaust Pipe and Caulk	15-30% Chrysotile 30% Crocidolite	15 ft	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The asbestos transite fume hood exhaust pipe is protruding from a chase in the southwest corner of the room; the black caulk on the pipe is ACM.
Rough Ceiling Texture Over-Spray (on pipes)	3% Chrysotile	80 ft	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	The asbestos over-spray is on pipes along the ceiling.
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Hard Fittings on Fiberglass Insulation	0-30% Chrysotile 0-15% Amosite	17 fittings	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	The asbestos hard fittings on fiberglass pipe insulation are along the west end of the room.
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
Fume Hood	10-15% Chrysotile	1 ea	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos transite fume hood is along the north wall.
Black Lab Countertop	5-10% Chrysotile	1 ea	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos black lab countertop is under the fume hood along the north wall.

Room 241A Now Part of Room 243

Rough Ceiling Texture Abated July 2009	15% Chrysotile	205 ft ²	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	None
9" Floor Tile and Mastic Abated July 2009	Assumed	205 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.
Transite Fume Hood Exhaust Pipe and Caulk	15-30% Chrysotile 30% Crocidolite	15 ft	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos transite fume hood exhaust pipe is protruding from a chase in the northwest corner of the room; the black caulk on the pipe is ACM.
Rough Ceiling Texture Over-Spray (on pipes) Abated July 2009	3% Chrysotile	59 ft	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	The asbestos over-spray is on pipes along the ceiling.

Room 243 Abated July 2009

Rough Ceiling Texture	15% Chrysotile	111 ft ²	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	None
9" Floor Tile and Mastic	Assumed	111 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs; they are under the carpet.
Rough Ceiling Texture Over-Spray (on pipes)	3% Chrysotile	54 ft	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	The asbestos over-spray is on pipes along the ceiling.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 243A Abated July 2009

Rough Ceiling Texture	15% Chrysotile	97 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	97 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 245

Rough Ceiling Texture	15% Chrysotile	434 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	434 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs.
Transite Fume Hood Exhaust Pipe and Caulk	15-30% Chrysotile 30% Crocidolite	15 ft	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The asbestos transite fume hood exhaust pipe is protruding from a chase in the southwest corner of the room; the black caulk on the pipe is ACM.
Rough Ceiling Texture Over-Spray (on pipes)	3% Chrysotile	104 ft	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	The asbestos over-spray is on pipes along the ceiling.
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		

Room 246 Abated Sept 2016

Rough Ceiling Texture	15% Chrysotile	378 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	378 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs.
Transite Fume Hood Exhaust Pipe and Caulk	15-30% Chrysotile 30% Crocidolite	15 ft	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The asbestos transite fume hood exhaust pipe is protruding from a chase in the northwest corner of the room; the black caulk on the pipe is ACM.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
Rough Ceiling Texture Over-Spray (on pipes)	3% Chrysotile	101 ft	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	The asbestos over-spray is on pipes along the ceiling.
Gray Sink Undercoating	3% Chrysotile	1 sink	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos undercoating is on a sink along the north wall.

Room 247 Abated Sept 2016

Rough Ceiling Texture	15% Chrysotile	896 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
9" Floor Tile and Mastic	Assumed	896 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.
Transite Fume Hood Exhaust Pipe and Caulk	15-30% Chrysotile 30% Crocidolite	30 ft	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos transite fume hood exhaust pipe is protruding from a chase in the west end of the room; the black caulk on the pipe is ACM.
Rough Ceiling Texture Over-Spray (on pipes)	3% Chrysotile	146 ft	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	The asbestos over-spray is on pipes along the ceiling.

Room 249

Rough Ceiling Texture	15% Chrysotile	125 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
9" Floor Tile and Mastic	Assumed	125 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	-----------------------------	-------

Room 251

Rough Ceiling Texture	15% Chrysotile	125 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	125 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Hallway 288 (includes all hallways on 2nd floor and janitor's closet across from room 215)

9" Floor Tile and Mastic	Assumed	2,842 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs.
Red HVAC Duct Caulk	10% Chrysotile	85 ea	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The asbestos red HVAC duct caulk is above ceiling tile throughout the hallways.
Rough Ceiling Texture	15% Chrysotile	133 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	The asbestos ceiling texture is in the janitor's closet and above the ceiling tile between rooms 209 and 213.
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		

Room 288A

Rough Ceiling Texture	15% Chrysotile	261 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		

Room 288B

Window Glazing	5% Chrysotile	1 window	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The asbestos glazing is on the south window by the hallway entrance.
----------------	---------------	----------	------------------------------	------	------	------	------	--

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	-----------------------------	-------

Room 299M

9" Floor Tile and Mastic	Assumed	105 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.
--------------------------	---------	---------------------	------------------------------	------	------	--	------	--

Room 299W

9" Floor Tile and Mastic	Assumed	81 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.
--------------------------	---------	--------------------	------------------------------	------	------	--	------	--

Room 301

Rough Ceiling Texture	15% Chrysotile	120 ft ²	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>		6	None
					Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>			
					Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>			
9" Floor Tile and Mastic	Assumed	120 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 302

Rough Ceiling Texture	15% Chrysotile	343 ft ²	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>		6	None
					Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>			
					Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>			
9" Floor Tile and Mastic	Assumed	343 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs; they are under the carpet.

Abated June 2013

Room 303

Rough Ceiling Texture	15% Chrysotile	120 ft ²	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>		6	None
					Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>			
					Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>			

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
9" Floor Tile and Mastic	Assumed	120 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 305

Rough Ceiling Texture	15% Chrysotile	118 ft ²	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>		6	None
9" Floor Tile and Mastic	Assumed	118 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 306

Rough Ceiling Texture	15% Chrysotile	357 ft ²	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>		6	None
9" Floor Tile and Mastic Abated June 2013	Assumed	357 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs; they are under the carpet.
Window Glazing	5% Chrysotile	1 window	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos glazing is on the south window by the room entrance.

Room 306A

Rough Ceiling Texture	15% Chrysotile	150 ft ²	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>		6	None
9" Floor Tile and Mastic Abated June 2013	Assumed	150 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs; they are under the carpet.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	-----------------------------	-------

Room 306B

Rough Ceiling Texture	15% Chrysotile	56 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic Abated June 2013	Assumed	56 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 306C

Rough Ceiling Texture	15% Chrysotile	150 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic Abated June 2013	Assumed	150 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs; they are under the carpet.

Room 306D

Rough Ceiling Texture	15% Chrysotile	104 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic Abated June 2013	Assumed	104 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs; they are under the carpet.

Room 306E

Rough Ceiling Texture	15% Chrysotile	112 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic Abated June 2013	Assumed	112 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs; they are under the carpet.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 307

Rough Ceiling Texture	15% Chrysotile	255 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	255 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs; they are under the carpet.

Room 310 Abated October 2021

Rough Ceiling Texture	15% Chrysotile	112 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	112 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs; they are under the carpet.

Room 311

Rough Ceiling Texture	15% Chrysotile	1,011 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
	Abated Jan 2015				Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	1,011 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs.
	Abated Jan 2015							
Transite Fume Hood Exhaust Pipe and Caulk	15-30% Chrysotile 30% Crocidolite	45 ft	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The asbestos transite fume hood exhaust pipes are protruding from chases in the east end of the room; the black caulk on the pipe is ACM.
Fume Hood	10-15% Chrysotile	1 ea	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The asbestos transite fume hood is along the north wall and has an unattached transite panel that sits below the fume hood.
	Abated Jan 2015							

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	-----------------------------	-------

Room 311B Abated Jan 2015

Rough Ceiling Texture	15% Chrysotile	110 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	110 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 312 Abated October 2021

Rough Ceiling Texture	15% Chrysotile	122 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	122 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs; they are under the carpet.

Room 313

Rough Ceiling Texture	15% Chrysotile	215 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	215 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.
Transite Fume Hood Exhaust Pipe and Caulk	15-30% Chrysotile 30% Crocidolite	15 ft	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos transite fume hood exhaust pipe is protruding from a chase in the southeast corner of the room; the black caulk on the pipe is ACM.

Room 314

Rough Ceiling Texture	15% Chrysotile	261 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
9" Floor Tile and Mastic	Assumed	261 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 315 Abated Jan 2018

Rough Ceiling Texture	15% Chrysotile	791ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	791 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.
Transite Fume Hood Exhaust Pipe and Caulk	15-30% Chrysotile 30% Crocidolite	30 ft	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos transite fume hood exhaust pipe is protruding from a chase in the northeast corner of the room; the black caulk on the pipe is ACM.

Room 315A Now part of 315 Abated Jan 2018

Rough Ceiling Texture	15% Chrysotile	212 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	212 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 317

Rough Ceiling Texture	15% Chrysotile	126 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	126 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	-----------------------------	-------

Room 318 Abated Jan 2018

Rough Ceiling Texture	15% Chrysotile	234 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	234 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 318A Abated Jan 2018

Rough Ceiling Texture	15% Chrysotile	146 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	146 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 318B Abated Jan 2018

Rough Ceiling Texture	15% Chrysotile	147 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	147 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 319

Rough Ceiling Texture	15% Chrysotile	126 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	126 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	-----------------------------	-------

Room 320

Rough Ceiling Texture	15% Chrysotile	233 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	233 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 320A

Rough Ceiling Texture	15% Chrysotile	146 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	146 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 320B

Rough Ceiling Texture	15% Chrysotile	113 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	113 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 320C

Rough Ceiling Texture	15% Chrysotile	118 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	118 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	-----------------------------	-------

Room 321

Rough Ceiling Texture	15% Chrysotile	126 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	126 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 322

Rough Ceiling Texture	15% Chrysotile	128 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	128 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 323

Rough Ceiling Texture	15% Chrysotile	126 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	126 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 324

Rough Ceiling Texture	15% Chrysotile	123 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	123 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	-----------------------------	-------

Room 325

Rough Ceiling Texture	15% Chrysotile	126 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	126 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 326

Rough Ceiling Texture	15% Chrysotile	120 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	120 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs; they are under the carpet.

Abated Jan 2018

Room 327

Rough Ceiling Texture	15% Chrysotile	126 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	126 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 328

Now 399W

Abated Jan 2018

Rough Ceiling Texture	15% Chrysotile	118 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	118 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	-----------------------------	-------

Room 329

Rough Ceiling Texture	15% Chrysotile	126 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	126 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 331

Rough Ceiling Texture	15% Chrysotile	126 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	126 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 333

Rough Ceiling Texture	15% Chrysotile	126 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	126 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 335

Abated April 2008

Rough Ceiling Texture	15% Chrysotile	146 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	146 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 337

Rough Ceiling Texture Abated April 2008	15% Chrysotile	422 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
9" Floor Tile and Mastic Abated April 2008	Assumed	422 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	N/A*	The 9" floor tile and mastic are assumed to be ACMs.
Transite Fume Hood Exhaust Pipe and Caulk	15-30% Chrysotile 30% Crocidolite	15 ft	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos transite fume hood exhaust pipe is protruding from a chase in the southwest corner of the room; the black caulk on the pipe is ACM.
Fume Hood Abated April 2008	10-15% Chrysotile	1 ea	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos transite fume hood is along the south wall.
Black Lab Countertop Abated April 2008	5-10% Chrysotile	2 ea	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	1 asbestos black lab counter top is in the center of the room (west part of the island); the other is below the fume hood along the south wall.
Black Sink Undercoating Abated April 2008	3-10% Chrysotile	1 sink	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos undercoating is on a sink in the center of the room.

Room 339

Rough Ceiling Texture	15% Chrysotile	205 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
9" Floor Tile and Mastic	Assumed	205 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	N/A*	The 9" floor tile and mastic are assumed to be ACMs.
Transite Fume Hood Exhaust Pipe and Caulk	15-30% Chrysotile 30% Crocidolite	15 ft	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos transite fume hood exhaust pipe is protruding from a chase in the northwest corner of the room; the black caulk on the pipe is ACM.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 341

Rough Ceiling Texture	15% Chrysotile	205 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	205 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.
Fume Hood	10-15% Chrysotile	1 ea	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos transite fume hood is along the north wall.

Room 343

Rough Ceiling Texture	15% Chrysotile	205 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	205 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.
Black Lab Countertop	15% Chrysotile	1 ea	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos black lab countertop is along the south wall.

Room 345 Abated Jan 2018

Rough Ceiling Texture	15% Chrysotile	632 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	632 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.
Transite Fume Hood Exhaust Pipe and Caulk	15-30% Chrysotile 30% Crocidolite	40 ft	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos transite fume hood exhaust pipe is protruding from a chase in the west end of the room; the black caulk on the pipe is ACM.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 347

Rough Ceiling Texture	15% Chrysotile	208 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	208 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 349

Rough Ceiling Texture	15% Chrysotile	205 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	205 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs.
Black Lab Countertop	15% Chrysotile	3 ea	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The asbestos black lab countertops are along the north, south, and east walls.
Transite Fume Hood Exhaust Pipe and Caulk	15-30% Chrysotile 30% Crocidolite	15 ft	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The asbestos transite fume hood exhaust pipe is protruding from a chase in the southwest corner of the room; the black caulk on the pipe is ACM.

Room 351

Rough Ceiling Texture	15% Chrysotile	205 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	205 ft ²	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic are assumed to be ACMs.
Transite Fume Hood Exhaust Pipe and Caulk	15-30% Chrysotile 30% Crocidolite	15 ft	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The asbestos transite fume hood exhaust pipe is protruding from a chase in the northwest corner of the room; the black caulk on the pipe is ACM.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	-----------------------------	-------

Room 351A

Rough Ceiling Texture	15% Chrysotile	101 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	101 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 351B

Rough Ceiling Texture	15% Chrysotile	87 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	87 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 353

Rough Ceiling Texture	15% Chrysotile	125 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	125 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.

Room 355

Rough Ceiling Texture	15% Chrysotile	125 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
9" Floor Tile and Mastic	Assumed	125 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Hallway 388

9" Floor Tile and Mastic	Assumed	2,824 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.
Red HVAC Duct Caulk	10% Chrysotile	85 ea	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos red HVAC duct caulk is above ceiling tile throughout the hallways.
Rough Ceiling Texture	15% Chrysotile	85 ft ²	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	The asbestos ceiling texture is above the ceiling tile between rooms 307 and 311A.
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		

Room 399M Abated Jan 2018

9" Floor Tile and Mastic	Assumed	105 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.
-------------------------------------	---------	---------------------	------------------------------	------	------	--	------	--

Room 399W Now 399U Abated Jan 2018

9" Floor Tile and Mastic	Assumed	81 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs.
-------------------------------------	---------	--------------------	------------------------------	------	------	--	------	--

South Stairway (includes 1st floor -3rd floor)

9" Floor Tile and Mastic	Assumed	165 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic are assumed to be ACMs; they are in the 1 st floor level.
--------------------------	---------	---------------------	------------------------------	------	------	--	------	---

Tunnel Abated May 2017

Hard Fittings on Fiberglass Insulation	0-30% Chrysotile 0-15% Amosite	301 fittings	Friable Surfacing	Significantly Damaged	Physical	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	1	The asbestos hard fittings on fiberglass pipe insulation are throughout the crawl tunnels.
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
WALSTER HALL (BUILDING A053)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
Foam Wall Panel Adhesive	10% Chrysotile	2,240 ft ²	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos foam wall panel adhesive is on the outer walls of the tunnels running along the perimeter of the building.
Hard Pack on Fiberglass Insulation	0-30% Chrysotile 0-5% Amosite	15 ea	Friable Surfacing	Significantly Damaged	Physical <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		1	The asbestos hard packs on fiberglass pipe insulation are throughout the crawl tunnels.

Exterior

Window/Panel Glazing	3% Chrysotile	116 ea	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	Refer to the ACM Locations Map for further information.
-------------------------	---------------	--------	------------------------------	------	------	--	------	---

¹Assessment Categories:

- | | |
|---|---|
| 1) Damaged or Significantly Damaged TSI ACM | 5) ACM with Potential for Damage |
| 2) Damaged Friable Surfacing ACM | 6) ACM with Potential for Significant Damage |
| 3) Significantly Damaged Friable Surfacing ACM | 7) Any Remaining Friable ACM or Friable Suspected ACM |
| 4) Damaged or Significantly Damaged Friable Miscellaneous ACM | |

End