

# NARRATIVE REPORT

## 1.0 BUILDING INFORMATION

Johnson Hall was originally constructed in 1963; the building has had no major renovations.

Johnson Hall is a four-story, 42,973 ft<sup>2</sup> building which primarily serves as dormitory areas for students. Reed Hall (A055) is attached to the north side of Johnson Hall and is reported separately; Residence Dining Center (A059) is attached to the south side of Johnson Hall and is reported separately.

The interior floor finishes included sheet vinyl flooring, floor tile, carpet, and concrete; the interior wall finishes included concrete block, concrete, gypsum wallboard, plaster, ceramic block, carpet, and terrazzo; and the interior ceiling finishes included ceiling tile, plaster, and metal. The roofing system is a flat rubber-membrane roof and the exterior of the structure is brick.

The piping systems were insulated; fiberglass insulation (with and without hard fittings) is located in the building. Steam enters the building via a tunnel into room 2. Domestic water enters the building in the southwest end of the tunnels. HVAC systems located in the building consisted of steam radiators and a forced air furnace with heating/cooling coils.

## 2.0 ASBESTOS SURVEY INFORMATION

Johnson Hall was surveyed as part of a larger project on NDSU's Fargo, ND Campus. This report is part of "Volume 6" of a nine volume series. This report includes building specific information only; please refer to the opening section of "Volume 6" for methodologies, definitions, and other pertinent supporting information.

LEGEND was granted full access to Johnson Hall during the initial walk-through and sampling of the building. During subsequent walk-throughs of the building, for resampling and reporting purposes, LEGEND was granted access to the common areas and to 2-4 dormitory rooms per floor, only. For the remainder of the dormitory rooms, LEGEND identified the locations of ACMs using survey notes taken during the initial walk-through of the building.

A total of 82 samples were collected from suspect asbestos-containing materials (ACM) from Johnson Hall on May 24, 2007, an additional 1 sample was collected on March 17, 2008, and an additional 1 sample was collected on March 25, 2008. Laboratory analysis results indicate **12 of these samples tested positive for asbestos.**

### 2.1 Suspect Materials Identified and Sampled

Ceiling Tile (6 types)	Sink Undercoating
Fiberglass Panel Adhesive	Penetration Putty
Baseboard Adhesive	Wood Panel Adhesive
Sheet Vinyl Flooring	Window Caulk
Textured Paint	Joint Compound
Gypsum Wallboard	Carpet Mastic
Ceiling Texture (3 types)	Floor Tile
Floor Tile Mastic	Hard Plaster- Skimcoat (2 types)
Hard Plaster- Basecoat (3 types)	Concrete Wall Texture

Hard Plaster- Monocoat  
 Hard Fittings on Fiberglass Insulation  
 Encapsulant on Fiberglass Insulation  
 Exterior Door Caulk  
 Underground Culvert Tar Wrap

Tar HVAC Duct Wrap  
 Hard Pack on Fiberglass Insulation  
 Exterior Building Seam Caulk (2 types)  
 Exterior Window Caulk (2 types)

The Asbestos Bulk Sample Results Table includes asbestos sampling data.

2.2 **Asbestos Containing Materials**

Concrete Wall Texture  
 Hard Fitting on Fiberglass Insulation  
 Hard Pack on Fiberglass Insulation  
 Underground Culvert Tar Wrap  
 9" Floor Tile and Mastic (assumed)

The ACM Locations/ Friable Materials Assessments Table includes ACM locations data.

2.3 **Cost Estimates**

Legend Technical Services Inc. estimates abatement costs (removal & disposal) of ACM for Johnson Hall as follows:

ACM	QUANTITY	UNIT COST	TOTAL COST
Asbestos Wall Texture	242 ft <sup>2</sup>	\$7.50/ft <sup>2</sup>	\$1,815.00
Asbestos Hard Fittings on Fiberglass Insulation	226 ea	\$60.00/ea	\$13,560.00
Asbestos Hard Pack on Fiberglass Insulation	19 ea	\$60.00/ea	\$1,140.00
Asbestos Underground Culvert Tar Wrap	51 ft	*	*
Asbestos Floor Tile and Mastic	31,491 ft <sup>2</sup>	\$4.00/ft <sup>2</sup>	\$125,964.00
<b>Total Estimated Abatement Costs:</b>			<b>\$142,479.00</b>

\*The underground culvert tar wrap is buried beneath Johnson Hall between the north and south branches of the west tunnel. It is currently not accessible. The material will require abatement in the future when Johnson Hall is demolished.

2.4 **Survey Notes**

LEGEND was able to visually quantify ACM hard fittings on fiberglass insulation throughout the basement on steam and water pipes. However, on floors 1-3 inaccessible ceilings and pipe chases prevented LEGEND from verifying the presence of possible additional hard fittings. LEGEND assumes additional hard fittings will be discovered during renovation or demolition activities on the water pipes supplying the laundry rooms, custodial rooms, and bathrooms and on steam pipes providing steam to radiators throughout the building. LEGEND recommends assuming an additional 100-150 hard fittings on fiberglass insulation on 1<sup>st</sup> and 2<sup>nd</sup> floors and an additional 50 hard fittings on 3<sup>rd</sup> floor.

Abandoned underground steam lines running between the north and south branches of the west tunnel exist; these steam lines are inside a corrugated metal culvert. The exterior of the culvert has an ACM tar wrap on it.

**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
JOHNSON HALL (BUILDING A058)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. <sup>1</sup>	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	-----------------------------	-------

**Tunnel**

Hard Fittings on Fiberglass Insulation	0-15% Chrysotile 0-25% Amosite	197 fittings	Friable TSI	Significantly Damaged	Physical Air Erosion Vibration	<input type="checkbox"/> ■ <input type="checkbox"/> <input type="checkbox"/> ■ <input type="checkbox"/> <input type="checkbox"/> ■ <input type="checkbox"/>	1	The hard fittings on fiberglass insulation are throughout the tunnel.
Hard Pack on Fiberglass Insulation	15% Chrysotile	19 ea	Friable TSI	Significantly Damaged	Physical Air Erosion Vibration	<input type="checkbox"/> ■ <input type="checkbox"/> <input type="checkbox"/> ■ <input type="checkbox"/> <input type="checkbox"/> ■ <input type="checkbox"/>	1	The hard pack is around valves and at the end of fiberglass insulation throughout the tunnel.

**Room 2**

Hard Fittings on Fiberglass Insulation	0-15% Chrysotile 0-25% Amosite	3 fittings	Friable TSI	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> ■ ■ <input type="checkbox"/> <input type="checkbox"/> ■ <input type="checkbox"/> <input type="checkbox"/>	6	The hard fittings on fiberglass insulation run along the north wall.
---	-----------------------------------	------------	----------------	------	--------------------------------------	---	---	--

**Room 2A**

Hard Fittings on Fiberglass Insulation	0-15% Chrysotile 0-25% Amosite	3 fittings	Friable TSI	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> ■ ■ <input type="checkbox"/> <input type="checkbox"/> ■ <input type="checkbox"/> <input type="checkbox"/>	6	None.
---	-----------------------------------	------------	----------------	------	--------------------------------------	---	---	-------

**Room 5A**

Hard Fittings on Fiberglass Insulation	0-15% Chrysotile 0-25% Amosite	3 fittings	Friable TSI	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> ■ ■ <input type="checkbox"/> <input type="checkbox"/> ■ <input type="checkbox"/> <input type="checkbox"/>	6	The hard fittings on fiberglass insulation are on the east end of the room.
---	-----------------------------------	------------	----------------	------	--------------------------------------	---	---	---

**Room 5C**

Hard Fittings on Fiberglass Insulation	0-15% Chrysotile 0-25% Amosite	3 fittings	Friable TSI	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> ■ <input type="checkbox"/> <input type="checkbox"/> ■ <input type="checkbox"/> <input type="checkbox"/> ■	6	The hard fittings on fiberglass insulation are in the southeast corner of the room, leading to the AHU.
---	-----------------------------------	------------	----------------	------	--------------------------------------	---	---	---

**Room 6 A**

Hard Fittings on Fiberglass Insulation	0-15% Chrysotile 0-25% Amosite	6 fittings	Friable TSI	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> ■ ■ <input type="checkbox"/> <input type="checkbox"/> ■ <input type="checkbox"/> <input type="checkbox"/>	6	The hard fittings on fiberglass insulation run along the north wall.
---	-----------------------------------	------------	----------------	------	--------------------------------------	---	---	--

\* = Non-Friable materials were not assessed

**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
JOHNSON HALL (BUILDING A058)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. <sup>1</sup>	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

**Room 7**

Hard Fittings on Fiberglass Insulation	0-15% Chrysotile 0-25% Amosite	3 fittings	Friable TSI	Good	Physical Air Erosion Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	7	The hard fittings on fiberglass insulation are above ceiling tile along the southeast corner of the room.
---	-----------------------------------	------------	----------------	------	--------------------------------------	---	---	---

**Room 8**

Concrete Wall Texture	2-3% Chrysotile	242 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The asbestos concrete wall texture is on the north and west walls.
--------------------------	-----------------	---------------------	------------------------------	------	------	------	------	--

**Hallway 88**

Hard Fittings on Fiberglass Insulation	0-15% Chrysotile 0-25% Amosite	8 fittings	Friable TSI	Good	Physical Air Erosion Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	7	The hard fittings on fiberglass insulation are above ceiling tile, refer to the ACM Locations Diagram for exact locations.
---	-----------------------------------	------------	----------------	------	--------------------------------------	---	---	--

**Dorm Rooms 141, 142, 143, 144, 145, 146, 147, 148, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, 161, 162, 163, 164, 165, 166, 167, 170, 171, 172, 173, 174, 175, 176, 177, and 178** Abated June 2013

<del>9" Floor Tile and Mastic</del>	Assumed	184 ft <sup>2</sup> each	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The floor tile and mastic were assumed to be ACMs (under carpet in room 159 only).
---	---------	-----------------------------	------------------------------	------	------	------	------	--

**Dorm Rooms 149, 150, 168, and 169** Abated June 2013

<del>9" Floor Tile and Mastic</del>	Assumed	246 ft <sup>2</sup> each	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The floor tile and mastic were assumed to be ACMs.
---	---------	-----------------------------	------------------------------	------	------	------	------	--

**Room 180** Abated June 2013

<del>9" Floor Tile and Mastic</del>	Assumed	32 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The floor tile and mastic were assumed to be ACMs.
---	---------	--------------------	------------------------------	------	------	------	------	--

ACM-containing mudded fittings removed from 179, 281, 381 and adjacent rooms to the east and west - May 2018

\* = Non-Friable materials were not assessed

**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
JOHNSON HALL (BUILDING A058)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. <sup>1</sup>	NOTES
<b>Room 181</b> Abated June 2013								
<del>9" Floor Tile and Mastic</del>	Assumed	14 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The floor tile and mastic were assumed to be ACMs.
<b>Room 182</b> Abated May 2009								
<del>9" Floor Tile and Mastic</del>	Assumed	43 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The floor tile and mastic were assumed to be ACMs.
<b>Room 183</b> Abated June 2013								
<del>9" Floor Tile and Mastic</del>	Assumed	39 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The floor tile and mastic were assumed to be ACMs.
<b>Room 184</b> Abated May 2009								
<del>9" Floor Tile and Mastic</del>	Assumed	13 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The floor tile and mastic were assumed to be ACMs.
<b>Room 186</b> Abated June 2013								
<del>9" Floor Tile and Mastic</del>	Assumed	29 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The floor tile and mastic were assumed to be ACMs.
<b>Hallway 188 (including all hallways on 1<sup>st</sup> floor)</b> Abated June 2013								
<del>9" Floor Tile and Mastic</del>	Assumed	2,601 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The floor tile and mastic were assumed to be ACMs.

\* = Non-Friable materials were not assessed

**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
JOHNSON HALL (BUILDING A058)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. <sup>1</sup>	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	-----------------------------	-------

**Room 190** Abated June 2013

<del>9" Floor Tile and Mastic</del>	Assumed	14 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The floor tile and mastic were assumed to be ACMs.
-------------------------------------	---------	--------------------	------------------------------	------	------	--	------	--

**Room 191** Abated June 2013

<del>9" Floor Tile and Mastic</del>	Assumed	32 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The floor tile and mastic were assumed to be ACMs.
-------------------------------------	---------	--------------------	------------------------------	------	------	--	------	--

**Room 192** Abated June 2013

<del>9" Floor Tile and Mastic</del>	Assumed	29 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The floor tile and mastic were assumed to be ACMs.
-------------------------------------	---------	--------------------	------------------------------	------	------	--	------	--

**Dorm Rooms 241, 242, 243, 244, 245, 246, 247, 248, 249, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 272, 273, 274, 275, 276, 277, 278, 279, and 280** 279 & 280 Abated June 2011, 261-278 June 2022, remainder Abated June 2023

<del>9" Floor Tile and Mastic</del>	Assumed	184 ft <sup>2</sup> each	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The floor tile and mastic were assumed to be ACMs (under carpet in rooms 279 and 280 only).
-------------------------------------	---------	-----------------------------	------------------------------	------	------	--	------	---

**Dorm Rooms 250, 251, 270, and 271.** 270 & 271 Abated June 2022, 250 & 251 Abated June 2023

<del>9" Floor Tile and Mastic</del>	Assumed	299 ft <sup>2</sup> each	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The floor tile and mastic were assumed to be ACMs.
-------------------------------------	---------	-----------------------------	------------------------------	------	------	--	------	--

**Room 282** Abated June 2023

<del>9" Floor Tile and Mastic</del>	Assumed	14 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The floor tile and mastic were assumed to be ACMs.
-------------------------------------	---------	--------------------	------------------------------	------	------	--	------	--

ACM-containing mudded fittings removed from 179, 281, 381 and adjacent rooms to the east and west - May 2018

\* = Non-Friable materials were not assessed

**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
JOHNSON HALL (BUILDING A058)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. <sup>1</sup>	NOTES
<b>Room 283</b> <span style="border: 1px solid red; padding: 2px;">Abated June 2023</span>								
<del>9" Floor Tile and Mastic</del>	Assumed	39 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The floor tile and mastic were assumed to be ACMs.
<b>Room 284</b> <span style="border: 1px solid red; padding: 2px;">Abated May 2017</span>								
<del>9" Floor Tile and Mastic</del>	Assumed	14 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The floor tile and mastic were assumed to be ACMs.
<b>Room 286</b> <span style="border: 1px solid red; padding: 2px;">Abated May 2017</span>								
<del>9" Floor Tile and Mastic</del>	Assumed	29 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The floor tile and mastic were assumed to be ACMs.
<b>Hallway 288 (includes all hallways on the 2<sup>nd</sup> Floor)</b> <span style="border: 1px solid red; padding: 2px;">East Half Abated June 2022, West Half Abated June 2023</span>								
<del>9" Floor Tile and Mastic</del>	Assumed	2,065 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The floor tile and mastic were assumed to be ACMs.
<b>Room 289</b> <span style="border: 1px solid red; padding: 2px;">Abated June 2022</span>								
<del>9" Floor Tile and Mastic</del>	Assumed	14 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The floor tile and mastic were assumed to be ACMs.
<b>Room 290</b> <span style="border: 1px solid red; padding: 2px;">Abated May 2017</span>								
<del>9" Floor Tile and Mastic</del>	Assumed	32 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The floor tile and mastic were assumed to be ACMs.

\* = Non-Friable materials were not assessed

**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
JOHNSON HALL (BUILDING A058)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. <sup>1</sup>	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

**Room 291** Abated May 2017

<del>9" Floor Tile and Mastic</del>	Assumed	29 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The floor tile and mastic were assumed to be ACMs.
-------------------------------------	---------	--------------------	------------------------------	------	------	--	------	--

**Dorm Rooms 341, 342, 343, 344, 345, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, 363, 364, 365, 366, 367, 368, 369, 372, 373, 374, 375, 376, 377, 378, 379, and 380** 379 & 380 Abated June 2011, 361-378 June 2022, remainder Abated June 2023

<del>9" Floor Tile and Mastic</del>	Assumed	184 ft <sup>2</sup> each	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The floor tile and mastic were assumed to be ACMs (under carpet in rooms 379 and 380 only).
-------------------------------------	---------	-----------------------------	------------------------------	------	------	--	------	---

**Dorm Rooms 350, 351, 370, and 371.** 370 & 371 Abated June 2022, 350 & 351 Abated June 2023

<del>9" Floor Tile and Mastic</del>	Assumed	299 ft <sup>2</sup> each	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The floor tile and mastic were assumed to be ACMs.
-------------------------------------	---------	-----------------------------	------------------------------	------	------	--	------	--

**Room 382** Abated June 2023

<del>9" Floor Tile and Mastic</del>	Assumed	14 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The floor tile and mastic were assumed to be ACMs.
-------------------------------------	---------	--------------------	------------------------------	------	------	--	------	--

**Room 383** Abated June 2023

<del>9" Floor Tile and Mastic</del>	Assumed	23 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The floor tile and mastic were assumed to be ACMs.
-------------------------------------	---------	--------------------	------------------------------	------	------	--	------	--

**Room 384** Abated June 2023

<del>9" Floor Tile and Mastic</del>	Assumed	39 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The floor tile and mastic were assumed to be ACMs.
-------------------------------------	---------	--------------------	------------------------------	------	------	--	------	--

ACM-containing mudded fittings removed from 179, 281, 381 and adjacent rooms to the east and west - May 2018

\* = Non-Friable materials were not assessed



**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
JOHNSON HALL (BUILDING A058)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. <sup>1</sup>	NOTES
<b>Room 385</b> Abated May 2017								
<del>9" Floor Tile and Mastic</del>	Assumed	13 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The floor tile and mastic were assumed to be ACMs.
<b>Room 387</b> Abated May 2017								
<del>9" Floor Tile and Mastic</del>	Assumed	29 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The floor tile and mastic were assumed to be ACMs.
<b>Hallway 388 (includes all hallways on the 3<sup>rd</sup> Floor)</b> East Half Abated June 2022, West Half Abated June 2023								
<del>9" Floor Tile and Mastic</del>	Assumed	2,065 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The floor tile and mastic were assumed to be ACMs.
<b>Room 390</b> Abated June 2022								
<del>9" Floor Tile and Mastic</del>	Assumed	25 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The floor tile and mastic were assumed to be ACMs.
<b>Room 391</b> Abated June 2022								
<del>9" Floor Tile and Mastic</del>	Assumed	14 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The floor tile and mastic were assumed to be ACMs.
<b>Room 393</b> Abated May 2017								
<del>9" Floor Tile and Mastic</del>	Assumed	29 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The floor tile and mastic were assumed to be ACMs.

\* = Non-Friable materials were not assessed

**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
JOHNSON HALL (BUILDING A058)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. <sup>1</sup>	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

**East Stairway (from 1<sup>st</sup> to 3<sup>rd</sup> floor) Abated June 2022**

<del>9" Floor Tile and Mastic</del>	Assumed	411 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The floor tile and mastic were assumed to be ACMs.
-------------------------------------	---------	---------------------	------------------------------	------	------	--	------	--

**Center Stairway (from basement to 3<sup>rd</sup> floor) Abated June 2023**

<del>9" Floor Tile and Mastic</del>	Assumed	456 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The floor tile and mastic were assumed to be ACMs.
-------------------------------------	---------	---------------------	------------------------------	------	------	--	------	--

**West Stairway (from 1<sup>st</sup> to 3<sup>rd</sup> floor) Abated June 2023**

<del>9" Floor Tile and Mastic</del>	Assumed	411 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The floor tile and mastic were assumed to be ACMs.
-------------------------------------	---------	---------------------	------------------------------	------	------	--	------	--

**Underground (entering the building in the north and south branches of the west tunnel)**

Underground Culvert Tar Wrap	2% Chrysotile	51 ft	Friable TSI	Significantly Damaged	Physical Air Erosion Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	1	The tar wrap is on the abandoned culvert in the west tunnel. The visible material was assessed. Refer to section 2.4 "Survey Notes".
---------------------------------	---------------	-------	----------------	--------------------------	--------------------------------------	---	---	--

<sup>1</sup>Assessment Categories:

- |   |   |
|---|---|
| 1) Damaged or Significantly Damaged TSI ACM                   | 5) ACM with Potential for Damage                      |
| 2) Damaged Friable Surfacing ACM                              | 6) ACM with Potential for Significant Damage          |
| 3) Significantly Damaged Friable Surfacing ACM                | 7) Any Remaining Friable ACM or Friable Suspected ACM |
| 4) Damaged or Significantly Damaged Friable Miscellaneous ACM |   |

End

\* = Non-Friable materials were not assessed