

# NARRATIVE REPORT

## 1.0 BUILDING INFORMATION

Thompson Hall was originally constructed in 1966; although specific information could not be located, several small renovations are evident.

Thompson Hall is an eleven-story, 65,360 ft<sup>2</sup> building which primarily serves as dormitory areas for students. Sevrinson Hall (A067) and West Dining Center (A080) are attached via tunnel to the north side of Thompson Hall and are reported separately; the tunnel is reported with West Dining Center (A080).

The interior floor finishes included floor tile, concrete, carpet, and ceramic tile; the interior wall finishes included plaster, gypsum wallboard, concrete, ceramic tile, ceramic block, and concrete block; and the interior ceiling finishes included metal, plaster, gypsum wallboard, ceramic tile, ceiling tile, and concrete. The roofing system is a flat built-up roof and the exterior of the structure is brick.

The piping systems were insulated; fiberglass pipe insulation (with and without hard fittings) is located in the building, mag block pipe insulation (with hard fittings) is located in room 1, and incinerator breeching is located in room 6A. Steam and domestic water enter the building in room 4. HVAC systems located in the building consisted of steam radiators and forced air furnaces equipped with heating/cooling coils.

## 2.0 ASBESTOS SURVEY INFORMATION

Thompson Hall was surveyed as part of a larger project on NDSU's Fargo, ND Campus. This report is part of "Volume 7" of a nine volume series. This report includes building specific information only; please refer to the opening section of "Volume 7" for methodologies, definitions, and other pertinent supporting information.

LEGEND was granted full access to Thompson Hall during the initial walk-through and sampling of the building. During subsequent walk-throughs of the building, for resampling and reporting purposes, LEGEND was granted access to the common areas and to 2-4 dormitory rooms per floor, only.

A total of 93 samples were collected from suspect asbestos-containing materials (ACM) from Thompson Hall on June 5, 2007 and an additional 18 samples were collected on March 19, 2008. Laboratory analysis results indicate **46 of these samples tested positive for asbestos.**

### 2.1 Suspect Materials Identified and Sampled

Hard Plaster- Skimcoat (3 types)	Hard Plaster- Basecoat (3 types)
Gypsum Wallboard (2 types)	Joint Compound (3 types)
Ceiling Texture (3 types)	HVAC Canvas Connector
Black AHU Putty	Wall Texture
Window Caulk	Ceiling Tile (6 types)
Baseboard Adhesive	Carpet Mastic
Sink Undercoating (2 types)	Floor Tile (5 types)
Floor Tile Mastic (5 types)	Stair Tread Adhesive
Penetration Concrete (at base of incinerator exhaust)	Incinerator Exhaust Stack Interior Lining

Rainleader Bowl  
 HVAC Duct Caulk  
 Incinerator Breeching  
 Mag Block Pipe Insulation  
 Fireproofing- Basecoat  
 Exterior Door/Window System Caulk  
 Window Glazing  
 Exterior Penetration Putty

Hard Fittings on Fiberglass Insulation  
 Encapsulant on Fiberglass Insulation  
 Tank Insulation (2 types)  
 Fireproofing- Skimcoat  
 Exterior Building Seam Caulk (2 types)  
 Exterior Foundation Caulk  
 Roof Flashing

The Asbestos Bulk Sample Results Table includes asbestos sampling data.

2.2 **Asbestos Containing Materials**

Joint Compound (1 type)  
 Black AHU Putty  
 Heavy Wall Texture  
 2'x4' Off-White Ceiling Tile with Lengthwise Fissures  
 Gray Sink Undercoating  
 Unknown Gray Floor Tile and Mastic  
 Penetration Concrete (at base of incinerator exhaust)  
 Incinerator Exhaust Stack Interior Lining  
 Rainleader Bowl  
 Hard Fittings on Fiberglass Insulation  
 Incinerator Breeching  
 Tank #68-004-21 Insulation  
 Small Vertical Tank Insulation  
 Mag Block Pipe Insulation  
 Hard Fittings on Mag Block Insulation (assumed)  
 Lobby Ceiling Texture  
 Dorm Room Ceiling Texture  
 Mastic for 12" Gray/White/Black Mottled Floor Tile  
 Window Glazing  
 Exterior Building Seam Caulk (1 type)  
 Exterior Penetration Putty  
 9" Floor Tile and Mastic (assumed)

The ACM Locations/ Friable Materials Assessments Table includes ACM locations data.

2.3 **Cost Estimates**

Legend Technical Services Inc. estimates abatement costs (removal & disposal) of ACM for Thompson Hall as follows:

ACM	QUANTITY	UNIT COST	TOTAL COST
Asbestos Floor Tile and/or Mastic	39,039 ft <sup>2</sup>	\$4.00/ft <sup>2</sup>	\$156,156.00
Asbestos Ceiling Texture (all types)	36,748 ft <sup>2</sup>	\$7.50/ft <sup>2</sup>	\$275,610.00
Asbestos Wall Texture	4,914 ft <sup>2</sup>	\$7.50/ft <sup>2</sup>	\$36,855.00
Asbestos Sink Undercoating	1 ea	\$150.00/ea	\$150.00
Asbestos Joint Compound	24,689 ft <sup>2</sup>	\$5.00/ft <sup>2</sup>	\$123,445.00

Asbestos Tank Insulation	14 ft <sup>2</sup>	\$100.00/ft <sup>2</sup>	\$1,400.00
Asbestos Mag Block Pipe Insulation	151 ft	\$25.00/ft	\$3,775.00
Asbestos Hard Fittings on Mag Block Insulation	22 ea	\$25.00/ea	\$550.00
Asbestos Window Glazing	33 ea	\$225.00/ea	\$7,425.00
Asbestos Building Seam Caulk	180 ft	\$5.00/ft	\$900.00
Asbestos Penetration Putty	1 ea	\$60.00/ea	\$60.00
Asbestos Ceiling Tile	580 ft <sup>2</sup>	\$5.00/ft <sup>2</sup>	\$2,900.00
Asbestos Hard Fittings on Fiberglass Insulation	461 ea	\$60.00/ea	\$27,660.00
Hard Pack on Fiberglass Insulation	29 ea	\$60.00/ea	\$1,740.00
Asbestos Rainleader Bowl Insulation	2 ea	\$60.00/ea	\$120.00
Asbestos Incinerator Breeching	14 ft	\$100/ft	\$1,400.00
Asbestos AHU Putty	3 ea	\$1,000.00/ea	\$3,000.00
Asbestos Incinerator Exhaust Stack Interior Lining	1 ea	\$5,000.00/ea	\$5,000.00
Asbestos Penetration Concrete	1 ea	\$500.00/ea	\$500.00
<b>Total Estimated Abatement Costs:</b>			<b>\$648,646.00</b>

#### 2.4 Survey Notes

LEGEND identified and sampled 2 types (homogeneous areas) of 2'x4' Off-White Ceiling Tile with Lengthwise Fissures and Pinholes from room 3 and hallway 88; only 1 tested positive for asbestos. The differences between the 2 types of ceiling tile are very subtle, with the ACM ceiling tile having slightly wider fissures and a darker backing. In some instances, LEGEND was unable to determine whether individual tiles were ACM or non-ACM. Due to the difficulties determining whether individual ceiling tiles are ACM or non-ACM and the possibility that the ACM ceiling tile is the original vintage (resulting in contaminated ceiling tile grid), LEGEND considers all ceiling tile in room 3 and hallway 88 to be ACM.

LEGEND identified ACM incinerator exhaust stack interior lining starting in room 6A, running up through 1<sup>st</sup> floor in a pipe chase west of room 109A, through 2<sup>nd</sup>- 9<sup>th</sup> floors in a pipe chase between rooms -10 and -09, and ending in room 1001. In room 1001, LEGEND identified an ACM penetration concrete around the base of the incinerator exhaust stack.

LEGEND visually quantified hard fittings on fiberglass insulation throughout the basement and room 1001 on steam, domestic water, and rainleader pipes. In addition, LEGEND identified access panels in rooms 112, 304E, 306E, 706E, and 988; however, throughout the remainder of floors 1-9 inaccessible ceilings and pipe chases prevented LEGEND from verifying the presence of all possible additional hard fittings. LEGEND observed areas with hard fittings on fiberglass insulation and areas with un-insulated pipes in the access panels in the building and assumes at least half of the inaccessible pipes in the building will have hard fittings on fiberglass insulation present. LEGEND recommends assuming an additional 50-100 hard fittings on each of the 1<sup>st</sup>, 2<sup>nd</sup>, 3<sup>rd</sup>, 4<sup>th</sup>, 5<sup>th</sup>, 6<sup>th</sup>, 7<sup>th</sup>, 8<sup>th</sup>, and 9<sup>th</sup> floors will be discovered during renovation or demolition activities.

LEGEND identified and sampled 3 separate types (homogeneous areas) of joint compound in Thompson Hall from: original vintage and 2 newer renovations. The original vintage joint compound tested positive for asbestos; it is on portions of the exterior walls of 1<sup>st</sup> floor and portions of the exterior walls and bathroom ceilings on 2<sup>nd</sup>, 3<sup>rd</sup>, 4<sup>th</sup>, 5<sup>th</sup>, 6<sup>th</sup>, 7<sup>th</sup>, 8<sup>th</sup>, and 9<sup>th</sup> floors. Refer to the ACM Locations Diagrams for exact locations.

**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
THOMPSON HALL (BLDG A068)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. <sup>1</sup>	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	-----------------------------	-------

**Room 2**

Hard Fittings on Fiberglass Insulation	0-10% Chrysotile 5% Amosite	47 fittings	Friable TSI	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	6	The asbestos hard fittings are throughout the room.
---	--------------------------------	-------------	----------------	------	--------------------------------------	---	---	---

**Room 3**

Hard Fittings on Fiberglass Insulation	0-10% Chrysotile 5% Amosite	23 fittings	Friable TSI	Good	Physical Air Erosion Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	7	The asbestos hard fittings are above ceiling tiles.
2'x4' Off-White Ceiling Tile with Lengthwise Fissures	3% Amosite	328 ft <sup>2</sup>	Friable Miscellaneous	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	Refer to Section 2.4 "Survey Notes" for further information.

**Room 4**

Hard Fittings on Fiberglass Insulation	0-10% Chrysotile 5% Amosite	143 fittings	Friable TSI	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	The asbestos hard fittings are throughout the room.
Hard Pack on Fiberglass Insulation	10% Chrysotile 5% Amosite	29 ea	Friable TSI	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	The asbestos hard pack is throughout the room.
Mag Block Pipe Insulation	25% Chrysotile 10% Amosite	151 ft	Friable TSI	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	The asbestos mag block pipe insulation is throughout the room.
Hard Fittings on Mag Block Insulation	Assumed	22 fittings	Friable TSI	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
Tank #68-004-21 Insulation	25% Amosite	10 ft <sup>2</sup>	Friable TSI	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	The asbestos tank insulation is in the southeast corner of the room.
Small Vertical Tank Insulation	25% Chrysotile 10% Amosite	4 ft <sup>2</sup>	Friable TSI	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	The asbestos tank insulation is in the southeast corner of the room.

\* = Non-Friable materials were not assessed

**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
THOMPSON HALL (BLDG A068)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. <sup>1</sup>	NOTES
Black AHU Putty	40% Chrysotile	3 AHUs	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos black AHU putty is on the air handler units on the south side of room 4.

**Room 4A**

Hard Fittings on Fiberglass Insulation	0-10% Chrysotile 5% Amosite	3 fittings	Friable TSI	Good	Physical Air Erosion Vibration	<input type="checkbox"/> ■ <input type="checkbox"/> <input type="checkbox"/> ■ <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> ■	6	The asbestos hard fittings are in the northeast corner of the room.
---	--------------------------------	------------	----------------	------	--------------------------------------	---	---	---

**Room 5**

Hard Fittings on Fiberglass Insulation	0-10% Chrysotile 5% Amosite	34 fittings	Friable TSI	Good	Physical Air Erosion Vibration	■ <input type="checkbox"/> <input type="checkbox"/> ■ <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> ■ <input type="checkbox"/>	5	The asbestos hard fittings on fiberglass are above ceiling tile on the west half of room 5.
Mastic for 12" Gray/White/Black Mottled Floor Tile	15% Chrysotile	26 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The mastic for the 12" floor tile contains asbestos; the floor tile is negative. They are in the northeast corner of the room.

**Room 6**

Hard Fittings on Fiberglass Insulation	0-10% Chrysotile 5% Amosite	40 fittings	Friable TSI	Good	Physical Air Erosion Vibration	<input type="checkbox"/> ■ <input type="checkbox"/> ■ <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> ■ <input type="checkbox"/>	5	The asbestos hard fittings are throughout the room.
---	--------------------------------	-------------	----------------	------	--------------------------------------	---	---	---

**Room 6A**

Hard Fittings on Fiberglass Insulation	0-10% Chrysotile 5% Amosite	19 fittings	Friable TSI	Good	Physical Air Erosion Vibration	<input type="checkbox"/> ■ <input type="checkbox"/> ■ <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> ■ <input type="checkbox"/>	5	The asbestos hard fittings are throughout the room.
Incinerator Breeching	25% Amosite	14 ft	Friable TSI	Good	Physical Air Erosion Vibration	<input type="checkbox"/> ■ <input type="checkbox"/> ■ <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> ■ <input type="checkbox"/>	5	None
Incinerator Exhaust Stack Interior Lining	15% Chrysotile 5% Amosite	1 ea	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	None

\* = Non-Friable materials were not assessed

**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
THOMPSON HALL (BLDG A068)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. <sup>1</sup>	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

**Hallway 88**

Hard Fittings on Fiberglass Insulation	0-10% Chrysotile 5% Amosite	6 fittings	Friable TSI	Good	Physical Air Erosion Vibration	■□□ ■□□ ■□□	7	The asbestos hard fittings are above ceiling tile in the hallway.
2'x4' Off-White Ceiling Tile with Lengthwise Fissures	3% Amosite	328 ft <sup>2</sup>	Friable Miscellaneous	Good	Physical Air Erosion Vibration	□□■ □■□ ■□□	6	Refer to Section 2.4 "Survey Notes" for further information.

**Room 102**

<del>9" Floor Tile and Mastic</del> Abated December 2014	Assumed	981 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	The asbestos 9" floor tile and mastic were assumed to be ACMs; the east side of the room is under carpet.
Joint Compound	3% Chrysotile	542 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	The asbestos joint compound is on the south and east walls.

**Room 103**

<del>Unknown Gray Floor Tile and Mastic</del> Abated June 2010	5-10% Chrysotile	505 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	The asbestos unknown gray floor tile and mastic are under carpet in room 103.
Joint Compound	3% Chrysotile	353 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	The asbestos joint compound is on the south and west walls.

**Room 108**

<del>9" Floor Tile and Mastic</del> Abated June 2018	Assumed	493 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	The 9" floor tile and mastic were assumed to be ACMs; they are under the carpet.
Joint Compound	3% Chrysotile	350 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	The asbestos joint compound is on the north and west walls.

\* = Non-Friable materials were not assessed

**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
THOMPSON HALL (BLDG A068)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. <sup>1</sup>	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	-----------------------------	-------

**Room 109**

Window Glazing	5% Chrysotile	1 window	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos window glaze is along the south wall next to the entry door.
----------------	---------------	----------	------------------------------	------	------	--	------	---

**Room 109B**

Joint Compound	3% Chrysotile	100 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north wall.
----------------	---------------	---------------------	------------------------------	------	------	--	------	---

**Room 109B1**

Joint Compound	3% Chrysotile	81 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the ceiling.
----------------	---------------	--------------------	------------------------------	------	------	--	------	--

**Room 109D**

Gray Sink Undercoating	15% Chrysotile	1 sink	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos gray sink undercoating is along the south wall.
Joint Compound	3% Chrysotile	350 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north and east walls.

**Room 110**

<del>9" Floor Tile and Mastic</del> Abated June 2018	Assumed	42 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
---	---------	--------------------	------------------------------	------	------	--	------	---

**Room 111**

<del>9" Floor Tile and Mastic</del> Abated December 2015	Assumed	388 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs; they are under the carpet.
---	---------	---------------------	------------------------------	------	------	--	------	--

\* = Non-Friable materials were not assessed



**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
THOMPSON HALL (BLDG A068)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. <sup>1</sup>	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Joint Compound	3% Chrysotile	163 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on east wall.
----------------	---------------	---------------------	------------------------------	------	------	--	------	--

**Room 112A**

Joint Compound	3% Chrysotile	94 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the north wall.
----------------	---------------	--------------------	------------------------------	------	------	--	------	---

**Room 112A1**

Joint Compound	3% Chrysotile	81 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the ceiling.
----------------	---------------	--------------------	------------------------------	------	------	--	------	--

**Lobby 188**

Lobby Ceiling Texture	3% Chrysotile	733 ft <sup>2</sup>	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	Refer to the ACM Locations Map for further information.
Heavy Wall Texture	3% Chrysotile	546 ft <sup>2</sup>	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	Refer to the ACM Locations Map for further information.

**Dorm Rooms 201, 203, 204, 205, 206, and 207**

9" Floor Tile and Mastic	Assumed	91 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Dorm Room Ceiling Texture	3% Chrysotile	91 ft <sup>2</sup> <b>each</b>	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	None
Joint Compound	3% Chrysotile	12 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the bathroom ceiling.

\* = Non-Friable materials were not assessed

**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
THOMPSON HALL (BLDG A068)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. <sup>1</sup>	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	-----------------------------	-------

**Dorm Room 202 and 208**

9" Floor Tile and Mastic	Assumed	133 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Dorm Room Ceiling Texture	3% Chrysotile	133 ft <sup>2</sup> <b>each</b>	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	None
Joint Compound	3% Chrysotile	12 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the bathroom ceiling.

**Dorm Rooms 201AB, 201CD, 202AB, 203AB, 203CD, 204CD, 205AB, 205CD, 206AB, 207AB, 207CD, and 208CD**

9" Floor Tile and Mastic	Assumed	187 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Dorm Room Ceiling Texture	3% Chrysotile	187 ft <sup>2</sup> <b>each</b>	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	None
Joint Compound	3% Chrysotile	94 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the exterior walls.

**Dorm Rooms 202CD, 204AB, 206CD, and 208AB**

9" Floor Tile and Mastic	Assumed	187 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Dorm Room Ceiling Texture	3% Chrysotile	187 ft <sup>2</sup> <b>each</b>	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	None
Joint Compound	3% Chrysotile	191 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the exterior walls.

\* = Non-Friable materials were not assessed

**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
THOMPSON HALL (BLDG A068)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. <sup>1</sup>	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

**Dorm Rooms 202E and 208E**

9" Floor Tile and Mastic	Assumed	121 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Dorm Room Ceiling Texture	3% Chrysotile	121 ft <sup>2</sup> <b>each</b>	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	None
Joint Compound	3% Chrysotile	49 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the exterior walls.

**Room 204E and 206E**

9" Floor Tile and Mastic	Assumed	121 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Joint Compound	3% Chrysotile	49 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the exterior wall.
Window Glazing	5% Chrysotile	2 window s <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	Refer to the ACM Locations Map for further information.

**Room 210** Abated May 2008

9" Floor Tile and Mastic	Assumed	30 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
--------------------------	---------	--------------------	------------------------------	------	------	--	------	---

**Lobby 288**

Lobby Ceiling Texture	3% Chrysotile	396 ft <sup>2</sup>	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	Refer to the ACM Locations Map for further information.
-----------------------	---------------	---------------------	----------------------	------	--	--	---	---

\* = Non-Friable materials were not assessed

**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
THOMPSON HALL (BLDG A068)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. <sup>1</sup>	NOTES
Heavy Wall Texture	3% Chrysotile	546 ft <sup>2</sup>	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	Refer to the ACM Locations Map for further information.

**Dorm Rooms 301, 303, 304, 305, 306, and 307**

9" Floor Tile and Mastic	Assumed	91 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Dorm Room Ceiling Texture	3% Chrysotile	91 ft <sup>2</sup> <b>each</b>	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6 None
Joint Compound	3% Chrysotile	12 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	The asbestos joint compound is on the bathroom ceilings.

**Dorm Rooms 302 and 308**

9" Floor Tile and Mastic	Assumed	133 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Dorm Room Ceiling Texture	3% Chrysotile	133 ft <sup>2</sup> <b>each</b>	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6 None
Joint Compound	3% Chrysotile	12 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	The asbestos joint compound is on the bathrooms ceilings.

**Dorm Rooms 301AB, 301CD, 302AB, 303AB, 303CD, 304CD, 305AB, 305CD, 306AB, 307AB, 307CD, and 308CD**

9" Floor Tile and Mastic	Assumed	187 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*	N/A*	The 9" floor tile and mastic were assumed to be ACMs.
--------------------------	---------	------------------------------------	------------------------------	------	------	------	---

\* = Non-Friable materials were not assessed

**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
THOMPSON HALL (BLDG A068)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. <sup>1</sup>	NOTES
Dorm Room Ceiling Texture	3% Chrysotile	187 ft <sup>2</sup> <b>each</b>	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
Joint Compound	3% Chrysotile	94 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	N/A*	The asbestos joint compound is on the exterior walls.

**Dorm Rooms 302CD, 304AB, 306CD, and 308AB**

9" Floor Tile and Mastic	Assumed	187 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Dorm Room Ceiling Texture	3% Chrysotile	187 ft <sup>2</sup> <b>each</b>	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
Joint Compound	3% Chrysotile	191 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	N/A*	The asbestos joint compound is on the exterior walls.

**Dorm Rooms 302E and 308E**

9" Floor Tile and Mastic	Assumed	121 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Dorm Room Ceiling Texture	3% Chrysotile	121 ft <sup>2</sup> <b>each</b>	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
Joint Compound	3% Chrysotile	49 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	N/A*	The asbestos joint compound is on the exterior walls.

\* = Non-Friable materials were not assessed

**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
THOMPSON HALL (BLDG A068)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. <sup>1</sup>	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

**Room 304E and 306E**

Window Glazing	5% Chrysotile	2 windows <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	Refer to the ACM Locations Map for further information.
9" Floor Tile and Mastic	Assumed	121 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs; room 304E had non-ACM 12" floor tile and mastic.
Joint Compound	3% Chrysotile	49 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the exterior walls.

**Room 310**

9" Floor Tile and Mastic	Assumed	30 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
--------------------------	---------	--------------------	------------------------------	------	------	--	------	---

**Lobby 388**

Lobby Ceiling Texture	3% Chrysotile	982 ft <sup>2</sup>	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	Refer to the ACM Locations Map for further information.
Heavy Wall Texture	3% Chrysotile	546 ft <sup>3</sup>	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	Refer to the ACM Locations Map for further information.

**Dorm Rooms 401, 403, 404, 405, 406, and 407**

9" Floor Tile and Mastic	Assumed	91 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Dorm Room Ceiling Texture	3% Chrysotile	91 ft <sup>2</sup> <b>each</b>	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	None

\* = Non-Friable materials were not assessed

**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
THOMPSON HALL (BLDG A068)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. <sup>1</sup>	NOTES
Joint Compound	3% Chrysotile	12 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the bathroom ceiling.

**Dorm Rooms 402 and 408**

9" Floor Tile and Mastic	Assumed	133 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Dorm Room Ceiling Texture	3% Chrysotile	133 ft <sup>2</sup> <b>each</b>	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	None
Joint Compound	3% Chrysotile	12 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the bathroom ceiling.

**Dorm Rooms 401AB, 301CD, 402AB, 403AB, 403CD, 404CD, 405AB, 405CD, 406AB, 407AB, 407CD, and 408CD**

9" Floor Tile and Mastic	Assumed	187 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Dorm Room Ceiling Texture	3% Chrysotile	187 ft <sup>2</sup> <b>each</b>	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	None
Joint Compound	3% Chrysotile	94 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the exterior walls.

**Dorm Rooms 402CD, 404AB, 406CD, and 408AB**

9" Floor Tile and Mastic	Assumed	187 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
--------------------------	---------	------------------------------------	------------------------------	------	------	--	------	---

\* = Non-Friable materials were not assessed

**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
THOMPSON HALL (BLDG A068)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. <sup>1</sup>	NOTES
Dorm Room Ceiling Texture	3% Chrysotile	187 ft <sup>2</sup> <b>each</b>	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
Joint Compound	3% Chrysotile	191 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	N/A*	The asbestos joint compound is on the exterior walls.

**Dorm Rooms 402E and 408E**

9" Floor Tile and Mastic	Assumed	121 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Dorm Room Ceiling Texture	3% Chrysotile	121 ft <sup>2</sup> <b>each</b>	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
Joint Compound	3% Chrysotile	49 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	N/A*	The asbestos joint compound is on the exterior walls.

**Room 404E and 406E**

Window Glazing	5% Chrysotile	2 windows <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	Refer to the ACM Locations Map for further information.
9" Floor Tile and Mastic	Assumed	121 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Joint Compound	3% Chrysotile	49 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the exterior walls.

\* = Non-Friable materials were not assessed



**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
THOMPSON HALL (BLDG A068)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. <sup>1</sup>	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

**Room 410**

9" Floor Tile and Mastic	Assumed	30 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
--------------------------	---------	--------------------	------------------------------	------	------	--	------	---

**Lobby 488**

Lobby Ceiling Texture	3% Chrysotile	396 ft <sup>2</sup>	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	Refer to the ACM Locations Map for further information.
Heavy Wall Texture	3% Chrysotile	546 ft <sup>3</sup>	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	Refer to the ACM Locations Map for further information.

**Dorm Rooms 501, 503, 504, 505, 506, and 507**

9" Floor Tile and Mastic	Assumed	91 ft <sup>2</sup> each	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Dorm Room Ceiling Texture	3% Chrysotile	91 ft <sup>2</sup> each	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	None
Joint Compound	3% Chrysotile	12 ft <sup>2</sup> each	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the bathroom ceiling.

**Dorm Rooms 502 and 508**

9" Floor Tile and Mastic	Assumed	133 ft <sup>2</sup> each	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Dorm Room Ceiling Texture	3% Chrysotile	133 ft <sup>2</sup> each	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	None

\* = Non-Friable materials were not assessed

**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
THOMPSON HALL (BLDG A068)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. <sup>1</sup>	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

Joint Compound	3% Chrysotile	12 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the bathroom ceiling.
----------------	---------------	-----------------------------------	------------------------------	------	------	--	------	---

**Dorm Rooms 501AB, 501CD, 502AB, 503AB, 503CD, 504CD, 505AB, 505CD, 506AB, 507AB, 507CD, and 508CD**

9" Floor Tile and Mastic	Assumed	187 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Dorm Room Ceiling Texture	3% Chrysotile	187 ft <sup>2</sup> <b>each</b>	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	None
Joint Compound	3% Chrysotile	94 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the exterior walls.

**Dorm Rooms 502CD, 504AB, 506CD, and 508AB**

9" Floor Tile and Mastic	Assumed	187 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Dorm Room Ceiling Texture	3% Chrysotile	187 ft <sup>2</sup> <b>each</b>	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	None
Joint Compound	3% Chrysotile	191 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the exterior walls.

**Dorm Rooms 502E and 508E**

9" Floor Tile and Mastic	Assumed	121 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
--------------------------	---------	------------------------------------	------------------------------	------	------	--	------	---

\* = Non-Friable materials were not assessed

**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
THOMPSON HALL (BLDG A068)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. <sup>1</sup>	NOTES
Dorm Room Ceiling Texture	3% Chrysotile	121 ft <sup>2</sup> <b>each</b>	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
Joint Compound	3% Chrysotile	49 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	N/A*	The asbestos joint compound is on the exterior walls.

**Room 504E and 506E**

Window Glazing	5% Chrysotile	2 windows <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	Refer to the ACM Locations Map for further information.
9" Floor Tile and Mastic	Assumed	121 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs; room 504E has 12" floor tile with ACM mastic.
Joint Compound	3% Chrysotile	49 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the exterior walls.

**Room 510**

9" Floor Tile and Mastic	Assumed	30 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
-----------------------------	---------	--------------------	------------------------------	------	------	--	------	---

**Lobby 588**

Lobby Ceiling Texture	3% Chrysotile	982 ft <sup>2</sup>	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	Refer to the ACM Locations Map for further information.
Heavy Wall Texture	3% Chrysotile	546 ft <sup>3</sup>	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	Refer to the ACM Locations Map for further information.

\* = Non-Friable materials were not assessed

**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
THOMPSON HALL (BLDG A068)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. <sup>1</sup>	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

**Dorm Rooms 601, 603, 604, 605, 606, and 607**

9" Floor Tile and Mastic	Assumed	91 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Dorm Room Ceiling Texture	3% Chrysotile	91 ft <sup>2</sup> <b>each</b>	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	None
Joint Compound	3% Chrysotile	12 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the bathroom ceiling.

**Dorm Rooms 602 and 608**

9" Floor Tile and Mastic	Assumed	133 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Dorm Room Ceiling Texture	3% Chrysotile	133 ft <sup>2</sup> <b>each</b>	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	None
Joint Compound	3% Chrysotile	12 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the bathroom ceiling.

**Dorm Rooms 601AB, 601CD, 602AB, 603AB, 603CD, 604CD, 605AB, 605CD, 606AB, 607AB, 607CD, and 608CD**

9" Floor Tile and Mastic	Assumed	187 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Dorm Room Ceiling Texture	3% Chrysotile	187 ft <sup>2</sup> <b>each</b>	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	None
Joint Compound	3% Chrysotile	94 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the exterior walls.

\* = Non-Friable materials were not assessed

**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
THOMPSON HALL (BLDG A068)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. <sup>1</sup>	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

**Dorm Rooms 602CD, 604AB, 606CD, and 608AB**

9" Floor Tile and Mastic	Assumed	187 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Dorm Room Ceiling Texture	3% Chrysotile	187 ft <sup>2</sup> <b>each</b>	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	None
Joint Compound	3% Chrysotile	191 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the exterior walls.

**Dorm Rooms 602E and 608E**

9" Floor Tile and Mastic	Assumed	121 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Dorm Room Ceiling Texture	3% Chrysotile	121 ft <sup>2</sup> <b>each</b>	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	None
Joint Compound	3% Chrysotile	49 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the exterior walls.

**Room 604E and 606E**

Window Glazing	5% Chrysotile	2 windows <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	Refer to the ACM Locations Map for further information.
9" Floor Tile and Mastic	Assumed	121 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs; room 604E has 12" floor tile with ACM mastic.
Joint Compound	3% Chrysotile	49 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the exterior walls.

\* = Non-Friable materials were not assessed

**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
THOMPSON HALL (BLDG A068)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. <sup>1</sup>	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

**Room 610**

9" Floor Tile and Mastic	Assumed	30 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
--------------------------	---------	--------------------	---------------------------	------	------	--	------	---

**Lobby 688**

Lobby Ceiling Texture	3% Chrysotile	396 ft <sup>2</sup>	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	Refer to the ACM Locations Map for further information.
Heavy Wall Texture	3% Chrysotile	546 ft <sup>3</sup>	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	Refer to the ACM Locations Map for further information.

**Dorm Rooms 701, 703, 704, 705, 706, and 707**

9" Floor Tile and Mastic	Assumed	91 ft <sup>2</sup> each	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Dorm Room Ceiling Texture	3% Chrysotile	91 ft <sup>2</sup> each	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	None
Joint Compound	3% Chrysotile	12 ft <sup>2</sup> each	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the bathroom ceiling.

**Dorm Rooms 702 and 708**

9" Floor Tile and Mastic	Assumed	133 ft <sup>2</sup> each	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Dorm Room Ceiling Texture	3% Chrysotile	133 ft <sup>2</sup> each	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	None

\* = Non-Friable materials were not assessed

**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
THOMPSON HALL (BLDG A068)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. <sup>1</sup>	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	-----------------------------	-------

Joint Compound	3% Chrysotile	12 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the exterior walls.
----------------	---------------	-----------------------------------	------------------------------	------	------	--	------	---

**Dorm Rooms 701AB, 701CD, 702AB, 703AB, 703CD, 704CD, 705AB, 705CD, 706AB, 707AB, 707CD, and 708CD**

9" Floor Tile and Mastic	Assumed	187 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Dorm Room Ceiling Texture	3% Chrysotile	187 ft <sup>2</sup> <b>each</b>	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Joint Compound	3% Chrysotile	94 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the exterior walls.

**Dorm Rooms 702CD, 704AB, 706CD, and 708AB**

9" Floor Tile and Mastic	Assumed	187 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Dorm Room Ceiling Texture	3% Chrysotile	187 ft <sup>2</sup> <b>each</b>	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Joint Compound	3% Chrysotile	191 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the exterior walls.

**Dorm Rooms 702E and 708E**

9" Floor Tile and Mastic	Assumed	121 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
--------------------------	---------	------------------------------------	------------------------------	------	------	--	------	---

\* = Non-Friable materials were not assessed

**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
THOMPSON HALL (BLDG A068)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. <sup>1</sup>	NOTES
Dorm Room Ceiling Texture	3% Chrysotile	121 ft <sup>2</sup> <b>each</b>	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
Joint Compound	3% Chrysotile	49 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	N/A*	The asbestos joint compound is on the exterior walls.

**Room 704E and 706E**

Window Glazing	5% Chrysotile	2 windows <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	Refer to the ACM Locations Map for further information.
9" Floor Tile and Mastic	Assumed	121 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Joint Compound	3% Chrysotile	49 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the exterior walls.

**Room 710**

9" Floor Tile and Mastic	Assumed	30 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
-----------------------------	---------	--------------------	------------------------------	------	------	--	------	---

**Lobby 788**

Lobby Ceiling Texture	3% Chrysotile	982 ft <sup>2</sup>	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	Refer to the ACM Locations Map for further information.
Heavy Wall Texture	3% Chrysotile	546 ft <sup>3</sup>	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	Refer to the ACM Locations Map for further information.

\* = Non-Friable materials were not assessed



**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
THOMPSON HALL (BLDG A068)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. <sup>1</sup>	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

**Dorm Rooms 801, 803, 804, 805, 806, and 807**

9" Floor Tile and Mastic	Assumed	91 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Dorm Room Ceiling Texture	3% Chrysotile	91 ft <sup>2</sup> <b>each</b>	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	None
Joint Compound	3% Chrysotile	12 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the bathroom ceiling.

**Dorm Rooms 802 and 808**

9" Floor Tile and Mastic	Assumed	133 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Dorm Room Ceiling Texture	3% Chrysotile	133 ft <sup>2</sup> <b>each</b>	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	None
Joint Compound	3% Chrysotile	12 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the bathroom ceiling.

**Dorm Rooms 801AB, 801CD, 802AB, 803AB, 803CD, 804CD, 805AB, 805CD, 806AB, 807AB, 807CD, and 808CD**

9" Floor Tile and Mastic	Assumed	187 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Dorm Room Ceiling Texture	3% Chrysotile	187 ft <sup>2</sup> <b>each</b>	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	None
Joint Compound	3% Chrysotile	94 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the exterior walls.

\* = Non-Friable materials were not assessed

**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
THOMPSON HALL (BLDG A068)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. <sup>1</sup>	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

**Dorm Rooms 802CD, 804AB, 806CD, and 808AB**

9" Floor Tile and Mastic	Assumed	187 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Dorm Room Ceiling Texture	3% Chrysotile	187 ft <sup>2</sup> <b>each</b>	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	None
Joint Compound	3% Chrysotile	191 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the exterior walls.

**Dorm Rooms 802E and 808E**

9" Floor Tile and Mastic	Assumed	121 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Dorm Room Ceiling Texture	3% Chrysotile	121 ft <sup>2</sup> <b>each</b>	Friable Surfacing	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		6	None
Joint Compound	3% Chrysotile	49 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the exterior walls.

**Room 804E and 806E**

Window Glazing	5% Chrysotile	2 windows <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	Refer to the ACM Locations Map for further information.
9" Floor Tile and Mastic	Assumed	121 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Joint Compound	3% Chrysotile	49 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the exterior walls.

\* = Non-Friable materials were not assessed

**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
THOMPSON HALL (BLDG A068)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. <sup>1</sup>	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	------------------------------	-------

**Room 810**

9" Floor Tile and Mastic	Assumed	30 ft <sup>2</sup>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
--------------------------	---------	--------------------	---------------------------	------	------	--	------	---

**Lobby 888**

Lobby Ceiling Texture	3% Chrysotile	396 ft <sup>2</sup>	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	Refer to the ACM Locations Map for further information.
Heavy Wall Texture	3% Chrysotile	546 ft <sup>3</sup>	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	Refer to the ACM Locations Map for further information.

**Dorm Rooms 901, 903, 904, 905, 906, and 907**

9" Floor Tile and Mastic	Assumed	91 ft <sup>2</sup> each	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Dorm Room Ceiling Texture	3% Chrysotile	91 ft <sup>2</sup> each	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	None
Joint Compound	3% Chrysotile	12 ft <sup>2</sup> each	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the bathroom ceiling.

**Dorm Rooms 902 and 908**

9" Floor Tile and Mastic	Assumed	133 ft <sup>2</sup> each	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Dorm Room Ceiling Texture	3% Chrysotile	133 ft <sup>2</sup> each	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	None

\* = Non-Friable materials were not assessed

**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
THOMPSON HALL (BLDG A068)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. <sup>1</sup>	NOTES
--------------	---------------	------------------	----------	-----------------------	---------------------	--------------------	-----------------------------	-------

Joint Compound	3% Chrysotile	12 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the bathroom ceiling.
----------------	---------------	-----------------------------------	------------------------------	------	------	--	------	---

**Dorm Rooms 901AB, 901CD, 902AB, 903AB, 903CD, 904CD, 905AB, 905CD, 906AB, 907AB, 907CD, and 908CD**

9" Floor Tile and Mastic	Assumed	187 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Dorm Room Ceiling Texture	3% Chrysotile	187 ft <sup>2</sup> <b>each</b>	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	None
Joint Compound	3% Chrysotile	94 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the exterior walls.

**Dorm Rooms 902CD, 904AB, 906CD, and 908AB**

9" Floor Tile and Mastic	Assumed	187 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Dorm Room Ceiling Texture	3% Chrysotile	187 ft <sup>2</sup> <b>each</b>	Friable Surfacing	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	6	None
Joint Compound	3% Chrysotile	191 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos joint compound is on the exterior walls.

**Dorm Rooms 902E and 908E**

9" Floor Tile and Mastic	Assumed	121 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
--------------------------	---------	------------------------------------	------------------------------	------	------	--	------	---

\* = Non-Friable materials were not assessed

**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
THOMPSON HALL (BLDG A068)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. <sup>1</sup>	NOTES
Dorm Room Ceiling Texture	3% Chrysotile	121 ft <sup>2</sup> <b>each</b>	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	None
Joint Compound	3% Chrysotile	49 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	N/A*	The asbestos joint compound is on the exterior walls.

**Room 904E and 906E**

Window Glazing	5% Chrysotile	2 windows <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	N/A*	Refer to the ACM Locations Map for further information.
9" Floor Tile and Mastic	Assumed	121 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Joint Compound	3% Chrysotile	49 ft <sup>2</sup> <b>each</b>	Non-Friable Miscellaneous	N/A*	N/A*	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	N/A*	The asbestos joint compound is on the exterior walls.

**Lobby 988**

Lobby Ceiling Texture	3% Chrysotile	912 ft <sup>2</sup>	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	Refer to the ACM Locations Map for further information.
Heavy Wall Texture	3% Chrysotile	546 ft <sup>3</sup>	Friable Surfacing	Good	Physical	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	6	Refer to the ACM Locations Map for further information.

**Room 1001**

Hard Fittings on Fiberglass Insulation	0-10% Chrysotile 5% Amosite	150 fittings	Friable TSI	Good	Physical	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	6	The asbestos hard fittings are along all exterior walls in room 1001.
					Air Erosion	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		
					Vibration	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		

\* = Non-Friable materials were not assessed

**LEGEND TECHNICAL SERVICES, INC.**  
ACM LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)  
THOMPSON HALL (BLDG A068)

ROOM/ ACM	ASBESTOS TYPE	EST. QUANTITY	ACM TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. <sup>1</sup>	NOTES
Rainleader Bowl Insulation	10% Amosite	2 ea	Friable TSI	Good	Physical <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		6	Refer to the ACM Locations map for further information.
Penetration Concrete (at base of incinerator exhaust)	20% Chrysotile	1 ea	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos penetration concrete is at the base of the incinerator exhaust in room 1001.
Incinerator Exhaust Stack Interior Lining	15% Chrysotile 5% Amosite	1 ea	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	None

**Exterior**

Building Seam Caulk	2% Chrysotile	180 ft.	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos caulk is at the base of room 1001's exterior walls and around an air vent on the north end of the penthouse.
Penetration Putty	5% Chrysotile	1 ea	Non-Friable Miscellaneous	N/A*	N/A*		N/A*	The penetration putty is on the south end of the exterior of room 1001.

<sup>1</sup>Assessment Categories:

- |   |   |
|---|---|
| 1) Damaged or Significantly Damaged TSI ACM                   | 5) ACM with Potential for Damage                      |
| 2) Damaged Friable Surfacing ACM                              | 6) ACM with Potential for Significant Damage          |
| 3) Significantly Damaged Friable Surfacing ACM                | 8) Any Remaining Friable ACM or Friable Suspected ACM |
| 4) Damaged or Significantly Damaged Friable Miscellaneous ACM |   |

**End**