

NARRATIVE REPORT

1.0 BUILDING INFORMATION

South Weible Hall was originally constructed in 1965; the building has had no major renovations.

South Weible Hall is a four-story, 38,610 ft² building which primarily serves as dormitory areas for students.

The interior floor finishes included floor tile, carpet, ceramic tile, concrete, and epoxy flooring; the interior wall finishes included plaster, concrete block, concrete, ceramic block, and gypsum wallboard; and the interior ceiling finishes included plaster, ceiling tile, gypsum wallboard, and metal. The roofing system is a flat rubber-membrane roof and the exterior of the structure is brick.

The piping systems were insulated; fiberglass insulation (both with and without hard fittings) is located in the building. Steam and domestic water enter the building from North Weible Hall (A057) in the north end of the tunnel. HVAC systems located in the building consisted of steam radiators and a forced air furnace equipped with heating/cooling coils.

2.0 ASBESTOS SURVEY INFORMATION

South Weible Hall was surveyed as part of a larger project on NDSU's Fargo, ND Campus. This report is part of "Volume 6" of a nine volume series. This report includes building specific information only; please refer to the opening section of "Volume 6" for methodologies, definitions, and other pertinent supporting information.

LEGEND was granted full access to South Weible Hall during the initial walk-through and sampling of the building. During subsequent walk-throughs of the building, for resampling and reporting purposes, LEGEND was granted access to the common areas and to 2-4 dormitory rooms per floor, only. For the remainder of the dormitory rooms, LEGEND identified the locations of ACMs using survey notes taken during the initial walk-through of the building.

A total of 71 samples were collected from suspect asbestos-containing materials (ACM) from South Weible Hall on May 22, 2007 and an additional 3 samples were collected on March 13, 2008. Laboratory analysis results indicate **11 of these samples tested positive for asbestos.**

2.1 Suspect Materials Identified and Sampled

Ceiling Tile (5 types)	Ceiling Texture
Textured Paint	Gypsum Wallboard
Joint Compound	Hard Plaster- Skimcoat (2 types)
Hard Plaster- Basecoat (2 types)	Fiberglass Panel Adhesive
Tank Insulation (4 types)	Hard Fittings on Fiberglass Insulation
Floor Tile (2 types)	Floor Tile Mastic (2 types)
Pinboard Backing	Baseboard Adhesive
Carpet Mastic (2 types)	Sink Undercoating
HVAC Canvas Connector	Penetration Putty
Bathroom Sink Caulk	Window Caulk
Exterior Building Seam Caulk (3 types)	Exterior Penetration Putty
Exterior Window Caulk	Exterior Door Caulk

Exterior Foundation Caulk
Hard Pack on Fiberglass Insulation

Window Glazing

The Asbestos Bulk Sample Results Table includes asbestos sampling data.

2.2 **Asbestos Containing Materials**

Large Red Tank Insulation
Small Horizontal Yellow Tank Insulation
Small Vertical Blue Tank Insulation
Vertical Red Tank Insulation
Mastic for 12" White Floor Tile w/ Brown Marks
Carpet Mastic (1 type)
Black Sink Undercoating
Window Glazing
9" Floor Tile and Mastic (assumed)

The ACM Locations/ Friable Materials Assessments Table includes ACM locations data.

2.3 **Cost Estimates**

Legend Technical Services Inc. estimates abatement costs (removal & disposal) of ACM for South Weible Hall as follows:

ACM	QUANTITY	UNIT COST	TOTAL COST
Asbestos Tank Insulation	50 ft ²	\$100.00/ft ²	\$5,000.00
Asbestos Floor Tile and/or Mastic	31,875 ft ²	\$4.00/ft ²	\$127,500.00
Asbestos Carpet Mastic	930 ft ²	\$4.00/ft ²	\$3,720.00
Asbestos Sink Undercoating	1 ea	\$150.00/ea	\$150.00
Asbestos Window Glazing	48 ea	\$225.00/ea	\$10,800.00
Total Estimated Abatement Costs:			\$142,670.00

LEGEND TECHNICAL SERVICES, INC.
ACMS LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
SOUTH WEIBLE HALL (BUILDING A061)

ROOM/ ACMS	ASBESTOS TYPE	EST. QUANTITY	ACMS TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
---------------	---------------	------------------	-----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 2

9" Floor Tile and Mastic Abated June 2015	Assumed	909 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Black Sink Undercoating Abated June 2015	5% Chrysotile	1 sink	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos containing sink undercoating is on the sink along the west wall.
Window Glazing	3% Chrysotile	4 windows	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos window glazing is on the 4 windows in the northwest corner of the room.

Room 2A **Abated June 2015**

9" Floor Tile and Mastic	Assumed	117 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
-------------------------------------	---------	---------------------	------------------------------	------	------	--	------	---

Room 2B **Abated June 2015**

9" Floor Tile and Mastic	Assumed	120 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
-------------------------------------	---------	---------------------	------------------------------	------	------	--	------	---

Room 3 **Abated June 2015**

9" Floor Tile and Mastic	Assumed	83 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
-------------------------------------	---------	--------------------	------------------------------	------	------	--	------	---

Room 4A

Large Red Tank Insulation Abated for demo/removal May 2009	25% Amosite	32 ft ²	Friable TSI	Good	Physical <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Air Erosion <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> Vibration <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>		6	The asbestos hard packed tank insulation is on the large red tank in the middle of the room.
---	-------------	--------------------	----------------	------	--	--	---	--

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACMS LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
SOUTH WEIBLE HALL (BUILDING A061)

ROOM/ ACMS	ASBESTOS TYPE	EST. QUANTITY	ACMS TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
Vertical Red Tank Insulation	25% Amosite	6 ft ²	Friable TSI	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	6	The asbestos hard packed tank insulation is on the vertical red tank along the north wall.
Small Vertical Blue Tank Insulation	25% Amosite	2 ft ²	Friable TSI	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	6	The asbestos hard packed tank insulation is on small vertical blue tank directly south of the large red tank.
Vertical Yellow Tank Insulation	25% Amosite	10 ft ²	Friable TSI	Good	Physical Air Erosion Vibration	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	6	The asbestos hard packed tank insulation is on the vertical yellow tank on the southwest end.

Room 8 Abated June 2015

9" Floor Tile and Mastic	Assumed	448 ft ²	Non-friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic were assumed to be ACMs.
---	---------	---------------------	------------------------------	------	------	------	------	---

Room 9 Abated June 2015

9" Floor Tile and Mastic	Assumed	79 ft ²	Non-friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic were assumed to be ACMs.
---	---------	--------------------	------------------------------	------	------	------	------	---

Hallway 88 Abated June 2015

9" Floor Tile and Mastic	Assumed	237 ft ²	Non-friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic were assumed to be ACMs.
---	---------	---------------------	------------------------------	------	------	------	------	---

Dorm Room 131 Abated July 2011

9" Floor Tile and Mastic	Assumed	225 ft ²	Non-friable Miscellaneous	N/A*	N/A*	N/A*	N/A*	The 9" floor tile and mastic were assumed to be ACMs; they are under the carpet in the room.
---	---------	---------------------	------------------------------	------	------	------	------	--

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACMS LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
SOUTH WEIBLE HALL (BUILDING A061)

ROOM/ ACMS	ASBESTOS TYPE	EST. QUANTITY	ACMS TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
---------------	---------------	------------------	-----------	-----------------------	---------------------	--------------------	-----------------------------	-------

Dorm Rooms 132, 133, 134, 135, 136, 137, 138, 139, 140, 141, 142, 143, 144, 145, 146, 147, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, and 161.

9" Floor Tile and Mastic	Abated July 2011	ft ² each	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs; they are under the carpet in these dorm rooms.
-------------------------------------	------------------	-------------------------	------------------------------	------	------	--	------	--

Dorm Room 148 Abated July 2011

Mastic for 12" White Floor Tile with Brown Marks	8% Chrysotile	180 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The mastic contains asbestos, the floor tile is negative. They are under carpet in this room.
---	---------------	---------------------	------------------------------	------	------	--	------	---

Room 149 Abated July 2011

Mastic for 12" White Floor Tile with Brown Marks	8% Chrysotile	34 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The mastic contains asbestos, the floor tile is negative.
---	---------------	--------------------	------------------------------	------	------	--	------	---

Room 149A Abated July 2011

Mastic for 12" White Floor Tile with Brown Marks	8% Chrysotile	34 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The mastic contains asbestos, the floor tile is negative.
---	---------------	--------------------	------------------------------	------	------	--	------	---

Room 149B Abated July 2011

Mastic for 12" White Floor Tile with Brown Marks	8% Chrysotile	60 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The mastic contains asbestos, the floor tile is negative.
---	---------------	--------------------	------------------------------	------	------	--	------	---

Dorm Room 150 Abated July 2011

Mastic for 12" White Floor Tile with Brown Marks	8% Chrysotile	173 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The mastic contains asbestos, the floor tile is negative. They are under carpet in this room.
---	---------------	---------------------	------------------------------	------	------	--	------	---

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACMS LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
SOUTH WEIBLE HALL (BUILDING A061)

ROOM/ ACMS	ASBESTOS TYPE	EST. QUANTITY	ACMS TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
Room 163 Abated July 2011								
9" Floor Tile and Mastic	Assumed	288 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs; they are under the carpet in the room.
Room 163A Abated June 2012 Room removed and 164 made larger.								
9" Floor Tile and Mastic	Assumed	45 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Room 163B Abated July 2011								
9" Floor Tile and Mastic	Assumed	25 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs; they are under the carpet in the room.
Dorm Room 163C Abated July 2011								
9" Floor Tile and Mastic	Assumed	113 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs; they are under the carpet in the room.
Room 163D Abated July 2011								
9" Floor Tile and Mastic	Assumed	31 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs; they are under the carpet in the room.
Room 170								
9" Floor Tile and Mastic	Assumed	310 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs; they are under the carpet in the room.
Abated June 2018								
Carpet Mastic	2% Chrysotile	310 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	None.
Abated June 2018								

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACMS LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
SOUTH WEIBLE HALL (BUILDING A061)

ROOM/ ACMS	ASBESTOS TYPE	EST. QUANTITY	ACMS TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
Window Glazing	3% Chrysotile	12 windows	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos window glazing is on the 6 windows on the east and 6 windows on the west side of the room.
Room 172 Abated July 2011								
9" Floor Tile and Mastic	Assumed	9 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs; they are under the carpet in the room.
Room 174 Abated July 2011								
9" Floor Tile and Mastic	Assumed	86 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs; they are under the carpet in the room.
Room 176 Abated May 2019 along with any fittings behind structures as part of restroom remodel								
9" Floor Tile and Mastic	Assumed	295 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs; part of the room has carpet over the floor tile.
Room 178 Abated July 2011								
9" Floor Tile and Mastic	Assumed	91 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Room 182 Abated July 2011								
9" Floor Tile and Mastic	Assumed	58 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACMS LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
SOUTH WEIBLE HALL (BUILDING A061)

ROOM/ ACMS	ASBESTOS TYPE	EST. QUANTITY	ACMS TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
---------------	---------------	------------------	-----------	-----------------------	---------------------	--------------------	-----------------------------	-------

Room 184 Abated July 2011

9" Floor Tile and Mastic	Assumed	9 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs; they are under the carpet in the room.
--------------------------	---------	-------------------	------------------------------	------	------	--	------	--

Room 186 Abated July 2011

9" Floor Tile and Mastic	Assumed	29 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
--------------------------	---------	--------------------	------------------------------	------	------	--	------	---

Hallway 188 (including all hallways on 1st floor)

9" Floor Tile and Mastic	Assumed	2,453 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Window Glazing	3% Chrysotile	8 windows	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos window glazing is on the 4 window by room 163 and the 4 windows by room 132.

Room 190 Abated July 2011

9" Floor Tile and Mastic	Assumed	35 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
--------------------------	---------	--------------------	------------------------------	------	------	--	------	---

1st Floor Elevator Entry

9" Floor Tile and Mastic	Assumed	25 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
--------------------------	---------	--------------------	------------------------------	------	------	--	------	---

Dorm Rooms 231, 247, 248, and 264

9" Floor Tile and Mastic	Assumed	302 ft ² each	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
--------------------------	---------	-----------------------------	------------------------------	------	------	--	------	---

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACMS LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
SOUTH WEIBLE HALL (BUILDING A061)

ROOM/ ACMS	ASBESTOS TYPE	EST. QUANTITY	ACMS TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
---------------	---------------	------------------	-----------	-----------------------	---------------------	--------------------	------------------------------	-------

Dorm Rooms 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, and 263

9" Floor Tile and Mastic	Assumed	176 ft ² each	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
--------------------------	---------	-----------------------------	------------------------------	------	------	--	------	---

Room 265

9" Floor Tile and Mastic	Assumed	125 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
-------------------------------------	---------	---------------------	------------------------------	------	------	--	------	---

Room 270

9" Floor Tile and Mastic	Assumed	310 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs; they are under the carpet in the room.
Carpet Mastic	2% Chrysotile	310 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	None.
Window Glazing	3% Chrysotile	12 windows	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos window glazing is on the 6 windows on the east and 6 on the west side of the room.

Room 272

9" Floor Tile and Mastic	Assumed	9 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
--------------------------	---------	-------------------	------------------------------	------	------	--	------	---

Room 274

9" Floor Tile and Mastic	Assumed	233 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
--------------------------	---------	---------------------	------------------------------	------	------	--	------	---

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACMS LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
SOUTH WEIBLE HALL (BUILDING A061)

ROOM/ ACMS	ASBESTOS TYPE	EST. QUANTITY	ACMS TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
---------------	---------------	------------------	-----------	-----------------------	---------------------	--------------------	------------------------------	-------

Room 276 Abated May 2019 along with any fittings behind structures as part of restroom remodel

9" Floor Tile and Mastic	Assumed	295 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
--------------------------	---------	---------------------	------------------------------	------	------	--	------	---

Room 278

9" Floor Tile and Mastic	Assumed	91 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
--------------------------	---------	--------------------	------------------------------	------	------	--	------	---

Room 282

9" Floor Tile and Mastic	Assumed	58 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
--------------------------	---------	--------------------	------------------------------	------	------	--	------	---

Room 284

9" Floor Tile and Mastic	Assumed	9 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
--------------------------	---------	-------------------	------------------------------	------	------	--	------	---

Room 286

9" Floor Tile and Mastic	Assumed	29 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
--------------------------	---------	--------------------	------------------------------	------	------	--	------	---

Hallway 288

9" Floor Tile and Mastic	Assumed	1,706 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
--------------------------	---------	-----------------------	------------------------------	------	------	--	------	---

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACMS LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
SOUTH WEIBLE HALL (BUILDING A061)

ROOM/ ACMS	ASBESTOS TYPE	EST. QUANTITY	ACMS TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
Room 290								
9" Floor Tile and Mastic	Assumed	35 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
2nd Floor Elevator Entry								
9" Floor Tile and Mastic	Assumed	27 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Dorm Rooms 331, 347, 348, and 364								
9" Floor Tile and Mastic	Assumed	302 ft ² each	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Dorm Rooms 332, 333, 334, 335, 336, 337, 338, 339, 340, 341, 342, 343, 344, 345, 346, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, and 363.								
9" Floor Tile and Mastic	Assumed	176 ft ² each	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Room 365								
9" Floor Tile and Mastic	Assumed	125 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
Room 370								
9" Floor Tile and Mastic	Assumed	310 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs; they are under the carpet in this room.
	Abated June 2018							

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACMS LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
SOUTH WEIBLE HALL (BUILDING A061)

ROOM/ ACMS	ASBESTOS TYPE	EST. QUANTITY	ACMS TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
Carpet Mastic Abated June 2018	2% Chrysotile	310 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	None
Window Glazing	3% Chrysotile	12 windows	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The asbestos window glazing is on the 6 windows on the east and 6 on the west side of the room.

Room 372

9" Floor Tile and Mastic	Assumed	9 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
--------------------------	---------	-------------------	------------------------------	------	------	--	------	---

Room 374

9" Floor Tile and Mastic	Assumed	233 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
--------------------------	---------	---------------------	------------------------------	------	------	--	------	---

Room 376 **Abated May 2019 along with any fittings behind structures as part of restroom remodel**

9" Floor Tile and Mastic	Assumed	295 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
-------------------------------------	---------	---------------------	------------------------------	------	------	--	------	---

Room 378

9" Floor Tile and Mastic	Assumed	91 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
--------------------------	---------	--------------------	------------------------------	------	------	--	------	---

Room 382

9" Floor Tile and Mastic	Assumed	58 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
--------------------------	---------	--------------------	------------------------------	------	------	--	------	---

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACMS LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
 SOUTH WEIBLE HALL (BUILDING A061)

ROOM/ ACMS	ASBESTOS TYPE	EST. QUANTITY	ACMS TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSES. CAT. ¹	NOTES
---------------	---------------	------------------	-----------	-----------------------	---------------------	--------------------	-----------------------------	-------

Room 384

9" Floor Tile and Mastic	Assumed	9 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
--------------------------	---------	-------------------	------------------------------	------	------	--	------	---

Room 386

9" Floor Tile and Mastic	Assumed	29 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
--------------------------	---------	--------------------	------------------------------	------	------	--	------	---

Hallway 388

9" Floor Tile and Mastic	Assumed	1,706 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
--------------------------	---------	-----------------------	------------------------------	------	------	--	------	---

Room 390

9" Floor Tile and Mastic	Assumed	35 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
--------------------------	---------	--------------------	------------------------------	------	------	--	------	---

3rd Floor Elevator Entry

9" Floor Tile and Mastic	Assumed	27 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs.
--------------------------	---------	--------------------	------------------------------	------	------	--	------	---

North Stairway (Basement[†] through 3rd floors)

9" Floor Tile and Mastic	Assumed	672 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMs, includes stairwell.
--------------------------	---------	---------------------	------------------------------	------	------	--	------	---

* = Non-Friable materials were not assessed

LEGEND TECHNICAL SERVICES, INC.
ACMS LOCATIONS/FRIABLE MATERIALS ASSESSMENTS TABLE

LEGEND No. 0700048 (NDSU)
 SOUTH WEIBLE HALL (BUILDING A061)

ROOM/ ACMS	ASBESTOS TYPE	EST. QUANTITY	ACMS TYPE	MATERIAL CONDITION	DAMAGE POTENTIAL	LOW MOD HIGH	ASSESS. CAT. ¹	NOTES
---------------	---------------	------------------	-----------	-----------------------	---------------------	--------------------	------------------------------	-------

South Stairway (Basement through 3rd floors; including stairway to roof hatch))

9" Floor Tile and Mastic	Assumed	639 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMS, includes stairwell.
--------------------------	---------	---------------------	------------------------------	------	------	--	------	---

Elevator

9" Floor Tile and Mastic	Assumed	29 ft ²	Non-friable Miscellaneous	N/A*	N/A*		N/A*	The 9" floor tile and mastic were assumed to be ACMS.
--------------------------	---------	--------------------	------------------------------	------	------	--	------	---

¹Assessment Categories:

- | | |
|--|---|
| 1) Damaged or Significantly Damaged TSI ACMS | 5) ACMS with Potential for Damage |
| 2) Damaged Friable Surfacing ACMS | 6) ACMS with Potential for Significant Damage |
| 3) Significantly Damaged Friable Surfacing ACMS | 7) Any Remaining Friable ACMS or Friable Suspected ACMS |
| 4) Damaged or Significantly Damaged Friable Miscellaneous ACMS | |

End