


2001 SURFACE MINING REPORT



**For Minerals
Other Than Coal**

SUMMARY OF SURFACE MINING REPORT FOR MINERALS OTHER THAN COAL

The North Dakota State Soil Conservation Committee was designated by the Legislature to administer the Surface Mining Reports Law, which requires any person conducting surface mining operations for minerals other than coal, to comply with the reporting requirements of Chapter 38-16 (North Dakota Century Code).

The Law requires any person conducting surface mining operations for minerals, other than coal, who, within one calendar year, removes 10,000 cubic yards or more of earthen material or products, including overburden, or affects one-half acre or more, in combined mining operations to report. Minerals included are: cement rock, clay, gravel, limestone, manganese, molybdenum, peat, potash, pumicite, salt, sand, scoria, sodium sulfate, stone, zeolite, or other minerals, but does not include coal.

The Surface Mining Reports Law also requires the State Soil Conservation Committee to prepare and transmit to local soil conservation districts a report giving information about surface mining operations and reclamation activities conducted during the preceding calendar year.

Included in the Surface Mining Report is a list of surface mining operators and their surface mining activities for calendar year 2001.

There were 20 surface mining operators reporting for the calendar year 2001. The following are approximate total operations according to the reports submitted:

1.	Acres affected	285.1	
2.	Minerals mined		
	A) Gravel & Sand	1,977,903	cubic yards
	B) Clay	1,826,332	cubic yards
	C) Scoria	32,127	cubic yards
	D) Rock	7,207	cubic yards
	TOTAL	3,843,569	cubic yards
3.	Overburden disturbed	289,412	cubic yards

There are **65** pits ranging in size from .1 to **45** acres. Minerals mined were gravel, sand, clay, rock and scoria.

ND STATE SOIL CONSERVATION COMMITTEE
SFN 3813 (9/2001)

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DAY/R)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
Overburden was regraded and leveled	3-15-01	4-7-01	Fisher Sand and Gravel Co. P.O. Box 1034 Dickinson, ND 58602	Harvey Oase 1103 7th Ave. NW Reeder, ND 58649
	4-18-01	5-7-01	Fisher Sand and Gravel Co. P.O. Box 1034 Dickinson, ND 58602	Doc Eberly 1435 119th Ave. SE Dazey, ND 58429
Overburden will be regraded and topsoil respread	4-2-01	12-07-01	Hilltop Sand & Gravel Inc. 3520 Kathryn Road S Valley City, ND 58072	Gwen Blumer 3520 Kathryn Road S Valley City, ND 58072
	4-23-01	5-18-01	Fisher Sand and Gravel Co. P.O. Box 1034 Dickinson, ND 58602	Leslie Koll 1306 97th Ave. SE Wimbleton, ND 58492
	8-14-01	10-11-01	Benson Co. Hwy. Dept. PO Box 184 Minnewaukan, ND 58351-0184	Delphine Gibbs 406 10th St. SE Rugby, ND 58368
	4-19-01	11-21-01	Benson Co. Hwy. Dept. PO Box 184 Minnewaukan, ND 58351-0184	Bryan Britsch 4726 53rd St. NE York, ND 58386
	7-24-01	11-19-01	D.H. Blattner & Sons Inc. 400 County Road 50 Avon, MN 56310	US Dept. of the Interior PO Box 270 Fort Totten, ND 58335
	10-29-01	11-20-01	D.H. Blattner & Sons Inc. PO Box 37 Avon, MN 56310	Ramona Cannon PO Box 343 Fort Totten, ND 58335
	9-24-01	11-19-01	D.H. Blattner & Sons Inc. PO Box 37 Avon, MN 56310	US Dept. of the Interior PO Box 270 Fort Totten, ND 58335
	10-29-01	11-20-01	D.H. Blattner & Sons Inc. PO Box 37 Avon, MN 56310	Mary Swigart PO Box 610 Devils Lake, ND 58301
Overburden was regraded and topsoil respread	8-21-01	11-09-01	Benson Co. Hwy. Dept. PO Box 184 Minnewaukan, ND 58351-0184	Ed & Louie Aartle 9007 34th St. NE Warwick, ND 58381

ND STATE SOIL CONSERVATION COMMITTEE
SFN 3813 (9/2001)

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DAY/YR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
	7-30-01	11-15-01	Benson Co. Hwy. Dept. PO Box 184 Minnewaukan, ND 58351-0184	Marliss Hellerrud 4214 9th Ave. SW Fargo, ND 58103
	5-18-01	5-18-01	Benson Co. Hwy. Dept. PO Box 184 Minnewaukan, ND 58351-0184	Gavin Foss 4645 38th St. NE Maddock, ND 58348
	11-20-01	11-27-01	Sandberg Redi-Mix Inc. PO Box 84 Lignite, ND 58752	Johnny Roos 1515 17th Ave. SW Minot, ND 58752
	4-26-01	5-3-01	Sandberg Redi-Mix Inc. PO Box 84 Lignite, ND 58752	Leelyn Hermanson PO Box 14 Lignite, ND 58752
	6-30-01	7-23-01	Sandberg Redi-Mix Inc. PO Box 84 Lignite, ND 58752	Jim Hanson 224 Railway St. Powerslake, ND 58752
	11-13-01	11-19-01	Sandberg Redi-Mix Inc. PO Box 84 Lignite, ND 58752	Victor Hoff 9232 93rd St. NW Columbus, ND 58752
	5-3-01	5-13-01	Sandberg Redi-Mix Inc. PO Box 84 Lignite, ND 58752	Victor Hoff 9232 93rd St. NW Columbus, ND 58752
	7-23-01	8-15-01	Sandberg Redi-Mix Inc. PO Box 84 Lignite, ND 58752	Victor Hoff 9232 93rd St. NW Columbus, ND 58752
Reclamation is current	1978		Northern Improvement Co. PO Box 1254 Bismarck, ND 58502	Lazy S Ranch PO Box 1254 Bismarck, ND 58502
Overburden and topsoil are being stockpiled	10-20-01	11-24-01	Pioneer Construction Inc. 4025 County Road 82 Mandan, ND 58554	Monte & Karen Dralle 10002 275th St. NE Sterling, ND 58572
	1998		Dakota Redi Mix PO Box 998 Bismarck, ND 58501	Tony Fetting 4050 141st Ave. SE Braddock, ND 58524

ND STATE SOIL CONSERVATION COMMITTEE
 SFN 3813 (9/2001)

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/D/YR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
Topsail was respread	5-7-01		Northern Improvement Co. PO Box 1254 Bismarck, ND 58502	Bob Aberle PO Box 1254 Bismarck, ND 58502
Reclamation is complete	5-1-82	5-7-01	Northern Improvement Co. PO Box 1254 Bismarck, ND 58502	Betty McCormick 10351 Hwy 1804 S Bismarck, ND 58504
	8-16-01	9-3-01	Sandberg Redi-Mix Inc. PO Box 84 Lignite, ND 58752	Raymond Skor 8895 112th Ave. NW Wildrose, ND 58752
	9-4-01	10-2-01	Sandberg Redi-Mix Inc. PO Box 84 Lignite, ND 58752	Lowell Eide HCR 2 Box 22 Williston, ND 58752
	10-3-01	10-17-01	Sandberg Redi-Mix Inc. PO Box 84 Lignite, ND 58752	Brent Bakke HC 2 Box 16 Grenora, ND 58845
	10-18-01	11-12-01	Sandberg Redi-Mix Inc. PO Box 84 Lignite, ND 58752	Raymond Riveland Williston, ND 58752
Overburden was regraded to approximate original topography and topsoil was respread	7-7-01	9-1-01	Aggregate Construction Inc. PO Box 239 Minot, ND 58702	Daniel Shroyer 2126 65th Ave. NE New Rockford, ND 58356
Overburden was regraded to approximate original topography and topsoil was respread	6-15-01	7-10-01	Aggregate Construction Inc. PO Box 239 Minot, ND 58702	Daniel & Joan Shroyer 2126 65th Ave. NE New Rockford, ND 58356
Overburden was regraded	3-12-01	4-12-01	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	August & Loretta Vetter 602 Spruce Ave. E Linton, ND 58552
Overburden was regraded			Harley & Judy Camerud 2732 6th Ave. Northwood, ND 58267	Grensrch Farms RR Northwood, ND 58267
Topsoil was respread			Harley & Judy Camerud 2732 6th Ave. Northwood, ND 58267	Robert Lenz RR Thompson, ND 58257

ND STATE SOIL CONSERVATION COMMITTEE
SFN 3813 (9/2001)

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DAY/YR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
Reclamation is current	5-7-01		Northern Improvement Co. PO Box 1254 Bismarck, ND 58502	Renner/Schatz Steele, ND 58482
Overburden and topsoil are being stockpiled	3-31-01	6-16-01	Pioneer Construction Inc. 4025 County Road 82 Mandan, ND 58554	John & Margaret Blitz Napoleon, ND 58561
Overburden was regraded	5-24-01	6-7-01	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	James Harrison PO Box 171 Napoleon, ND 58561
Overburden was regraded			Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Peter Reis 6631 26th Ave SE Kyntre, ND 58549
Overburden was regraded to approximate topography	6-20-01	8-2-01	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Virgil Miller 109 Riverside Drive Velva, ND 58790
Overburden was regraded to approximate topography and topsoil was respread	6-23-01	8-2-01	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Jack Duchscherer PO Box 308 Velva, ND 58790
Overburden was regraded and topsoil was respread	12-12-01	12-20-01	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Ryan Goven 1751 9th St. NW Turtle Lake, ND 58575
Topsoil was respread	4-1-01	12-21-01	The Coteau Properties Company 204 County Road 15 Beulah, ND 58523	The Coteau Properties Company 204 County Road 15 Beulah, ND 58523
Area will be reclaimed	5-1-01	12-19-01	The Coteau Properties Company 204 County Road 15 Beulah, ND 58523	The Coteau Properties Company 204 County Road 15 Beulah, ND 58523
			Pioneer Construction Inc. 4025 County Road 82 Mandan, ND 58554	WW Ranch PO Box 838 Bismarck, ND 58501
Overburden was regraded to approximate topography	1960		Hebron Brick Co. PO Box S - Washington Ave. East Hebron, ND 58638	Wayne Petri 3215 County 90 Hebron, ND 58638

ND STATE SOIL CONSERVATION COMMITTEE
SFN 3813 (9/2001)

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DAY/YR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
Overburden was regraded to approximate topography	1970		Hebron Brick Co. PO Box S - Washington Ave. East Hebron, ND 58638	Wayne Petri 3215 County 90 Hebron, ND 58638
Overburden was regraded to approximate topography	1954		Hebron Brick Co. PO Box S - Washington Ave. East Hebron, ND 58638	Hebron Brick Co. PO Box S - Washington Ave. East Hebron, ND 58638
Reclamation is current	4-1-99		Northern Improvement Co. PO Box 1254 Bismarck, ND 58502	Northern Improvement Co. PO Box 1254 Bismarck, ND 58502
Reclamation is current	1-13-01		Northern Improvement Co. PO Box 1254 Bismarck, ND 58502	Jacobson 2890 Hwy 25 Mandan, ND 58554
	5-16-01	6-29-01	Sandberg Redi-Mix Inc. PO Box 84 Lignite, ND 58752	Sundhagen Construction Inc. 10428 67th St. NW Tioga, ND 58852
Reclamation has not started	2001		Susag Sand & Gravel, Inc. PO Box 23 Harvey, ND 58341	Marie Deck 2851 35th St. NE Harvey, ND 58341
Topsoil was respread	5-2-01	12-14-01	Soper Construction PO Box 791 Devils Lake, ND 58301	Townships in Ramsey County
Overburden was regraded	6-4-01	8-17-01	Bernard Mahrer Construction Inc. 201 First St. Box 57 Rutland, ND 58067	Keith Haistad 14027 74th St. SE Milnor, ND 58060
	3-12-01	5-30-01	Bernard Mahrer Construction Inc. 201 First St. Box 57 Rutland, ND 58067	Richland County County Courthouse Wahpeton, ND 58075
Topsoil was respread	10-2-01	10-15-01	Holen Construction Inc. PO Box 319 McCluskey, ND 58463	Albert Issak Sooline Drive Box 3A Drake, ND 58736
Overburden was regraded to approximate topography and topsoil was respread	7-1-01	8-1-01	Aggregate Construction Inc. PO Box 239 Minot, ND 58702	Gerhardt & Leona Reuer 555 36th St. SE Medina, ND 58467

ND STATE SOIL CONSERVATION COMMITTEE
SFN 3813 (9/2001)

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DAY/RR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
Overburden was regraded to approximate topography	5-1-01	10-1-01	Aggregate Construction Inc. PO Box 239 Minot, ND 58702	Gerhardt & Leona Reuer 555 36th St. SE Medina, ND 58467
	3-13-01	10-18-01	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Mark Wagner 3022 76th Ave. SE Jamestown, ND 58401
Overburden will be regraded	5-1-61		Miller Gravel & Ready Mix, Inc. PO Box 728 Cando, ND 58324	Roger L. Miller PO Box 728 Cando, ND 58324
Overburden will be regraded	10-10-01	12-20-01	Aggregate Construction Inc. PO Box 239 Minot, ND 58702	John Novodvorsky HCR 1 Box 86 Douglas, ND 58735
Overburden was regraded to approximate topography	8-1-01	9-1-01	Aggregate Construction Inc. PO Box 239 Minot, ND 58702	Evert Johnson RR Heimdahl, ND 58341
Overburden was regraded to approximate topography	6-3-01	7-22-01	Aggregate Construction Inc. PO Box 239 Minot, ND 58702	Duane & Donna Gafkjen RR Alamo, ND 58830
Overburden was regraded to approximate topography and topsoil was respread	5-6-01	7-11-01	Aggregate Construction Inc. PO Box 239 Minot, ND 58702	Duane & Donna Gafkjen RR Alamo, ND 58830
	1999		Kulland Excavating & Gravel Inc. 1505 58th St. W Williston, ND 58801	Kermit Smith 1310 Hill Court Williston, ND 58801
	7-30-01	11-15-01	Vizina's Ready Mix PO Box 108 Williston, ND 58801	Dale Moline 6102 Hwy 85 Williston, ND 58801
	5-1-01	11-26-01	Harris Graveling Inc. PO Box 367 Kenmare, ND 58746	

