


2003 SURFACE MINING REPORT



**For Minerals
Other Than Coal**

SUMMARY OF SURFACE MINING REPORT FOR MINERALS OTHER THAN COAL

The North Dakota State Soil Conservation Committee was designated by the Legislature to administer the Surface Mining Reports Law, which requires any person conducting surface mining operations for minerals other than coal, to comply with the reporting requirements of Chapter 38-16 (North Dakota Century Code).

The Law requires any person conducting surface mining operations for minerals, other than coal, who, within one calendar year, removes 10,000 cubic yards or more of earthen material or products, including overburden, or affects one-half acre or more, in combined mining operations to report. Minerals included are: cement rock, clay, gravel, limestone, manganese, molybdenum, peat, potash, pumicite, salt, sand, scoria, sodium sulfate, stone, zeolite, or other minerals, but does not include coal.

The Surface Mining Reports Law also requires the State Soil Conservation Committee to prepare and transmit to local soil conservation districts a report giving information about surface mining operations and reclamation activities conducted during the preceding calendar year.

Included in the Surface Mining Report is a list of surface mining operators and their surface mining activities for calendar year 2003.

There were 15 surface mining operators reporting for the calendar year 2003. The following are approximate total operations according to the reports submitted:

1.	Acres affected	227.6	
2.	Minerals mined		
	A) Gravel & Sand	1,955,669	cubic yards
	B) Clay	78,930	cubic yards
	C) Rock	37,177	cubic yards
	D) Scoria	18,248	cubic yards
	TOTAL	2,090,024	cubic yards
3.	Overburden disturbed	377,035	cubic yards

There are **43** pits ranging in size from **.5** to **20** acres. Minerals mined were gravel, sand, clay, rock and scoria.

ND STATE SOIL CONSERVATION COMMITTEE
SFN 3813 (9/2001)

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DA/YR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
Overburden was regraded and topsoil respread	4-1-03	12-8-03	Hilltop Sand & Gravel Inc. 3520 Kathryn Road S Valley City, ND 58072	Gwen Blumer 3520 Kathryn Road S Valley City, ND 58072
	6-01		Bismarck Sand & Gravel Inc. PO Box 601 Bismarck, ND 58503	Wayne Weber 1021 Waterfront Bismarck, ND 58503
	4-20-03	6-4-03	Pioneer Construction Inc. 4025 Co Rd 82 Mandan, ND 58554	Monte Dralle 10002 - 275th St NE Sterling, ND 58572
	7-98		Dakota Redi Mix PO Box 998 Bismarck, ND 58501	Tony Feltig 4050 - 141st Ave. SE Braddock, ND 58524
Overburden was regraded to approximate original topography and topsoil was respread	5-7-01		Northern Improvement Co. PO Box 1254 Bismarck, ND 58502	Northern Improvement Co. PO Box 1254 Bismarck, ND 58502
Reclamation is current	5-13-02		Northern Improvement Co. PO Box 1254 Bismarck, ND 58502	Northern Improvement Co. PO Box 1254 Bismarck, ND 58502
Overburden was regraded and topsoil was respread	5-1-03	5-8-03	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Theodore Lang 30600 - 30 th Ave NE Sterling, ND 58572
Overburden was regraded to approximate original topography and topsoil was respread	8-1-03	9-13-03	Aggregate Construction Inc. PO Box 239 Minot, ND 58702	Arnold Skachenko 139 - 107th Ave NW Killdeer, ND 58640
Overburden was regraded to appropriate original topography and topsoil was respread	8-21-03	9-12-03	Pioneer Construction Inc. 4025 Co Rd 82 Mandan, ND 58554	Andrew Baumgartner 704 S 2nd St Strasburg, ND 58573
Overburden was regraded and topsoil was respread			Harley & Judy Camerud 2732 6th Ave. Northwood, ND 58267	Grensrich Farms RR Northwood, ND 58267
Topsoil was respread			Harley & Judy Camerud 2732 6th Ave. Northwood, ND 58267	Robert Lenz 1951 - 5th Ave Thompson, ND 58278

ND STATE SOIL CONSERVATION COMMITTEE
SFN 3813 (9/2001)

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DAY/YR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
Overburden was regraded and topsoil was respread	7-11-03	8-1-03	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Blaine Roth 28 - 2nd Ave SE New Leipzig, ND 58562
Overburden was regraded and topsoil was respread	5-7-01	10-20-03	Northern Improvement Co. PO Box 1254 Bismarck, ND 58502	Renner Schatz Steele, ND 58482
Overburden was regraded to approximate original topography and topsoil was respread	7-14-03	8-1-03	Pioneer Construction Inc. 4025 Co Rd 82 Mandan, ND 58554	Blane Robert 7357 Co Rd 60 Lamoure, ND 58458
Overburden was regraded and topsoil was respread	7-28-03	8-21-03	Pioneer Construction Inc. 4025 Co Rd 82 Mandan, ND 58554	Thomas Flink 4921 70th St SE Lehr, ND 58460
Overburden was regraded to approximate original topography and topsoil was respread	5-17-03	5-31-03	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	
	6-4-03	6-16-03	Pioneer Construction Inc. 4025 Co Rd 82 Mandan, ND 58554	North Dakota
Overburden was regraded and topsoil was respread on reclaimed areas	11-23-03	12-24-03	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Wesley Ewine 1618 N 26th St Bismarck, ND 58501
	4-8-03	4-25-03	Pioneer Construction Inc. 4025 Co Rd 82 Mandan, ND 58554	Pablo Ronderos 1039 - 16th Ave SW Washburn, ND 58577
	3-1-03	12-31-03	The Coteau Properties Company 204 County Road 15 Beulah, ND 58523	The Coteau Properties Company 204 County Road 15 Beulah, ND 58523
	9-1-03		The Coteau Properties Company 204 County Road 15 Beulah, ND 58523	The Coteau Properties Company 204 County Road 15 Beulah, ND 58523
Area reclaimed	8-03	9-03	Dion Jacobs East Industrial Park Dickinson, ND 58601	Paul Reinhardt Beulah, ND 58523

ND STATE SOIL CONSERVATION COMMITTEE
SFN 3813 (9/2001)

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DAY/YR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
	4-1-03		The Coteau Properties Company 204 County Road 15 Beulah, ND 58523	The Coteau Properties Company 204 County Road 15 Beulah, ND 58523
Overburden was regraded to approximate topography	1960		Hebron Brick Co. 1000 E Washington Ave. Hebron, ND 58638	Wayne Petri 3215 County 90 Hebron, ND 58638
Overburden was regraded to approximate topography	1970		Hebron Brick Co. 1000 E Washington Ave. Hebron, ND 58638	Wayne Petri 3215 County 90 Hebron, ND 58638
Overburden was regraded to approximate topography	1954		Hebron Brick Co. 1000 E Washington Ave. Hebron, ND 58638	Hebron Brick Co. 1000 E Washington Ave. Hebron, ND 58638
Area reclaimed as gravel is removed	4-1-99		Northern Improvement Co. PO Box 1254 Bismarck, ND 58502	Northern Improvement Co. PO Box 1254 Bismarck, ND 58502
Area reclaimed as gravel is removed	1-13-99		Northern Improvement Co. PO Box 1254 Bismarck, ND 58502	Paul Jacobson 2890 Hwy 25 Mandan, ND 58554
Overburden was regraded	3-27-03	8-4-03	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Jerry Aftem 519 14th St NW Minot, ND 58703
Overburden was regraded and topsoil was respread	5-15-03	7-9-03	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Peter Smith New Town, ND 58763
Overburden was regraded to approximate original topography and topsoil was respread	8-29-03	10-21-03	Aggregate Construction Inc. PO Box 239 Minot, ND 58702	Ernie & Shari Mau 4840 87th St NW Tolley, ND 58787
	4-8-03	7-4-03	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Allan Brossart RR 2 Rugby, ND 58368
	Spring 2003		Susag Sand & Gravel, Inc. PO Box 23 Harvey, ND 58341	Marie Deck 2851 - 35th St NE Harvey, ND 58341

ND STATE SOIL CONSERVATION COMMITTEE
SFN 3813 (9/2001)

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DA/YR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
Topsoil was respread	5-27-03	11-20-03	Soper Construction PO Box 791 Devils Lake, ND 58301	Townships in Ramsey County
	8-11-03	10-7-03	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Clayton McKay RR 1 Dunseith, ND 58329
Overburden was regraded	6-1-03	8-15-03	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Stanley Pope Ardmon, ND 58620
Topsoil was respread and leveled			Lindberg Bros. Inc. PO Box 2115 Jamestown, ND 58402	Gayne Gasal RR 1 Box 242 Jamestown, ND 58402
Overburden was regraded	1961		Miller Gravel & Ready Mix, Inc. PO Box 728 Cando, ND 58324	Roger L. Miller PO Box 728 Cando, ND 58324
Pit area is reclaimed	8-13-03	9-27-03	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Bob Miller Fordville, ND 58231
Overburden was regraded to approximate topography and topsoil was respread	7-1-03	8-1-03	Aggregate Construction Inc. PO Box 239 Minot, ND 58702	Robin Funke Surrey, ND 58785
Overburden was regraded to approximate topography and topsoil was respread	4-23-03	11-26-03	Aggregate Construction Inc. PO Box 239 Minot, ND 58702	John Novodvorsky 23101 - 114th St SW Douglas, ND 58735
			Kulland Excavating & Gravel Inc. 1505 - 58th St. W Williston, ND 58801	Kenneth Heen Williston, ND 58801
Overburden was regraded	4-1-03	5-30-03	Northern Improvement Co. PO Box 1035 Dickinson, ND 58602	Northern Improvement Co. PO Box 1035 Dickinson, ND 58602

