

# NARRATIVE REPORT

## 1.0 BUILDING INFORMATION

The original date of construction for Softball Intramural Facility was not immediately available; the building has had no major renovations.

Softball Intramural Facility is a one-story, <1,000 ft<sup>2</sup> building which primarily serves as a concessions stand and restrooms during sporting events.

The interior floor finishes included wood; the interior wall finishes included wood; and the interior ceiling finishes included wood. The roofing system is a flat built-up roof and the exterior of the structure is metal.

The piping systems were not insulated. Domestic water enters the building through the west exterior wall; the building does not utilize steam. HVAC systems were not present.

## 2.0 ASBESTOS SURVEY INFORMATION

Softball Intramural Facility was surveyed as part of a larger project on NDSU's Fargo, ND Campus. This report is part of "Volume 4" of a nine volume series. This report includes building specific information only; please refer to the opening section of "Volume 4" for methodologies, definitions, and other pertinent supporting information.

A total of 5 samples were collected from suspect asbestos-containing materials (ACM) from Softball Intramural Facility on October 11, 2007. Laboratory analysis results indicate **none of these samples tested positive for asbestos.**

### 2.1 Suspect Materials Identified and Sampled

Sink Undercoating	Building Seam caulk
Asphalt Shingle Sheets	Roof Flashing
Roof Penetration Putty	

The Asbestos Bulk Sample Results Table includes asbestos sampling data.

### 2.2 Asbestos Containing Materials

**No asbestos containing materials were detected.**