


2004

# SURFACE MINING REPORT



**For Minerals  
Other Than Coal**

PREPARED BY: ND STATE SOIL CONSERVATION COMMITTEE - BISMARCK, ND

**SUMMARY  
OF  
SURFACE MINING REPORT FOR MINERALS OTHER THAN COAL**

The North Dakota State Soil Conservation Committee was designated by the Legislature to administer the Surface Mining Reports Law, which requires any person conducting surface mining operations for minerals other than coal, to comply with the reporting requirements of Chapter 38-16 (North Dakota Century Code).

The Law requires any person conducting surface mining operations for minerals, other than coal, who, within one calendar year, removes 10,000 cubic yards or more of earthen material or products, including overburden, or affects one-half acre or more, in combined mining operations to report. Minerals included are: cement rock, clay, gravel, limestone, manganese, molybdenum, peat, potash, pumicite, salt, sand, scoria, sodium sulfate, stone, zeolite, or other minerals, but does not include coal.

The Surface Mining Reports Law also requires the State Soil Conservation Committee to prepare and transmit to local soil conservation districts a report giving information about surface mining operations and reclamation activities conducted during the preceding calendar year.

Included in the Surface Mining Report is a list of surface mining operators and their surface mining activities for calendar year 2004.

There were 16 surface mining operators reporting for the calendar year 2004. The following are approximate total operations according to the reports submitted:

1.	Acres affected	257.4	
2.	Minerals mined		
	A) Gravel & Sand	2,640,419	cubic yards
	B) Clay	107,938	cubic yards
	C) Rock	74,830	cubic yards
	D) Scoria	126,672	cubic yards
	TOTAL	2,949,859	cubic yards
3.	Overburden disturbed	459,226	cubic yards

There are 60 pits ranging in size from .2 to 40 acres. Minerals mined were gravel, sand, clay, rock and scoria.

ND STATE SOIL CONSERVATION COMMITTEE  
SFN 3813 (10/2003)

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DAY/YR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
The pit will be reclaimed as mining continues and space becomes available			Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Betsy Illes 111 Murray Court Escondido, CA 92025
The pit will be reclaimed as mining continues and space becomes available	3-22-04	4-12-04	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	James Eberle 1435 119th Ave SE Dazey, ND 58429
Overburden was regraded and topsoil was respread	4-28-04	12-1-04	Hilltop Sand & Gravel Inc. 3520 Kathryn Road S Valley City, ND 58072	Gwen Blumer 3520 Kathryn Road S Valley City, ND 58072
Overburden was regraded to approximate original topography and topsoil was respread			Pioneer Construction Inc. 4025 Co Rd 82 Mandan, ND 58554	Jarvis Heglund 3078 31st St NE Oberon, ND 58357
The pit area has been reclaimed	6-15-04	8-17-04	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Charles Septon 308 2nd Ave SE Bowman, ND 58623
	5-04	5-04	Harris Graveling Inc. 45201 Hwy 52 N Kenmare, ND 58746	Randy Edwards 7410 Co Rd 20 Kenmare, ND 58746
	5-7-04	10-18-04	Sundre Sand & Gravel 4103 55th St SE Minot, ND 58701	Brian Ankenbauer 9195 Co Rd 17 Bowbells, ND 58721
	9-7-04		Northern Improvement Co. PO Box 1254 Bismarck, ND 58502	Northern Improvement Co. PO Box 1254 Bismarck, ND 58502
	7-98		Dakota Redi Mix PO Box 998 Bismarck, ND 58501	Tony Fetting 4050 141st Ave SE Braddock, ND 58524
Overburden was regraded to approximate original topography and topsoil was respread	3-25-04	5-20-04	Pioneer Construction Inc. 4025 Co Rd 82 Mandan, ND 58554	Monte Dralle 10002 275th St SE Sterling, ND 58572
The pit will be reclaimed as mining continues and space becomes available	11-1-04	12-17-04	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Wesley Ewine 1618 N 26th St Bismarck, ND 58501

ND STATE SOIL CONSERVATION COMMITTEE  
SFN 3813 (10/2003)

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DAY/YR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
Overburden was regraded and topsoil was respread	5-7-01		Northern Improvement Co. PO Box 1254 Bismarck, ND 58502	Northern Improvement Co. PO Box 1254 Bismarck, ND 58502
Pit reclaimed according to landowner instructions	5-15-04		Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Arnold Skachenko Killdeer, ND 58640
Overburden was regraded to approximate original topography and topsoil was respread	7-10-04	8-3-04	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Glen Lindstrom 8155 Hwy 200 Glenfield, ND 58445
Overburden was regraded			Harley & Judy Camerud 2732 6th Ave. Northwood, ND 58267	Grensrich Farms RR Northwood, ND 58267
Topsoil was respread			Harley & Judy Camerud 2732 6th Ave. Northwood, ND 58267	Robert Lenz 1951 5th Ave Thompson, ND 58278
Overburden was regraded to approximate original topography and topsoil was respread	5-20-04	6-12-04	Pioneer Construction Inc. 4025 Co Rd 82 Mandan, ND 58554	Randy Volk 8295 41st Ave Shields, ND 58569
Overburden was regraded to approximate original topography and topsoil was respread	10-6-04	10-22-04	Pioneer Construction Inc. 4025 Co Rd 82 Mandan, ND 58554	John & Margaret Blitz 6362 Hwy 3 Napoleon, ND 58561
Overburden was regraded to approximate original topography and topsoil was respread	6-25-04	10-31-04	Aggregate Construction Inc. PO Box 239 Minot, ND 58702	Curtis Feist PO Box 42 Velva, ND 58790
Overburden was regraded to approximate original topography and topsoil was respread	12-13-04	12-21-04	Sundre Sand & Gravel 4103 55th St SE Minot, ND 58701	Clarence Zaulhney PO Box 324 Velva, ND 58790
Overburden was regraded to approximate original topography and topsoil was respread	8-10-04	8-13-04	Aggregate Construction Inc. PO Box 239 Minot, ND 58702	Ryan Goven 1690 Hwy 1804 SW Wilton, ND 58579
Overburden was regraded to approximate original topography and topsoil was respread	9-23-04	10-22-04	Aggregate Construction Inc. PO Box 239 Minot, ND 58702	Gerard Goven 204 Becker St Turtle Lake, ND 58575

ND STATE SOIL CONSERVATION COMMITTEE  
SFN 3813 (10/2003)

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DAY/YR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
	11-15-04	11-19-04	Sundre Sand & Gravel 4103 55th St SE Minot, ND 58701	Thomas Hauf 2852 27th St NW Max, ND 58579
Reclamation is complete	9-28-04	10-6-04	Aggregate Construction Inc. PO Box 239 Minot, ND 58702	Leonard Johnson 122 14th Ave NW Turtle Lake, ND 58575
Overburden was regraded to approximate original topography and topsoil was respread	9-10-04	10-5-04	Pioneer Construction Inc. 4025 Co Rd 82 Mandan, ND 58554	Pablo & Colette Ronderos 1039 16th Ave SW Washburn, ND 58577
Pit is being reclaimed as the gravel is mined	10-11-04	10-25-04	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Glen Mattoon 5021 Heather Drive Zephyrhills, FL 84248
	8-15-04	11-1-04	The Coteau Properties Company 204 County Road 15 Beulah, ND 58523	The Coteau Properties Company 204 County Road 15 Beulah, ND 58523
	3-29-04	12-16-04	The Coteau Properties Company 204 County Road 15 Beulah, ND 58523	The Coteau Properties Company 204 County Road 15 Beulah, ND 58523
	4-15-04	10-28-04	The Coteau Properties Company 204 County Road 15 Beulah, ND 58523	The Coteau Properties Company 204 County Road 15 Beulah, ND 58523
Overburden was regraded to approximate original topograph	1960		Hebron Brick Co. 1000 E Washington Ave. Hebron, ND 58638	Wayne Petri 3215 County 90 Hebron, ND 58638
Overburden was regraded to approximate original topograph	1970		Hebron Brick Co. 1000 E Washington Ave. Hebron, ND 58638	Wayne Petri 3215 County 90 Hebron, ND 58638
Overburden was regraded to approximate original topograph	1954		Hebron Brick Co. 1000 E Washington Ave. Hebron, ND 58638	Hebron Brick Co. 1000 E Washington Ave. Hebron, ND 58638
Overburden was regraded to approximate original topograph	7-04	9-04	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Peter Smith Makoti, ND 58756

ND STATE SOIL CONSERVATION COMMITTEE  
SFN 3813 (10/2003)

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DAY/YR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
Overburden was regraded to approximate topography and topsoil was respread	7-27-04	8-26-04	Aggregate Construction Inc. PO Box 239 Minot, ND 58702	Marie Harstad 5796 Hwy 8 Stanley, ND 58784
	Spring-2004		Susag Sand & Gravel, Inc. PO Box 23 Harvey, ND 58341	Marie Deck 2851 35th St. NE Harvey, ND 58341
Topsoil was respread and leveled	4-26-04	12-1-04	Soper Construction PO Box 791 Devils Lake, ND 58301	Townships in Ramsey County
	6-1-04	9-2-04	Sundre Sand & Gravel 4103 55th St SE Minot, ND 58701	State
	10-30-04	12-1-04	Harris Graveling Inc. PO Box 367 Kenmare, ND 58746	Curtis Ones 10045 River Road Tolley, ND 58787
	6-04	9-04	Harris Graveling Inc. PO Box 367 Kenmare, ND 58746	Don Funke 302 Smith St Tolley, ND 58787
Overburden was regraded to approximate topography and topsoil was respread	9-1-04	9-28-04	Aggregate Construction Inc. PO Box 239 Minot, ND 58702	Don Wanning PO Box 322 McCluskey, ND 58463
	8-13-04	9-1-04	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Barbra Price 628 5th Ave S Clinton, IA 52732
	3-24-04	4-28-04	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Darl Patzer 4238 4th Ave NW Jamestown, ND 58401
	5-3-04	8-15-04	Fisher Sand & Gravel Co. PO Box 1034 Dickinson, ND 58602	Richard Klose 8197 42nd St SE Jamestown, ND 58401
Overburden was regraded	5-1-04		Miller Gravel & Ready Mix, Inc. PO Box 728 Cando, ND 58324	Roger L. Miller PO Box 728 Cando, ND 58324



ND STATE SOIL CONSERVATION COMMITTEE  
SFN 3813 (10/2003)

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DAY/YR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
	1-1-04	12-31-04	Sundre Sand & Gravel 4103 55th St SE Minot, ND 58701	Sundre Sand & Gravel 4103 55th St SE Minot, ND 58701
Overburden was regraded to approximate topography and topsoil was respread	4-15-04	10-31-04	Aggregate Construction Inc. PO Box 239 Minot, ND 58702	John Novodvorsky Jr. 23101 114th St SW Douglas, ND 58735
Topsoil was respread	9-04	10-1-04	Harris Graveling Inc. PO Box 367 Kenmare, ND 58746	Ronald Workman 21101 422nd St SW Donnybrook, ND 58734
Overburden was regraded to approximate topography and topsoil was respread	8-10-04	8-16-04	Sundre Sand & Gravel 4103 55th St SE Minot, ND 58701	Robert Sheldon 10971 60th St NW Tioga, ND 58852
Overburden was regraded to approximate topography and topsoil was respread	7-7-04	7-26-04	Aggregate Construction Inc. PO Box 239 Minot, ND 58702	Duane & Donna Garfen Alamo, ND 58830
Overburden was regraded to approximate topography and topsoil was respread	8-20-04	9-2-04	Sundre Sand & Gravel 4103 55th St SE Minot, ND 58701	Daryl Holte PO Box 1501 Williston, ND 58901
	9-7-04	10-1-04	Sundre Sand & Gravel 4103 55th St SE Minot, ND 58701	Tom Haustveit 225 River St Tioga, ND 58852
Overburden was regraded to approximate topography and topsoil was respread	7-16-04	8-6-04	Sundre Sand & Gravel 4103 55th St SE Minot, ND 58701	Wayne Foss PO Box 445 Ray, ND 58849
	1975		Cactus Concrete Products PO Box 1483 Williston, ND 58901	John Sanders 1203 Park Place Williston, ND 58901
	6-9-04	7-23-04	Sundre Sand & Gravel 4103 55th St SE Minot, ND 58701	Patrick O'neil Trust PO Box 1827 Williston, ND 58902
			Kulland Excavating & Gravel Inc. 1505 58th St. W Williston, ND 58901	Kenneth Heen 410 17th St W Williston, ND 58901

