


2019 SURFACE MINING REPORT



**For Minerals
Other Than Coal**

PREPARED BY: ND STATE SOIL CONSERVATION COMMITTEE – BISMARCK, ND

SUMMARY OF SURFACE MINING REPORT FOR MINERALS OTHER THAN COAL

The North Dakota State Soil Conservation Committee was designated by the Legislature to administer the Surface Mining Reports Law, which requires any person conducting surface mining operations for minerals other than coal, to comply with the reporting requirements of Chapter 38-16 (North Dakota Century Code).

The Law requires any person conducting surface mining operations for minerals, other than coal, who, within one calendar year, removes 10,000 cubic yards or more of earthen material or products, including overburden, or affects one-half acre or more, in combined mining operations to report. Minerals included are: cement rock, clay, fines, gravel, limestone, manganese, molybdenum, peat, potash, pumicite, salt, sand, scoria, sodium sulfate, stone, zeolite, or other minerals, but does not include coal.

The Surface Mining Reports Law also requires the State Soil Conservation Committee to prepare and transmit to local soil conservation districts a report giving information about surface mining operations and reclamation activities conducted during the preceding calendar year.

Included in the Surface Mining Report is a list of surface mining operators and their surface mining activities for calendar year 2019.

There were 16 surface mining operators reporting for the calendar year 2019. The following are approximate total operations according to the reports submitted:

1. Acres affected	394.5	
2. Minerals mined		
A) Gravel	830,573	cubic yards
B) Sand & Gravel	1,851,222	cubic yards
C) Clay	67,360	cubic yards
D) Scoria	105,393	cubic yards
E) Rock	200,419	cubic yards
F) Fines	23,921	cubic yards
G) Topsoil	60,000	cubic yards
TOTAL	3,139,158	cubic yards
3. Overburden disturbed	519,159	cubic yards

There are 59 pits ranging in size from .5 to 53 acres. Minerals mined were: clay, fines, gravel, sand, rock and scoria.

SURFACE MINING REPORT FOR MINERALS OTHER THAN COAL

Calendar Year 2019

ND STATE SOIL CONSERVATION COMMITTEE

SFN 3813 (10/2003)

LOCATION OF MINING OPERATION					CURRENT YEAR OPERATIONS			Depth (ft) Mining Operation	Land Use Prior to Mining	Intended Land Use After Mining
County	Section	Township	Range	Type of Mineral Mined	Acres Affected	Cubic Yards Mineral Mined	Cubic Yards Overburden Disturbed			
Bowman	7	131	102	Sand & Gravel	9.0	123,420	29,040	12'	Hayland	Cropland
Bowman	10	131	103	Sand & Gravel	7.0	112,933	67,760		Rangeland	Pastureland
Bowman	16	131	103	Sand & Gravel	3.0	29,040	9,680	8'	Hayland	Pastureland
Burleigh	23	140	77	Sand & Gravel	15.7	27,852	14,075	7'	Cropland	Cropland
Burleigh	32 & 33	140	77	Sand & Gravel	9.0	60,000	11,000	8'	Cropland Hayland	Pastureland Cropland
Burleigh	33	140	77	Sand & Gravel	5.0	40,000	4,000	8'	Rangeland	Pastureland
Dickey	29	130	65	Rock	3.0	25,000	4,000		Improved Pasture	Pastureland
Dickey	34	131	65	Gravel	20.0	54,000	5,000	15'	Rangeland	Pastureland

ND STATE SOIL CONSERVATION COMMITTEE

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DA/YR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
No reclamation performed at this time	04/08/2019	06/13/2019	Fisher Sand & Gravel PO Box 1034 Dickinson ND 58602	Ron Bowman 14902 86th St SW Bowman ND 58623
Overburden was laid back in mined area & will be finished off w/topsoil removed to perform mining activities. Reclamation will resume once hotmix plant is off site in 2020. Stockpile areas have yet to be reclaimed			Fisher Sand & Gravel PO Box 1034 Dickinson ND 58602	Paul White 10010 146th Ave SW Bowman ND 58623
Site reclaimed except the stockpile area	08/28/2019	09/05/2019	Fisher Sand & Gravel PO Box 1034 Dickinson ND 58602	Wade Schwartz PO Box 573 Bowman ND 58623
Reclaimed western portion, 25% complete	06/03/2019	10/12/2019	Knife River Corporation-North Dakota 3303 Rock Island Place Bismarck ND 58504	Michael and Brenda Victor 210 NE St McKenzie ND 58572
Topsoil & overburden are removed. After gravel is mined, topsoil & overburden are replaced. Reclamation is current	05/07/2001		Northern Improvement Co PO Box 1254 Bismarck ND 58502-1254	Northern Improvement Co PO Box 1254 Bismarck ND 58502-1254
Topsoil & overburden are removed. After gravel is mined, topsoil & overburden are replaced. Reclamation is current	08/2013		Northern Improvement Co PO Box 1254 Bismarck ND 58502-1254	Duane Kershaw McKenzie ND 58572
Reclaim done by landowner	10/21/2019	11/05/2019	RTS Shearing, LLC PO Box 1177 Jamestown ND 58402	Dennis Durheim 10153 Hwy 281 Ellendale ND 58436
Pit will be reclaimed this calendar year (2020) once mined material has been	06/01/2019	08/31/2019	JMAC Resources, Inc 121 48th Ave SW Williston ND 58801	Robert W Kaiser, John M Kaiser, Frank A Kaiser 8909 76th Ave SE Monango ND 58436

SURFACE MINING REPORT FOR MINERALS OTHER THAN COAL

Calendar Year 2019

ND STATE SOIL CONSERVATION COMMITTEE

SFN 3813 (10/2003)

LOCATION OF MINING OPERATION					CURRENT YEAR OPERATIONS					
County	Section	Township	Range	Type of Mineral Mined	Acres Affected	Cubic Yards Mineral Mined	Cubic Yards Overburden Disturbed	Depth (ft) Mining Operation	Land Use Prior to Mining	Intended Land Use After Mining
Eddy	1	150	67	Gravel	3.0	15,600	1,000	15'	Hayland	Pastureland
Eddy	6	150	66	Gravel	5.0	34,130	1,000	15'	Rangeland	Wildlife Habitat
Grand Forks	5	151	53	Sand & Gravel	9.0	10,340	1,000	10'	Cropland	Cropland
Grand Forks	8	149	52	Sand & Gravel	1.0			8'		Wildlife Habitat
Kidder	10	140	71							
Kidder	11	142	74	Sand & Gravel	15.7	196,410	54,888	20'	Gravel Pit Rangeland	Pastureland
Kidder	13	140	73							
Kidder	14	137	70	Sand & Gravel	8.1	104,542	24,305	10'	Cropland	Cropland

Calendar Year 2019

ND STATE SOIL CONSERVATION COMMITTEE

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DA/YR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
Reclamation will proceed as areas no longer used	06/01/2019	10/31/2019	Milton R Gowan PO Box 228 Oslo ND 56744	Nick & Jackie Thompson Sheyenne ND 58374
Reclamation will proceed as areas become ready	06/01/2019	09/01/2019	Milton R Gowan PO Box 228 Oslo ND 56744	Arlene Benson (Robert E Benson Family Trust) Sheyenne ND 58374
Reclamation will begin next year once we are done with mining activities	06/01/2019	10/31/2019	Milton R Gowan PO Box 228 Oslo ND 56744	Scott Kosmatka Oslo MN 56744
				Gensrich Farms Northwood ND 58267
No activity in 2019; plan to reclaim in 3-5 years			Hoffer Sand & Gravel 5353 40th Ave SE Tappen ND 58487	Jeff Dewitz 2969 34th St SE Steele ND 58482
Southern portion has been reclaimed. Further mining will occur in the future	04/07/2019	09/30/2019	Knife River Corporation - ND 3303 Rock Island Place Bismarck ND 58504	Dean and Linda Wong 6131 Goodview Trail Ct N Hugo MN 55038
No activity in 2019; plan to reclaim in 3-5 years			Hoffer Sand & Gravel 5353 40th Ave SE Tappen ND 58487	Scott Underwood 528 W 8th St S Brookings SD 57006
Site reclaimed except for stock piles	06/17/2019	08/17/2019	Knife River Corporation - North Dakota 3303 Rock Island Place Bismarck ND 58504	Bonny Stroh 4120 40th St SE Tappen ND 58487

SURFACE MINING REPORT FOR MINERALS OTHER THAN COAL

Calendar Year 2019

ND STATE SOIL CONSERVATION COMMITTEE

SFN 3813 (10/2003)

LOCATION OF MINING OPERATION					CURRENT YEAR OPERATIONS					
County	Section	Township	Range	Type of Mineral Mined	Acres Affected	Cubic Yards Mineral Mined	Cubic Yards Overburden Disturbed	Depth (ft) Mining Operation	Land Use Prior to Mining	Intended Land Use After Mining
Kidder	23	139	74							
Kidder	24	137	70							
Kidder	34	137	71							
Logan	6	133	68							
Logan	19	136	72	Rock	2.0	20,000	1,000		Hayland	
Logan	20	134	72							
Logan	30	136	72							
Logan	35	135	70	Rock Crushed Rock	1.0 1.0	10,000 3,000			Gravel Pit	

Calendar Year 2019

ND STATE SOIL CONSERVATION COMMITTEE

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DA/YR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
No activity in 2019; plan to reclaim in 3-5 years			Hoffer Sand & Gravel 5353 40th Ave SE Tappen ND 58487	Richard Morlock 3829 24th Ave SE Steele ND 58482
No activity in 2019; plan to reclaim in 3-5 years			Hoffer Sand & Gravel 5353 40th Ave SE Tappen ND 58487	Garry Bonnet 5191 48th Ave SE Streeter ND 58483
No activity in 2019; plan to reclaim in 3-5 years			Hoffer Sand & Gravel 5353 40th Ave SE Tappen ND 58487	Bill Hoffer 5353 40th Ave SE Tappen ND 58487
No activity in 2019; plan to reclaim in 3-5 years			Hoffer Sand & Gravel 5353 40th Ave SE Tappen ND 58487	Darryl Buchholz 7361 54th Ave SE Lehr ND 58460
Existing gravel pit	06/06/2019	06/19/2019	RTS Shearing, LLC PO Box 1177 Jamestown ND 58402	Victor Wald 5794 Hwy 3 Napoleon ND 58561
No activity in 2019; plan to reclaim in 3-5 years			Hoffer Sand & Gravel 5353 40th Ave SE Tappen ND 58487	Kambeitz Estate c/o Phil Kambeitz 106 Seminole Ave Bismarck ND 58501
No activity in 2019; plan to reclaim in 3-5 years			Hoffer Sand & Gravel 5353 40th Ave SE Tappen ND 58487	Bill Hoffer 5353 40th Ave SE Tappen ND 58487
Existing gravel pit	10/28-2019	11/20/2019	RTS Shearing, LLC PO Box 1177 Jamestown ND 58402	Reed Zimmerman 6112 45th Ave SE Napoleon ND 58561

SURFACE MINING REPORT FOR MINERALS OTHER THAN COAL

Calendar Year 2019

ND STATE SOIL CONSERVATION COMMITTEE

SFN 3813 (10/2003)

LOCATION OF MINING OPERATION					CURRENT YEAR OPERATIONS					
County	Section	Township	Range	Type of Mineral Mined	Acres Affected	Cubic Yards Mineral Mined	Cubic Yards Overburden Disturbed	Depth (ft) Mining Operation	Land Use Prior to Mining	Intended Land Use After Mining
McIntosh	22	130	67	Rock 3" rock	40.0 40.0	30,000 5,000	5,000 1,000		Improve Pasture	Pastureland
McKenzie	7	151	97	Scoria	6.0	17,900	1,000	10'	Rangeland	
McLean	3	147	79	Sand & Gravel	3.0	58,500	5,500	12'	Hayland Gravel Pit	Pastureland
McLean	11	148	87	Sand & Gravel	9.3	18,813		6'	Gravel Pit	Cropland
Mercer	21	144	84	Topsoil	53.0	60,000		1'	Hayland	Pastureland
Mercer	36	143	89	Scoria	1.5	19,493	20,000	30'	Rangeland	Pastureland
Morton	5	140	90	Clay	1.0		20,000	60'	Rangeland	Other

Calendar Year 2019

ND STATE SOIL CONSERVATION COMMITTEE

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DA/YR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
Overburden, regraded with scraper, topsoil reseeded by landowner	08/21/2019	09/30/2019	RTS Shearing, LLC PO Box 1177 Jamestown ND 58402	Tony & Tricia Schneider 6245 94th St SE Ashley ND 58413
No reclamations planned	04/05/2019	04/23/2019	JMAC Resources, Inc 121 48th Ave SW Williston ND 58801	Milton Omlid 421 University Ave Williston ND 58801
No reclamation done in 2019	08/15/2019	09/25/2019	Sundre Sand & Gravel, Inc 6220 37th Ave SE Minot ND 58701	Russell Makeeff 1039 8th Ave NW Mercer ND 58559
Reclamation completed except for stock piles	06/04/2019	06/14/2019	Knife River Corporation - North Dakota 3303 Rock Island Place Bismarck ND 58504	Terry Kolden 2124 58th Ave NW Roseglen ND 58775
The entire borrow area was completed; land has been seeded w/alfalfa & will continue as hayland once alfalfa has been established. Topography at the site is back to its original state. Currently, stormwater BMPs are in place to eliminate sediment loading in ditch on the south side of Hwy 200A. These will be removed once vegetation's been established & risk of erosion is minimal	08/26/2019	11/08/2019	Baranko Bros Inc 3048 Highway 22 N Dickinson ND 58601	Great River Energy 2875 3rd Ave SW Underwood ND 58576
Most of area will be available for reclamation in 2022. Remainder of area will be used for future long-term support facilities & will be reclaimed w/mine closure, likely in 2042	01/01/2019	12/30/2019	Coyote Creek Mining Co, LLC 6502 17th St SW Zap ND 58580	North Dakota Dept of Trust Lands PO Box 5523 Bismarck ND 58506
In process of stripping overburden down to clay; still active pit	04/01/2019		Hebron Brick Co 1000 Washington Ave E Hebron ND 58638	Vernon Glass 3170 79th Ave Hebron ND 58638

SURFACE MINING REPORT FOR MINERALS OTHER THAN COAL

Calendar Year 2019

ND STATE SOIL CONSERVATION COMMITTEE

SFN 3813 (10/2003)

LOCATION OF MINING OPERATION					CURRENT YEAR OPERATIONS			Depth (ft) Mining Operation	Land Use Prior to Mining	Intended Land Use After Mining
County	Section	Township	Range	Type of Mineral Mined	Acres Affected	Cubic Yards Mineral Mined	Cubic Yards Overburden Disturbed			
Morton	5	140	90	Clay	3.0	26,360	60,000	60'	Rangeland	Other
Morton	10	140	90	Clay	1.0	11,000	2,000	30'	Cropland	Other
Morton	11	140	90	Clay	5.0	30,000	10,000	20'	Rangeland	Other
Morton	24	140	82	Sand & Gravel	8.5	92,000	41,000	14'	Rangeland	Pastureland
Morton	25	139	82	Sand & Gravel	2.2	37,627	4,100	30'	Rangeland	Pastureland
Mountrail	22	155	94	Sand & Gravel	9.4	394,900	30,300	26'	Gravel Pit Pastureland	Pastureland

Calendar Year 2019

ND STATE SOIL CONSERVATION COMMITTEE

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DA/YR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
Still active pit; will reclaim when clay is completely mined	04/01/2019		Hebron Brick Co 1000 Washington Ave E Hebron ND 58638	Don Wanner 3555 County Rd 140 Hebron ND 58638
Still active pit; will reclaim when clay is completely mined	1960		Hebron Brick Co 1000 Washington Ave E Hebron ND 58638	Wayne Petri 3265 County Rd 90 Hebron ND 58638
Still active pit; will reclaim when clay is completely mined	1954		Hebron Brick Co 1000 Washington Ave E Hebron ND 58638	Hebron Brick Co 1000 Washington Ave E Hebron ND 58638
Overburden was used to fill in & level depleted areas of pit. Topsoil was then respread over the overburden as more pit was opened. Once mining finished, the rest of the remaining pit was leveled w/overburden & we started replacing the topsoil w/a scraper. We have about half of the pit area reclaimed w/topsoil before cold weather sets in. We plan on reclaiming the rest of the pit this year once weather permits	05/01/2019	07/16/2019	Fisher Sand & Gravel PO Box 1034 Dickinson ND 58602	Larry Graf 3370 25th Ave Mandan ND 58554
No reclamation activities performed during 2019	10/13/2019	11/22/2019	Knife River Corporation - North Dakota 3303 Rock Island Place Bismarck ND 58504	Knife River Corporation - North Dakota 3303 Rock Island Place Bismarck ND 58504
No reclamation done in 2019	04/26/2019	10/26/2019	Sundre Sand & Gravel, Inc 6220 37th Ave SE Minot ND 58701	Randal Jeffrey 29 8th Ave Brooklyn NY 11217

SURFACE MINING REPORT FOR MINERALS OTHER THAN COAL

Calendar Year 2019

ND STATE SOIL CONSERVATION COMMITTEE

SFN 3813 (10/2003)

LOCATION OF MINING OPERATION					CURRENT YEAR OPERATIONS					
County	Section	Township	Range	Type of Mineral Mined	Acres Affected	Cubic Yards Mineral Mined	Cubic Yards Overburden Disturbed	Depth (ft) Mining Operation	Land Use Prior to Mining	Intended Land Use After Mining
Mountrail	30	153	92	Sand & Gravel	2.4	77,700	2,000	20'	Gravel Pit Pastureland	Pastureland
Mountrail	30	153	92	Sand & Gravel	1.7	49,600	3,000	20'	Gravel Pit Pastureland	Pastureland
Oliver	11 & 14	141	81	Gravel	0.0	0	0	8'	Cropland Rangeland	Pastureland
Pierce	34	152	73	Gravel	2.75	387,500	240	10'		Pastureland
Ramsey	2¼	52	62	Gravel Fill	0.5 0	34,475 632	0 0	10'-17'		Pastureland
Ransom	7	133	54	Rock	3.0	75,000			Gravel Pit	Existing Gravel Pit
Ransom	13	136	58	Crushed Rock	3.0	20,000	3,000		Gravel Pit	Existing Gravel Pit

Calendar Year 2019

ND STATE SOIL CONSERVATION COMMITTEE

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DA/YR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
No reclamation done in 2019	07/10/2019	08/06/2019	Sundre Sand & Gravel, Inc 6220 37th Ave SE Minot ND 58701	Les Wheeler PO Box 1089 Minot ND 58702
No reclamation done in 2019	10/15/2019	11/16/2019	Sundre Sand & Gravel, Inc 6220 37th Ave SE Minot ND 58701	Les Wheeler PO Box 1089 Minot ND 58702
Gravel is removed from stockpiles. Reclamation is current	05/01/2013		Northern Improvement Co PO Box 1254 Bismarck ND 58502-1254	Price Family Price ND 58530
Reclamation has not started yet	Spring 2019		Susag Sand and Gravel Inc PO Box 23 Harvey ND 58341	Tebelius Family Trust 3396 Pete Miller Lane N Stillwater MN 55082
Pit still in use			Soper Construction, LLP 513 Gouldings Road Devils Lake ND 58301	Carla Christofferson 11554 Kelsey St Studio City CA 91604
No reclamation planned at this time	07/29/2019	08/21/2019	RTS Shearing, LLC PO Box 1177 Jamestown ND 58402	Lesmeister Gravel, Inc PO Box 414 Lisbon ND 58054
Reclaim done by landowner	06/25/2019	07/08/2019	RTS Shearing, LLC PO Box 1177 Jamestown ND 58402	Lesmeister Gravel PO Box 414 Lisbon ND 58054

SURFACE MINING REPORT FOR MINERALS OTHER THAN COAL

Calendar Year 2019

ND STATE SOIL CONSERVATION COMMITTEE

SFN 3813 (10/2003)

LOCATION OF MINING OPERATION					CURRENT YEAR OPERATIONS					
County	Section	Township	Range	Type of Mineral Mined	Acres Affected	Cubic Yards Mineral Mined	Cubic Yards Overburden Disturbed	Depth (ft) Mining Operation	Land Use Prior to Mining	Intended Land Use After Mining
Ransom	14	134	56	Gravel Crush Rock Fines	1.0 0.5 0	43,449 117 12,804	6,000 1,000 0	12'		Pastureland
Richland	27	130	50	Gravel Rock Fines	2.0 0.5 0.5	46,485 2,114 9,470		35'		Other
Richland	27	130	50	Gravel Rock Fines	2.0 0.5 0.5	43,402 188 1,647		12'		Other
Stutsman	15	142	69	Rock	4.0	10,000	2,000		Cropland	Cropland
Towner	18	157	66	Gravel	0.75	7,000	350	35'	Gravel Pit	
Walsh	E ½ SW ¼ 21	156	56	Gravel	5.0	140,000	5,000	20'	Cropland	Pastureland
Walsh	E ½ 4	155	56	Sand & Gravel	9.8	94,745	31,621	10.4'	Cropland	Cropland

Calendar Year 2019

ND STATE SOIL CONSERVATION COMMITTEE

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DA/YR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
No reclamation this year	06/03/2019	06/24/2019	Mark Sand & Gravel Co PO Box 458 Fergus Falls MN 56538	Rodney & Lyle Olson 13050 69th St SE Lisbon ND 58054
Pit will remain open for future use; no reclamation	05/02/2019	10/04/2019	Mark Sand & Gravel Co PO Box 458 Fergus Falls MN 56538	Mark Sand & Gravel Co PO Box 458 Fergus Falls MN 56538
Pit will remain open for future use; no reclamation	05/22/2019	11/07/2019	Mark Sand & Gravel Co PO Box 458 Fergus Falls MN 56538	Henry Behle 6435 Tidewater Dr, Ste 1 Norfolk VA 23509
Reclaim topsoil with dozer, let landowner seed 2020 crop	11/14/2019	12/10/2019	RTS Shearing, LLC PO Box 1177 Jamestown ND 58402	Jamie Clark 1890 55th Ave SE Woodworth ND 58496
Overburden was regraded; grass & trees planted & ponds established	05/01/1961		Miller Gravel & Ready Mix, Inc PO Box 728 Cando ND 58324	Roger L Miller PO Box 728 Cando ND 58324
Reclamation will proceed as areas are no longer used	07/15/2019	11/01/2019	Milton R Gowan PO Box 228 Oslo MN 56744	Ron & Terry Borgeson 6307 Hwy 32 Park River ND 58270
Landscaping has taken place, but reclamation has not yet been completed	04/17/2019	06/06/2019	Fisher Sand & Gravel PO Box 1034 Dickinson ND 58602	James Miller 5950 Hwy 32 Fordville ND 58231

SURFACE MINING REPORT FOR MINERALS OTHER THAN COAL

Calendar Year 2019

ND STATE SOIL CONSERVATION COMMITTEE

SFN 3813 (10/2003)

LOCATION OF MINING OPERATION					CURRENT YEAR OPERATIONS					
County	Section	Township	Range	Type of Mineral Mined	Acres Affected	Cubic Yards Mineral Mined	Cubic Yards Overburden Disturbed	Depth (ft) Mining Operation	Land Use Prior to Mining	Intended Land Use After Mining
Williams	1	156	100	Gravel Gravel	8.0 8.0	7,800 16,100	1,000	12'	Gravel Pit	Pastureland
Williams	6	155	100	Sand & Gravel	4.9	118,800	6,500	15'	Cropland Gravel Pit	Cropland
Williams	11	155	100	No mining in 2019	0.0	0	0	15'	Hayland	Cropland
Williams	12	153	102	Sand & Gravel	1.1	40,300	15,000	24'	Gravel Pit	Pastureland
Williams	12	154	96	Scoria	25.0	68,000	5,000	30'	Scoria Pit	None
Williams	28	155	100	Gravel	0.0	0	0	15'	Hayland	Cropland
Williams	30	150	100	No mining in 2019	0.0	0	0	15'	Hayland	Cropland
Williams	30	156	96	Sand & Gravel	6.7	163,700	9,800	15'	Gravel Pit CRP	Pastureland

Extent and Status of Reclamation	DATES OF MINING OPERATION (MO/DA/YR)		Operator Name/Address	Landowner Name/Address
	Commence	Abandoned/ Completed		
Reclamation will take place upon final lease term date	05/01/2019	06/01/2019	JMAC Resources, Inc 121 48th Ave SW Williston ND 58801	Dean Smith 5609 Carolville Loop Williston ND 58801
The overburden was regraded to the approx original topography & the topsoil was respread & leveled over the mined area to the west. The remaining mined area will be reclaimed when mining activities are completed	08/15/2019	10/10/2019	Sundre Sand & Gravel, Inc 6220 37th Ave SE Minot ND 58701	Nicholas Andre 7136 Layton Drive Springfield VA 22150
Reshaped the disturbed area to prevent erosion & to prevent storm water from leaving the site			Northern Improvement Company PO Box 1035 Dickinson ND 58602	Mark Ellis 5658 1st Ave NW Williston ND 58801
No reclamation done in 2019	07/22/2019	08/12/2019	Sundre Sand & Gravel, Inc 6220 37th Ave SE Minot ND 58701	Tammi Dickerson 4742 119th Rd NW, Lot 405 Epping ND 58843
No reclamation planned	03/08/2019	04/04/2019	JMAC Resources, Inc 121 48th Ave SW Williston ND 58801	JMAC Resources/Sundhagen Williston ND 58801
No mining in 2019			Northern Improvement Company PO Box 1035 Dickinson ND 58602	Gordon Brokaw 18933 Crest Street Williston ND 58801
Reshaped the disturbed area to prevent erosion & to prevent storm water from leaving the site			Northern Improvement Company PO Box 1035 Dickinson ND 58602	Northern Improvement Company PO Box 1035 Dickinson ND 58602
No reclamation done in 2019	05/03/2019	07/03/2019	Sundre Sand & Gravel, Inc 6220 37th Ave SE Minot ND 58701	Bennie & Evelyn Foss Family Trust 6933 101st Ave NW Tioga ND 58852