

NARRATIVE REPORT

1.0 BUILDING INFORMATION

Ellig Sports Center was originally constructed in 1994 and has had no major renovations.

Ellig Sports Center is a one-story, 753 ft² building which primarily serves as a concessions stand and restrooms during sporting events.

The interior floor finishes included concrete; the interior wall finishes included concrete block; and the interior ceiling finishes included wood. The roofing system is a peaked asphalt-shingled roof and the exterior of the structure is concrete block.

The piping systems were insulated; neoprene is located in the building. Domestic water enters the building in room 101; the building does not utilize steam. HVAC systems located in the building consisted of electric unit heaters.

2.0 ASBESTOS SURVEY INFORMATION

Ellig Sports Center was surveyed as part of a larger project on NDSU's Fargo, ND Campus. This report is part of "Volume 8" of a nine volume series. This report includes building specific information only; please refer to the opening section of "Volume 8" for methodologies, definitions, and other pertinent supporting information.

A total of 10 samples were collected from suspect asbestos-containing materials (ACM) from the Ellig Sports Center on October 1, 2007. Laboratory analysis results indicate **none of these samples tested positive for asbestos.**

2.1 Suspect Materials Identified and Sampled

Foundation Coating	Roof Flashing (2 types)
Exterior Penetration Putty (on electric conduit)	Asphalt Shingle
Roof Tarpaper	Door Caulk
Sink Undercoating	Baseboard Adhesive
Building Seam Caulk	

The Asbestos Bulk Sample Results Table includes asbestos sampling data.

2.2 Asbestos Containing Materials

No asbestos containing materials were detected.